

6/20/2008 12:51:56 PM Aerial View of second floor steel erection with metal deck placement ongoing. Including erection sequence 17 progress.



6/20/2008 12:29:55 PM Steel erection sequence 16 looking from the east side of the building along Delaware Avenue.



6/19/2008 1:17:23 PM Steel Erection sequence 5 and 6 at the southeast corner along Delaware Avenue.



6/18/2008 2:18:05 PM Structural Steel Erection Sequence 17 along the basement entrance ramp at the northeast corner.



6/19/2008 7:47:56 AM Inaccessible bolted connection along the perimeter exterior foundation wall at 3.1/H line.



6/18/2008 7:22:08 AM Inaccessible bolted connection due to the exterior foundation wall location and column stiffner locations at 3.1/G line.

