

Vehicle Operation News

Safety Recall

Subject: Dodge Dakota Pick Up Trucks

From: Ken Collings
GSA Fleet Operations Division
(703) 308-4673
Kenneth.collings@gsa.gov

Please see that all Field Service Representatives are informed of this news so that our customers may be notified.

DaimlerChrysler Corporation has decided that a defect, which relates to motor vehicle safety, exists in some 2001 through 2003 model year Dodge Dakota trucks that are equipped with manual transmissions.

A wiring harness located under the instrument panel may be chafed by the actuation of the clutch pedal. This could result in abnormal operation of the wipers, horn, turn signals and/or lighting systems.

The Dealer will repair the vehicle at no charge (parts and labor). To do this, they will reroute the wiring harness or replace/repair it if necessary. Approximate completion of repair time is .5 hrs.

If you have paid for a repair of this condition already, you may send the original receipts and/or other adequate proof of payment to the following address for reimbursement:

DaimlerChrysler
P.O. Box 610207
Port Huron, MI 48061-0207

Attn: Reimbursement

This should be an easy visual inspection we can make or have our GSA Fleet customers make on these trucks. Please do so as soon as possible. KC.