



Photograph 37. Building 105 SAFR. Floor post-remediation, September 2002.



Photograph 33. Building 105 SAFR. Typical 50 micron filter assembly, September 2002.



Photograph 34. Building 105 SAFR. Rinsate after 50 micron filtration and before 0.5 micron filtration, September 2002.



Photograph 35. Building 105 SAFR. 50 micron filter assembly at work, September 2002.



Photograph 36. Building 105 SAFR. SAFR floor post-remediation, September 2002.



Photograph 29. Building 105 SAFR. After demolition and pressure washing, September 2002.



Photograph 30. Building 105 SAFR. Post remediation, after washdown, September 2002.