



Photograph 19. Building 105 SAFR. Roll-off staged outside ventilation window east side of Building 105, September 2002.



Photograph 20. Building 105 SAFR. Hose used to remove sand from basement; disposed as hazardous wastet, September 2002.





Photograph 13. Building 105 SAFR. Rear of SAFR prior to demolition, September 2002.



Photograph 14. Building 105 SAFR. Typical scarification evidence on Bullet Pit backstop and of wood framing, September 2002.





Photograph 15. Building 105 SAFR. End on view of Bullet Pit metal backstop showing curvature, September 2002.



Photograph 16. Building 105 SAFR. Debris (metal pipe, wood, plastics) behind range, September 2002.