24000 AVILA RD. LAGNA NIGL CA 92677 949-279-4621 ART 949-322-1484 JOYCE

The second second

MAY 11, 2017 7:02 AM

SYSTEM STATUS REPORT
ALL FUNCTIONS NORMAL

SENSOR ALARM
L 1:PIPE SUMP
PIPING SUMP
FUEL ALARM
MAY 11. 2017 7:18 AM

L S:ANNULAR SPACE ANNULAR SPACE ANNULAR SPACE FUEL ALARM MAY 11, 2017 7:10 AM

24000 AVILA RD. LAGNA NIGL CA 92677 949-279-4521 AKT 949-322-1434 JOYCE

MAY 11, 2017 7:22 AM

SYSTEM STATUS REPORT

L 2:FILL SUMP L 2:FILL SUMP PIPING SUMP FUEL ALARM MAY 11, 2017 7:18 AM

Spill Bucket Testing Report Form

This form is intended for use by contractors performing annual testing of UST spill containment structures. The completed form and printouts from tests (if applicable), should be provided to the facility owner/operator for submittal to the local regulatory agency.

Facility Name:	1. FACILIT Chet Holifield Federal Building	Y INFORMATION	Date of Testing:	5-11-17
	24000 Avila Rd. Laguna Nigue		Date of Testing.	3-11-17
	Art Zandi	Phone	: 949-279-4521	
		5-1-17	949-279-4321	
Date Local Agency Was No				-
Name of Local Agency Insp	ector (if present during testing):	Bri Dewe	у	
	2. TESTING CONTI	RACTOR INFORMAT	ION	
Company Name:	CALIFORNIA HAZARDOUS	S, INC.		
Technician Conducting Test				
Credentials ¹ :		ech. SWRCB Tank T	ester Other (Specify)
License Number(s): 734854	ICC#: 5006847-UT			
	3. SPILL BUCKET	TESTING INFORMA	TION	
Test Method Used:		☐ Vacuum	Other	
Геst Equipment Used: Таре	Measure		Equipment Resolution:	1/16"
Identify Spill Bucket (By Ta Number, Stored Product, etc.				
Bucket Installation Type:	☐ Direct Bury ☐ Contained in Sump	☐ Direct Bury ☐ Contained in Sump	☐ Direct Bury ☐ Contained in Sump	☐ Direct Bury ☐ Contained in Sum
Bucket Diameter:	11"			
Bucket Depth:	16"			
Wait time between applying vacuum/water and start of te				
Test Start Time (T ₁):	7:45am			
Initial Reading (R ₁):	14.5"			
Test End Time (T _P):	8:45am			
Final Reading (R _F):	14.5"			
Test Duration (T _F - T _f):	1 Hour			
Change in Reading (RF-RI):	0			
Pass/Fail Threshold or Crite	ria: Any Visible Drop			
Test Result:	☐ Pass ☐ Fail	Pass Fail	Pass Fail	Pass Fail
	formation on repairs made prior	to testing and recommend	ed follow-up for falled test	(2)
Donate and Control of the		8		
	CATION OF TECHNICIAN the information contained in t			
Technician's Signature:	11 - 6,	Date Date	5-11-17	
1 conficient 5 Digitature.	12	Date	w 44 41	

State laws and regulations do not currently require testing to be performed by a qualified contractor. However, local requirements may be more stringent.

Secondary Containment Testing Report Form

This form is intended for use by contractors performing periodic testing of UST secondary containment systems. Use the appropriate pages of this form to report results for all components tested. The completed form, written test procedures, and printouts from tests (if applicable), should be provided to the facility owner/operator for submittal to the local regulatory agency.

Facility Name: Chet Ho	1. lifield Federa		INFORMAT		Date of Testing:		5-11	-17	
		una Niguel, C	A 92577						
Facility Contact: Art Zand				Phone:	949-279-4521				
Date Local Agency Was Notified of	Testing:			5-1-17					
Name of Local Agency Inspector (if		ng testing):		Bri Dewey					
	2 TEST	INC CONTE	ACTOR INC	FORMATION					
Company Name: CA. HA		SERVICES,IN		ORMATION					
Technician Conducting Test:	Brian Half								
Credentials: SCSLB Lice				WRCB Licensed	Tank Tester				-
License Number: 734854	ilocu Collina	O(O)		Technician# 500					
Liverise Humber. 104004					3017 01		The state of the s	- N	
Manufacturer		56	Component Component			Da	te Tra	aining Exp	nines
INCON		ST	S SUMP TES)-21-17	on co
	3. Si	IMMARY (OF TEST R	ESULTS					
Component	3. SI	Fail Not	OF TEST RI		mponent	Pass	Fail	Not Testad	Repair
Component Piping Sump	Pass	Not	Repairs		mponent	Pass	Fail	Not Tested	
Piping Sump Fill Sump	Pass	Fail Not	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary	Pass	Fail Not	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary	Pass	Fail Not	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary	Pass	Fail Not Tested	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary	Pass	Fail Not	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary	Pass	Fail Not Tested	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary	Pass	Fail Not Tested	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary	Pass	Fail Not Tested	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary	Pass	Fail Not Tested	Repairs		mponent	Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary Annular	Pass	Fail Not Tested	Repairs Made	Col		Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary Annular f hydrostatic testing was performed,	Pass A A A A A A A A A A A A	Fail Not Tested	Repairs Made	Col		Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary Annular	Pass A A A A A A A A A A A A	Fail Not Tested	Repairs Made	Col		Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary Annular hydrostatic testing was performed,	Pass A A A A A A A A A A A A	Fail Not Tested	Repairs Made	Col		Pass	Fail		
Piping Sump Fill Sump Supply Line Secondary Return Line Secondary Vent Line Secondary Annular f hydrostatic testing was performed,	Pass A A A A A A A A A A A A	Fail Not Tested	Repairs Made	Col		Pass	Fail		

4	TANK	ANNIH	AR	TESTING
-		MINIANT	~ 1	LCOING

Test Method Developed By:	☐ Tank Manufacture ☐ Other (Specify)	er Industry Stan	dard Profession	al Engineer
Test Method Used:	Pressure Other (Specify)			;
Test Equipment Used: 0-30 In Hg Vac			Equipment Resolution: 0.5	5% of span
	Diesel			
Is Tank Exempt From Testing?1		Yes No	Yes No	Yes No
Tank Capacity:				
Tank Material:				
Tank Manufacturer:				
Product Stored:				
Wait time between applying pressure/vacuum/water and starting test:				
Test Start Time:				
Initial Reading (R _i):				
Test End Time:				
Final Reading (R _F):				
Test Duration:				
Change in Reading (RF-Ri):				
Pass/Fail Threshold or Criteria:				
Test Result:	Pass Fail	Pass Fail	Pass Fail	Pass Fail
Was sensor removed for testing?	Yes No NA	Yes No NA	Yes No NA	Yes No No
Was sensor property replaced and verified functional after testing?	Yes No NA	Yes No NA	Yes No NA	Yes No No
Comments — (include information of This is a wet annular. No testin		ing, and recommended folio	ww-up for failed tests)	

¹ Secondary containment systems where the continuous monitoring automatically monitors both the primary and secondary containment, such as systems that are hydrostatically monitored or under constant vacuum, are exempt from periodic containment testing. {California Code of Regulations, Title 23, Section 2637(a)(6)}

5. SECONDARY PIPE TESTING

Test Method Developed By:	☐ Piping Manufac ☐ Other (Specify)	turer Industry	Standard Profess	sional Engineer
Test Method Used:	☐ Pressure ☐ Other (Specify)	☐ Vacuum	Hydros	tatic
Test Equipment Used: 0-15 PSI F			Equipment Resolution: 0.59	% of span
0	Supply	Return	Vent	
Distant Materials	Supply		FRP	
Piping Material:	FRP	FRP	Smith	
Piping Manufacturer:	Smith 3"	Smith 3"	3"	
Piping Diameter:				
Length of Piping Run:	30'	30'	30'	
Product Stored:	Diesel	Diesei	Diesel	
Method and location of piping- run isolation:	Test Boot Piping Sump	Test Boot Piping Sump	Test Boot Piping Sump	
Wait time between applying pressure/vacuum/water and starting test:	15 Minutes	15 Minutes	15 Minutes	
Test Start Time:	7:30am	7:30am	7:35am	
Initial Reading (R _i):	5.1	5.1	5.0	
Test End Time:	8:30am	8:30am	8:35am	
Final Reading (R _F):	5.1	5.1	5.0	
Test Duration:	1 Hour	1 Hour	1 Hour	
Change in Reading (RF-RI):	0	0	0	
Pass/Fail Threshold or Criteria:	Any Visible Drop	Anny Visible Drop	Any Visible Drop	
Test Result:	☐ Pass☐ Fail ☐ N/A	Pass Fail N/A	☐ Pass☐ Fail ☐ N/A	Pass Fail N/A
Comments – (include informa	tion on repairs made prior to t	testing, and recommended fo	ollow-up for failed tests)	

6. PIPING SUMP TESTING

ump Manufactur ther (Specify)	rer 🔲 Industry St	andard Profes	ssional Engineer
ressure ther (Specify)	☐ Vacuum ☐ Hydrostatic		static
		Equipment Resolution:	.0001 inches
iping			1 A
42"			
76"			
			-
erglass 22°			
25"			
Good			
ve Highest etration			
No ⊠ NA	Yes No NA	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA
NA			
□ No ⊠ NA	Yes No NA	☐ Yes ☐ No ☐ NA	Yes No NA
□ No ⊠ NA	Yes No NA	Yes No NA	Yes No NA
Minutes			
m/9:21am			
66/5.9063			
m/9:36am			
33/5.9064			
inute Tests			
3/0.0001			
02/0.002			
s Fail	Pass Fail	Pass Fail	Pass Fail
□ No □ NA	Yes No NA	Yes No NA	Yes No NA
⊠ No □ NA	Yes No NA	Yes No NA	Yes No NA
		flow-up for failed tests)	
		nade prior to testing, and recommended for rified functional after testing.	nade prior to testing, and recommended follow-up for failed tests) rified functional after testing.

¹ If the entire depth of the sump is not tested, specify how much was tested. If the answer to <u>any</u> of the questions indicated with an asterisk (*) is "NO" or "NA", the entire sump must be tested. (See SWRCB LG-160)

CHET HOLIFIELD FB 24000 AUTLA RD AGUNA MIGUEL 92677

35/11/2917

9:20 AM

SUMP LEAK TEST REPORT

FILL

TEST STARTED 9:05 AT TEST STARTED 05/11/2017 3.9895 l∾ 9:20 AM SEGIN LEVEL END DATE 05/11/2017 END LEUEL 3.9895 IN LEAK THRESHOLD 0.002 IN TEST RESULT RASSED

DIPING

9:95 AM 95/11/**29**17 TEST STARTED TEST STARTED BEGIN LEVEL 5.9066 Ik END TIME 9:20 AM 85/11/2017 END LEUEL 5.9863 IN LEAK THRESHOLD 9.882 IN TEST RESULT PASSED

CHET HOLIFIELD F3 24880 AUILA RO LAGUNA NIGUEL 92677

35/11/2017 9:36 AR

SUMP LEAK TEST REPORT

=1:

TEST STARTED 9:2: AM TEST STARTED 35/11/2017 3.9894 IN BEGIN LEVEL 9:36 AM END DATE 95/11/2017 END LIVEL 3.9894 IN. LEAK THRESHOLD 0.002 IN TEST RESULT PASSED

PIPING

TEST STARTED TEST STARTED BEGIN LEVEL END TIME 9:21 Am 05/11/2017 5.9063 IN 9:36 AM END DATE 05/11/2017
SND LEVEL 5.9064 IN
LEAK THRESHOLD 0.002 IN
TEST RESULT PASSED 85/11/2917

~	EII I	DICED	CONTAINMENT	CHINAD	TECTING
1.		KISEK	CONTAINMENT	SUMP	I ESTIMA

Fill Riser Containment Sumps are Pre	sent, but were Not Tested				
Test Method Developed By:	☐ Sump Manufacturer ☐ Other (Specify)			Professional Engineer	
Test Method Used:	Pressure	☐ Vacuum		static	
	Other (Specify)				
Test Equipment Used: INCON STS			Equipment Resolution:	.0001 inches	
	Fill				
Sump Diameter:	42"				
Sump Depth:	84"				
Height from Tank Top to Top of Highest Piping Penetration:	No Piping Penetration				
Height from Tank Top to Lowest Electrical Penetration:	18"				
Condition of sump prior to testing:	Good	- 189 miles (
Portion of Sump Tested	4" Above Highest Penetration				
Sump Material:	Fiberglass				
Wait time between applying pressure/vacuum/water and starting test:	15 Minutes				
Test Start Time:	9:05am/9:21am				
nitial Reading (R _i):	3.9895/3.9894				
lest End Time:	9:20am/9:36am				
inal Reading (R _F):	3.9895/3.9894				
Test Duration:	2-15 Minute Tests				
Change in Reading (Rr-Rı):	0.0000/0.0000				
Pass/Fail Threshold or Criteria:	0.002/0.002				
Test Result:	Pass Fail	Pass Fail	Pass Fail	Pass Fail	
s there a sensor in the sump?		Yes No	Yes No	Yes No	
Does the sensor alarm when either product or water is detected?	☐ Yes ☐ No ☒ NA	Yes No NA	☐ Yes ☐ No ☐ NA	Yes No NA	
Was sensor removed for testing?	Yes No NA	Yes No NA	Yes No NA	Yes No NA	
Was sensor properly replaced and verified functional after testing?	☐ Yes ☒ No ☐ NA	☐ Yes ☐ No ☐ NA	☐ Yes ☐ No ☐ NA	Yes No NA	
Comments – (include information The sensor was properly replaced			ollow-up for failed tests)		

MONITORING SYSTEM CERTIFICATION

For Use By All Jurisdictions Within the State of California
Authority Cited: Chapter 6.7, Health and Safety Code; Chapter 16, Division 3, Title 23, California Code of Regulations

This form must be used to document testing and servicing of monitoring equipment. A separate certification or report must be prepared for each monitoring system control panel by the technician who performs the work. A copy of this form must be provided to the tank system owner/operator. The owner/operator must submit a copy of this form to the local agency regulating UST systems within 30 days of test date.

A. General Information				
Facility Name: Chet Holyfield Federal Building	Bldg. No.			
Site Address: 24000 Avila Rd.	City: Laguna Niguel Zip: 92577			
Facility Contact Person: Art Zandi	Phone: 949-279-4521			
Make/Model of Monitoring System: Veeder Root TLS 300c	Date of Testing/Servicing: 4-29-16			
B. Inventory of Equipment Tested/Certified				
Check the appropriate boxes to indicate specific equipment inspected/serviced:				
Tank ID: Diesel	Tank ID:			
☑ In-Tank Gauging Probe. Model: 847390-104/722026	☐ In-Tank Gauging Probe. Model:			
Annular Space or Vault Sensor. Model: 794380-301/No#	Annular Space or Vault Sensor. Model:			
☐ Piping Sump / Trench Sensor(s). Model: 794380-208/884394	Piping Sump / Trench Sensor(s). Model:			
☐ Fill Sump Sensor(s). Model: 794380-208/511996	Fill Sump Sensor(s). Model:			
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:			
☐ Electronic Line Leak Detector. Model:	☐ Electronic Line Leak Detector. Model:			
☐ Tank Overfill / High-Level Sensor. Model: Drop Tube	Tank Overfill / High-Level Sensor. Model:			
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).			
Tank ID:	Tank ID:			
In-Tank Gauging Probe. Model:	In-Tank Gauging Probe. Model:			
Annular Space or Vault Sensor. Model:	Annular Space or Vault Sensor. Model:			
Piping Sump / Trench Sensor(s). Model:	Piping Sump / Trench Sensor(s). Model:			
Fill Sump Sensor(s). Model:	Fill Sump Sensor(s). Model:			
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:			
Electronic Line Leak Detector. Model:	Electronic Line Leak Detector. Model:			
Tank Overfill / High-Level Sensor. Model:	Tank Overfill / High-Level Sensor. Model:			
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).			
Dispenser ID:	Dispenser ID:			
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:			
Shear Valve(s).	Shear Valve(s).			
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).			
Dispenser ID:	Dispenser ID:			
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:			
Shear Valve(s).	Shear Valve(s).			
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).			
Dispenser ID:	Dispenser ID:			
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:			
☐ Shear Valve(s). ☐ Dispenser Containment Float(s) and Chain(s).	☐ Shear Valve(s). ☐ Dispenser Containment Float(s) and Chain(s).			
*If the facility contains more tanks or dispensers, copy this form. Include in				
The racinty contains more tanks of dispensers, copy and form. Include in	mornation for every talk and dispenser at the facility.			
C. Certification - I certify that the equipment identified in this do				
	urers' checklists) necessary to verify that this information is correct and			
	pment capable of generating such reports, I have also attached a copy of			
the report; (check all that apply): System set-up	larm history report			
Technician Name (print): Brian Halfwassen	Signature: 1/2			
Certification No.: A24602	License. No.: 734854			
Testing Company Name: California Hazardous Services, Inc.	Phone: (714) 434-9995			
Site Address: 2205 S. Yale St. Santa Ana, CA 92704	Date of Testing/Servicing: 4-29-16			

Page 1 of 3

D. Results of Testing/Servicing

Softv	ware Versio	n Installed: 424.01
		ng checklist:
⊠ Yes	□ No*	Is the audible alarm operational?
⊠ Yes	☐ No*	Is the visual alarm operational?
⊠ Yes	☐ No*	Were all sensors visually inspected, functionally tested, and confirmed operational?
⊠ Yes	☐ No*	Were all sensors installed at lowest point of secondary containment and positioned so that other equipment will not interfere with their proper operation?
Yes	□ No* □ N/A	If alarms are relayed to a remote monitoring station, is all communications equipment (e.g. modem) operational?
Yes	□ No* □ N/A	For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) Sump/Trench Sensors; Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? Yes No
Yes	□ No* ⊠ N/A	For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? %
Yes*	⊠ No	Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below.
Yes*	⊠ No	Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) Product Water If yes, describe causes in Section E, below.
X Yes	☐ No*	Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable
X Yes	No*	Is all monitoring equipment operational per manufacturer's specifications?
III SCCU	DIE DE DESCRIPTION	, describe now and when these deficiencies were or will be corrected.
	Comment	s: There is a overfill valve on the drop tube.

Page 2 of 3

F.	In-Tank (Gauging / SIR Equipment:	☐ Check this box if tank gauging is used only for inventory control.☐ Check this box if no tank gauging or SIR equipment is installed.
This s	ection must	be completed if in-tank gauging	equipment is used to perform leak detection monitoring.
Compl	ete the follow	ing checklist:	
Yes			or proper entry and termination, including testing for ground faults?
Yes	□ No*		y inspected for damage and residue buildup?
Yes	□ No*	Was accuracy of system product leve	l readings tested?
Yes	□ No*	Was accuracy of system water level re	eadings tested?
Yes	□ No*	Were all probes reinstalled properly?	
Yes	□ No*		ufacturer's maintenance checklist completed?
* In th	e Section H, b	elow, describe how and when these de	
	The second second		
G.	Line Leak	Detectors (LLD):	Check this box if LLDs are not installed.
Compl	ete the follow	ing checklist:	
Yes	□ No* □ N/A		ipment certification, was a leak simulated to verify LLD performance? k rate: 3 g.p.h. 0.1 g.p.h. 0.2 g.p.h.
Yes	□ No*	Were all LLDs confirmed operational	and accurate within regulatory requirements?
Yes	□ No*	Was the testing apparatus properly ca	librated?
Yes	□ N/A	For mechanical LLDs, does the LLD	restrict product flow if it detects a leak?
Yes	□ No*	For electronic LLDs, does the turbine	automatically shut off if the LLD detects a leak?
Yes	□ No*	For electronic LLDs, does the turbine or disconnected?	automatically shut off if any portion of the monitoring system is disabled
Yes	□ No*	For electronic LLDs, does the turbine malfunctions or fails a test?	automatically shut off if any portion of the monitoring system
☐ Yes	□ No* □ N/A	For electronic LLDs, have all accessit	ble wiring connections been visually inspected?
☐ Yes	□ No*	Were all items on the equipment man	ufacturer's maintenance checklist completed?
* In th	e Section H, b Comment	elow, describe how and when these do s: Suction system no leak dete	
A.A.	Comment	s. Suction system to rotal dete	AUG.
			,
-			


Page 3 of 3

UST Monitoring Site Plan

Date:	4/29/2016
Date.	TILOILUIU

Site Location:

		Date.	4/25/2010
AMB Engineering (Chet Ho	lifield Federal Bldg)		
24000 Avila Rd.	***************************************		
Laguna Niguel, CA	92577		



INSTRUCTIONS

If you already have a diagram that shows all required information, you may include it, rather than this page, with your Monitoring System Certification. On your site plan, show the general layout of tanks and piping. Clearly identify locations of the following equipment, if installed; monitoring system control panels; snesors monitoring tank annular spaces, sumps, dispenser pans, spill containers, or other secondary containment areas; mechanical or electronic line leak detectors; and in-tank liquid level probes (if used for leak detection). In the space provided, note the date this Site Plan was prepared.

MONITORING SYSTEM CERTIFICATION

For Use By All Jurisdictions Within the State of California
Authority Cited: Chapter 6.7, Health and Safety Code; Chapter 16, Division 3, Title 23, California Code of Regulations

This form must be used to document testing and servicing of monitoring equipment. A separate certification or report must be prepared for each monitoring system control panel by the technician who performs the work. A copy of this form must be provided to the tank system owner/operator. The owner/operator must submit a copy of this form to the local agency regulating UST systems within 30 days of test date.

A. General Information	
Facility Name: Chet Holyfield Federal Building	Bldg. No.
Site Address: 24000 Avila Rd.	City: Laguna Niguel Zip: 92577
Facility Contact Person: Art Zandi	Phone: 949-279-4521
Make/Model of Monitoring System: Veeder Root TLS 300c	Date of Testing/Servicing: 6-22-15
Transferred of Frontiering Dystem.	Date of Total good Tomb.
B. Inventory of Equipment Tested/Certified	
Check the appropriate boxes to indicate specific equipment inspected/serviced:	
Tank ID: Diesel	Tank ID:
☐ In-Tank Gauging Probe. Model: 847390-104/722026	In-Tank Gauging Probe. Model:
Annular Space or Vault Sensor. Model: 794380-301/No#	Annular Space or Vault Sensor. Model:
Piping Sump / Trench Sensor(s). Model: 794380-208/884394	Piping Sump / Trench Sensor(s). Model:
∑ Fill Sump Sensor(s). Model: 794380-208/511996	Fill Sump Sensor(s). Model:
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:
Electronic Line Leak Detector. Model:	☐ Electronic Line Leak Detector. Model:
☐ Tank Overfill / High-Level Sensor. Model: Drop Tube	Tank Overfill / High-Level Sensor. Model:
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).
Tank YD:	Tank ID:
In-Tank Gauging Probe. Model:	In-Tank Gauging Probe. Model:
Annular Space or Vault Sensor. Model:	Annular Space or Vault Sensor. Model:
Piping Sump / Trench Sensor(s). Model:	Piping Sump / Trench Sensor(s). Model:
Fill Sump Sensor(s). Model:	Fill Sump Sensor(s). Model:
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:
Electronic Line Leak Detector. Model:	Electronic Line Leak Detector. Model:
Tank Overfill / High-Level Sensor. Model:	Tank Overfill / High-Level Sensor. Model:
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).
Dispenser ID:	Dispenser ID:
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:
Shear Valve(s).	Shear Valve(s).
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).
Dispenser LD:	Dispenser ID:
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:
Shear Valve(s).	Shear Valve(s).
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).
Dispenser ID: Dispenser Containment Sensor(s). Model:	Dispenser ID: Dispenser Containment Sensor(s). Model:
	☐ Dispenser Containment Sensor(s). Model: ☐ Shear Valve(s).
Shear Valve(s). Dispenser Containment Float(s) and Chain(s).	☐ Dispenser Containment Float(s) and Chain(s).
*If the facility contains more tanks or dispensers, copy this form. Include	
if the facility contains more tanks of dispensers, copy this form. Include	information for every tank and dispenses at the facility.
~ ~	
C. Certification - I certify that the equipment identified in this d	ocument was inspected/serviced in accordance with the manufacturers'
	turers' checklists) necessary to verify that this information is correct and
	pment capable of generating such reports, I have also attached a copy of
the report; (check all that apply): System set-up	Alarm history report
Technician Name (print): Brian Halfwassen	Signature:
Certification No.: A24602	License. No.: 734854
Testing Company Name: California Hazardous Services, Inc.	Phone: (714) 434-9995
Site Address: 2205 S. Vale St. Santa Ana. CA 92704	Date of Testing/Servicing: 6-22-15

Page 1 of 3

Results of Testing/Servicing

Complete the following checklist: Yes	Softv	vare Version	n Installed: 424.01
Yes			
☑ Yes ☐ No* Is the visual alarm operational? ☑ Yes ☐ No* Were all sensors visually inspected, functionally tested, and confirmed operational? ☑ Yes ☐ No* Were all sensors installed at lowest point of secondary containment and positioned so that other equipment will not interfere with their proper operation? ☐ Yes ☐ No* If alarms are relayed to a remote monitoring station, is all communications equipment (e.g. modem) operational? ☐ Yes ☐ No* For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) ☐ Sump/Trench Sensors; ☐ Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? ☐ Yes ☐ No ☐ Yes ☐ No* For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? % ☐ Yes* ☐ No Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below. ☐ Yes ☐ No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable			
☑ Yes No* Were all sensors visually inspected, functionally tested, and confirmed operational? ☑ Yes No* Were all sensors installed at lowest point of secondary containment and positioned so that other equipment will not interfere with their proper operation? ☐ Yes No* If alarms are relayed to a remote monitoring station, is all communications equipment (e.g. modem) operational? ☐ Yes No* For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) ☐ Sump/Trench Sensors; ☐ Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? ☐ Yes ☐ No ☐ Yes No* For tank systems that utilize the monitoring system as the primary tank overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? % ☐ Yes* No Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below. ☑ Yes* No Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) ☑ Yes No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable ☑ Yes		-	
Yes			
not interfere with their proper operation? Yes No* If alarms are relayed to a remote monitoring station, is all communications equipment (e.g. modem) operational? Yes No* For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) Sump/Trench Sensors; Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? Yes No* For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? % Yes* No Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below. Yes* No Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) Product Water If yes, describe causes in Section E, below. Yes No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable Yes No* Is all monitoring equipment operational per manufacturer's specifications?			
N/A			not interfere with their proper operation?
N/A monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) Sump/Trench Sensors; Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? Yes No No* For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? % Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below. Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) Yes No* Water If yes, describe causes in Section E, below. Yes No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable Yes No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected.	Yes		
N/A mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger?	Yes		monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) Sump/Trench Sensors; Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? Yes No
and list the manufacturer name and model for all replacement parts in Section E, below. Yes* No Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) Product Water If yes, describe causes in Section E, below. Yes No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable Yes No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected.	Yes	⊠ N/A	mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger?
Product ☐ Water If yes, describe causes in Section E, below. Yes ☐ No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable ☐ Yes ☐ No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected.	☐ Yes*	⊠ No	
Yes No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable Yes No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected.	⊠ Yes*	□No	
Yes No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected.	⊠ Yes	□ No*	
* In Section E below, describe how and when these deficiencies were or will be corrected.		□ No*	
	E. C	omments	There was a small amount of diesel in the piping sump. We wiped it out.
	200		

Page 2 of 3 11/06

This sec	tion	must	be completed if in-tank gauging equipment is used to perform leak detection monitoring.
Complete	tha	fallow	ing checklist:
Yes	TI	No*	Has all input wiring been inspected for proper entry and termination, including testing for ground faults?
Yes	十一	No*	Were all tank gauging probes visually inspected for damage and residue buildup?
Yes	+=	No*	Was accuracy of system product level readings tested?
Yes	+	No*	Was accuracy of system water level readings tested?
Yes	+	No*	Were all probes reinstalled properly?
Yes	1	No*	Were all items on the equipment manufacturer's maintenance checklist completed?
	ontic		pelow, describe how and when these deficiencies were or will be corrected.
th the S	CCLIC	,,, ii, ii,	clow, describe now and when these deflectates were or will be corrected.
G. I	Line	Leak	x Detectors (LLD):
Complete	the	follow	ing checklist:
Yes		No*	For equipment start-up or annual equipment certification, was a leak simulated to verify LLD performance? (Check all that apply) Simulated leak rate: 3 g.p.h. 0.1 g.p.h. 0.2 g.p.h.
Yes		No*	Were all LLDs confirmed operational and accurate within regulatory requirements?
Yes		No*	Was the testing apparatus properly calibrated?
Yes		No*	For mechanical LLDs, does the LLD restrict product flow if it detects a leak?
Yes		No*	For electronic LLDs, does the turbine automatically shut off if the LLD detects a leak?
Yes		No*	For electronic LLDs, does the turbine automatically shut off if any portion of the monitoring system is disabled
		N/A	or disconnected?
Yes		No*	For electronic LLDs, does the turbine automatically shut off if any portion of the monitoring system
		N/A	malfunctions or fails a test?
Yes] No*] N/A	For electronic LLDs, have all accessible wiring connections been visually inspected?
Yes		No*	Were all items on the equipment manufacturer's maintenance checklist completed?
* In the S	ectio	on H, b	pelow, describe how and when these deficiencies were or will be corrected.
Н. (Com	ment	s: Suction system no leak detector.
~~~			
,			***
			•

In-Tank Gauging / SIR Equipment:

Page 3 of 3

Check this box if tank gauguig is used only for inventory control.

Check this box if no tank gauging or SIR equipment is installed.


#### **UST Monitoring Site Plan**

Date:	6/22/2015

Site Location: AMB Engineering ( Chet Holifield Federal Bldg)

24000 Avila Rd.

Laguna Niguel, CA 92577



#### INSTRUCTIONS

If you already have a diagram that shows all required information, you may include it, rather than this page, with your Monitoring System Certification. On your site plan, show the general layout of tanks and piping. Clearly identify locations of the following equipment, if installed; monitoring system control panels; snesors monitoring tank annular spaces, sumps, dispenser pans, spill containers, or other secondary containment areas; mechanical or electronic line leak detectors; and in-tank liquid level probes (if used for leak detection). In the space provided, note the date this Site Plan was prepared.

#### **Secondary Containment Testing Report Form**

This form is intended for use by contractors performing periodic testing of UST secondary containment systems. Use the appropriate pages of this form to report results for all components tested. The completed form, written test procedures, and printouts from tests (if applicable), should be provided to the facility owner/operator for submittal to the local regulatory agency.

Facility Name: Facility Address: Facility Contact:	Chet Holifiel 24000 Avila						Date of Testing:		5/7/		
Facility Contact:			auma	Niguel. (	Ca 92677						
	Art Zandi		garia	inguo,	50 02011	Phone:	949-643-1027				
Date Local Agency Wa		00:				4/29/14	343-040-1021		_		
Name of Local Agency				din m)							
Name of Local Agency	inspector (ii presi	eni aun	ng tes	ung).		None			_		
	2.	TEST	TING	CONTR	ACTOR IN	ORMATION					
Company Name:	CA. HAZAR	DOUS	SERV	ICES,IN	С						
Technician Conducting	Test: Fr	ank Ne	wson	1							
Credentials:	CSLB Licensed	Contra	ctor		□ SI	VRCB Licensed	Tank Tester				
License Number:	734854				ICC T	echnician#8166	900-UT				
			4 7-1-1	Ma	nufacturer 1			<del></del>			
Manufacturer				me	Component			Da	te Tra	ining Ex	pires
NCON				STS	SUMP TEST			-		-20-15	
		-						-			
		3. S	UMN	IARY C	F TEST R	ESULTS					
Compon	ent	Pass	Fail	Not	Repairs	Con	nponent	Pass	Fail	Not	Repair
<u> </u>	CIIL		ran	Tested	Made		mponent	1 035	1 QII	Tested	Made
Piping Sump Fill Sump								++	H		
Vent Secondary			H					H	H	H	+ =
Supply Secondary			H					11	H		
Return Secondary		X	H		H			17		H	H
Annular				X				TH	T		
		T									
hydrostatic testing was	performed, descr	ibe wha	at was	done wi	th the water a	after completion	of tests:				
Water Pumped Into	-		_			•					
rator rampod into	o do ganon Di	dillo i	01( 01	oito.							
	CERTIFICATION	LOE TI	CHN	CIAN DI	ECDONCIDI	E FOR CONDU	CTING THIS TESTIN	10			
									uiram	onte	
s the hest of my know											
o the best of my know	vieage, the facts	Stateu	m um	s docum	elif ale accu	rate and in run	compnance with re	gar rod	311 G111	CIILS	

Test Method Developed By:	☐ Tank Manufacture☐ Other (Specify)					
Test Method Used:	☐ Pressure ☐ Other (Specify)		☐ Hydrostatic			
Test Equipment Used: 0-30 In Hg Vacu	um Gauge		Equipment Resolution: 0.	5% of span		
			TO A SECRETARY OF THE PARTY.			
- Landa Balance	Diesel					
s Tank Exempt From Testing?1	⊠ Yes □ No	Yes No	Yes No	Yes No		
Tank Capacity:						
Tank Material:						
Tank Manufacturer:						
Product Stored:						
Wait time between applying pressure/vacuum/water and starting test:						
Fest Start Time:						
nitial Reading (R _I ):						
Test End Time:						
Final Reading (R _F ):						
Test Duration:						
Change in Reading (RF-RI):						
Pass/Fail Threshold or Criteria:						
Test Result:	☐ Pass ☐ Fail	Pass Fail	Pass Fail	Pass Fail		
Was sensor removed for testing?	Yes No NA	Yes No NA	Yes No NA	Yes No No		
Was sensor properly replaced and verified functional after testing?	Yes No NA	☐ Yes ☐ No ☐ NA	Yes No NA	Yes No No		
Comments – (include information or Liquid filled annular. No test requ		ng, and recommended follo	w-up for failed tests)			

¹ Secondary containment systems where the continuous monitoring automatically monitors both the primary and secondary containment, such as systems that are hydrostatically monitored or under constant vacuum, are exempt from periodic containment testing. {California Code of Regulations, Title 23, Section 2637(a)(6)}

5. SECONDARY PIPE TESTING

Test Method Developed By:	Piping Manufact	turer Industry S	Standard Profess	ional Engineer
Test Method Used:		☐ Vacuum	Hydrost	atic
Test Equipment Used: 0-15 PSI F			Equipment Resolution: 0.5%	6 of span
	Vent	Supply	Return	
Piping Material:	Fiberglass	Fiberglass	Fiberglass	
Piping Manufacturer:	Smith	Smith	Smith	
Piping Diameter:	3 ⁿ	3 ⁿ	3 ⁿ	
Length of Piping Run:	30'	30'	30'	
Product Stored:	Diesel	Diesel	Diesel	
Method and location of piping- run isolation:	Test Boot in Piping Sump	Test Boot in Piping Sump	Test Boot in Piping Sump	
Wait time between applying pressure/vacuum/water and starting test:	15 Minutes	15 Minutes	15 Minutes	
Test Start Time:	10:00am	10:00am	10:00am	
Initial Reading (R _I ):	5 PSI	5 PSI	5 PSI	
Test End Time:	11:00am	11:00am	11:00am	
Final Reading (R _F ):	5 PSI	5 P\$1	5 PSI	
Test Duration:	1 Hour	1 Hour	1 Hour	
Change in Reading (Rr-Ri):	0	0	0	
Pass/Fail Threshold or Criteria:	0	0	0	
Test Result:	☐ Pass☐ Fail ☐ N/A	☐ Pass☐ Fail ☐ N/A	Pass Fail N/A	Pass Fail N/A
Comments – (include informa	tion on repairs made prior to to	esting, and recommended fo	llow-up for failed tests)	

6. PIPING SUMP TESTING

Test Method Developed By:	☐ Sump Manufactu☐ Other (Specify)	rer 🛛 Industry S	tandard Profes	sional Engineer		
Test Method Used:	☐ Pressure ☐ Other (Specify)	☐ Vacuum	⊠ Hydro	static		
Test Equipment Used: INCON STS			Equipment Resolution: .0001 inches			
to the way	Piping					
Sump Diameter:	42"					
Sump Depth:	76"					
Sump Material:	Fiberglass					
Height from Tank Top to Top of Highest Piping Penetration:	22"					
Height from Tank Top to Lowest Electrical Penetration:	25"					
Condition of sump prior to testing:	Good					
Portion of Sump Tested ¹	2" Above all Penetrations					
Does turbine shut down when sump sensor detects liquid (both product and water)?"	☐ Yes ☐ No ☒ NA	Yes No NA	Yes No NA	☐ Yes ☐ No ☐ NA		
Turbine shutdown response time	NA					
s system programmed for fail-safe shutdown?*	☐ Yes ☐ No ☒ NA	☐ Yes ☐ No ☐ NA	Yes No NA	☐ Yes ☐ No ☐ NA		
Was fail-safe verified to be operational?*	☐ Yes ☐ No ☐ NA	Yes No NA	Yes No NA	Yes No NA		
Wait time between applying pressure/vacuum/water and starting test:	15 Minutes					
Test Start Time:	10:18am/10:33am					
nitial Reading (R _I ):	3.6822/3.6831					
Test End Time:	10:33am/10:48am					
Final Reading (R _F ):	3.6833/3.6819					
Test Duration:	15 X 2					
Change in Reading (RF-Ri):	0.0011/0.0012					
Pass/Fail Threshold or Criteria:	0.002					
Test Result:	Pass Fail	Pass Fail	Pass Fail	Pass Fail		
Was sensor removed for testing?	Yes □ No □ NA	Yes No NA	Yes No NA	Yes No NA		
Was sensor properly replaced and verified functional after testing?	☐ Yes ☒ No ☐ NA	Yes No NA	Yes No NA	Yes No NA		
Comments – (include information Sensor reinstalled at lowest point			llow-up for failed tests)			

¹ If the entire depth of the sump is not tested, specify how much was tested. If the answer to <u>any</u> of the questions indicated with an asterisk (*) is "NO" or "NA", the entire sump must be tested. (See SWRCB LG-160)

7. FILL RISER CONTAINMENT SUMP TESTING

Facility is Not Equipped With Fill Rise	r Containment Sumps			
Fill Riser Containment Sumps are Pre	esent, but were Not Tested			
Test Method Developed By:	Sump Manufacturer		ndard Profes	sional Engineer
	Other (Specify)			
Test Method Used:	Pressure	☐ Vacuum		static
	Other (Specify)			
Test Equipment Used: INCON STS			Equipment Resolution:	.0001 inches
	Fill			The same of the sa
Sump Diameter:	42"	\		
Sump Depth:	84"			
Height from Tank Top to Top of	No Piping			
Highest Piping Penetration:	Penetrations			
Height from Tank Top to Lowest	18"			
Electrical Penetration:				
Condition of sump prior to testing:	Good			
Portion of Sump Tested	2" Above alf			
	Penetrations			
Sump Material:	Fiberglass			
Wait time between applying pressure/vacuum/water and starting	15 Minutes			
test:	10.10.110.00			
Test Start Time:	10:18am/10:33am			
Initial Reading (Ri):	2.6046/2.6042			
Test End Time:	10:33am/10:48am			
Final Reading (RF):	2.6034/2.6040			
Test Duration:	15 X 2 0.0012/0.0002			
Change in Reading (R _F -R _I ): Pass/Fail Threshold or Criteria:	0.002			
Test Result:	☐ Pass ☐ Fail	Pass Fail	Pass Fail	Pass Fail
Is there a sensor in the sump?	⊠ Yes □ No	Yes No	Yes No	Yes No
Does the sensor alarm when either				
product or water is detected?	☐ Yes ☐ No ☒ NA	Yes No NA	Yes No NA	Yes No NA
Was sensor removed for testing?	✓ Yes ☐ No ☐ NA	Yes No NA	Yes No NA	Yes No NA
Was sensor properly replaced and verified functional after testing?	☐ Yes ☒ No ☐ NA	☐ Yes ☐ No ☐ NA	Yes No NA	Yes No NA
omments – (include information on ensor reinstalled at lowest point bu		ng, and recommended follo	ow-up for failed tests)	
*				
	_			

	PLUS	FINAL REPORT
DATE:	4/28/2014	LOCATION∷Chet Holyfield Federal Building
		24000 Avila Rd.
TOTAL TANK VOL.	3,918	Laguna Niguel, CA 92577
PRODUCT VOL.	2,786	
JLLAGE VOL.	1,132	<b>TANK #</b> 1
PRODUCT TYPE:	Diesel	
	THE ACOUSTIC CHARACT	ERISTIC OF A LEAK REVEALS
THIS HAD		SSES THE CRITERIA SET FORTH BY THE U.S. EPA.
	ERGROUND STORAGE TAIN PA	SSES THE CRITERIA SET FORTH BY THE U.S. EPA.
	E (DRY) PORTION LEAK DERGROUND STORAGE TANK FA	ILS THE CRITERIA SET FORTH BY THE U.S. EPA.
	PRODUCT LEVEL (WET) PO DERGROUND STORAGE TANK FA	ORTION LEAK ILS THE CRITERIA SET FORTH BY THE U.S. EPA.
	WATER SENSOR (CHECK ONL	
NO WATER INTR		SION NOT APPLICABLE
XXXXXX	X	SION NOT APPLICABLE
OPERATOR NAME: F	X	SION NOT APPLICABLE
OPERATOR NAME: F	X	SION NOT APPLICABLE
	X	
OPERATOR NAME: F	PRINT/ Brian Halfwassen	ON: 1/26/2015
OPERATOR NAME: F	PRINT/ Brian Halfwassen  72-1069 EXPIRATI	ON: 1/26/2015 //CES

6.2. 18.5

EZY 3 LOCATOR PLUS	PRESSURE CALCUI		SENSOR CALIE	BRATION	1
		DATA SHEET		,	]
DATE: 4/28/14	LOCATIO	N: Chet Holifield Fe	deral Building	1	Ţ
		24000 Avila Rd.		1	
TOTAL TANK VOL. 3,918		Laguna Niguel, C	A 92577		
PRODUCT VOL. 2,786	TANK#	1			
ULLAGE VOL. 1,132				<u> </u>	
PRODUCT TYPE Diesel					
	PRESSURE SENSOR C	ALCULATION			
48" X INCHES OF PRODUCT	WGT OF PRODU			1.488	PSI(1)
.85" X INCHES OF WATER IN TANK	0.03	6 =		0.03	PSI(2)
LINE 1 + LINE 2 = TOTAL POSITIVE HE	AD PRESSURE IN TANK	=		1.518	PSI(3)
48" X INCHES OF WATER OUTSIDE TANK	0.04	9 =		2.352	PSI(4)
TOTAL HEAD PRESSURE MINUS OUT	SIDE WATER PRESSURE	=		-0.834	PSI(5)
ALWAYS ADD Note: F LINE 6 IS LESS THAN .5 PSI LII	0.5 NE 7 SHALL BE .5 PSI			-0.334	PSI(6)
TEST PRESSURE	TIME	PRESSURE		0.5	PSI(7)
BLOWER STARTED:	11:02am				
TEST PRESSURE REACHED:	11:06am	0.55	DEPTH O	F GROUNDW	ATER:
BLOWER TURNED OFF:	11:11am	0.55	BY:	Wet Annular	
TEST BEGUN:	11:12am	0.55			
TEST ENDED:	11:16am	0.54	WHERE:	Wet Annular	
WATER SENSOR CALCULATION		T			
ADDED: 30 30	30	TECH	t: Brian Half	wassen	
CAL#1 CAL#2 CAL#3					
AVERAGE: 30		SIGN	ATURE:	- //	
WATER INTRUSION TEST PERIOD: BEGA			03-1532	/	
CALCULATION FOR TEST PERIOD:					
30 / 3780 = 0.0079 / .09 AVE. CAL. "A"FACTOR	5 = 10:0 TIME OF TEST:	OO CER	Г. # 72-1069		

. . .

#### HORNER EZY CHEK PRODUCT LINE TEST

LOCATION:	Chet Holyfield Federal Building	
ADDRESS:	24000 Avila Rd.	]
CITY,STATE:	Laguna Niguel, CA 92577	]
APPLIED PRESSURE:	7 PSI	
TECHNICIAN:	Brian Halfwassen	a
DATE:	4/28/2014	
LIC# /CERT#	03-1532/72-1069	

M/T	TIME	DATA	+/-	GPL	RES	GPH		
Ť	12:20pm	75		0.0037	0	0		
T	12:35pm	75	0	0.0037	0		1	
T	12:50pm	75	0	0.0037	0	0	1	
<u> </u>				0.0037	0	0	1	
Г				0.0037	0	0	]	
Г				0.0037	0	0	1	
Γ				0.0037	Ö	0	LINE 1	Diesel
Γ				0.0037	0	0	GPH	C
Γ				0.0037	0	0	PASS	XXXXXX
T			1	0.0037	<u> </u>		FAIL	
M/T_	TIME	DATA	+/-	GPL 0.0037	RES	<b>GPH</b>	1	
M				0.0037	0	0		
							1	
				0.0037	0	0		
VI				0.0037 0.0037	0	0		
VI				0.0037 0.0037 0.0037	0 0	0 0		
N M				0.0037 0.0037 0.0037 0.0037	0 0 0	0 0 0		
VI VI VI				0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0	0 0 0 0		
VI M M M				0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0	0 0 0 0 0	LINE 2	
VI VI VI T				0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0	0 0 0 0 0	LINE 2	0
VI VI VI VI T				0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0 0	0 0 0 0 0 0 0	LINE 2	O XXXXXXX
VI VI VI T				0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0 0 0	0 0 0 0 0 0 0	LINE 2	
M M M M T T				0.0037 0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0 0 0	0 0 0 0 0 0 0	LINE 2	
M M M M	TIME	DATA	+/-	0.0037 0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0	PASS	
M M M M T T T	TIME	DATA	+/-	0.0037 0.0037 0.0037 0.0037 0.0037 0.0037 0.0037 <b>GPL</b>	0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0	PASS	
M M M T T T M M M M M M M M M M M M M M	TIME	DATA	+/-	0.0037 0.0037 0.0037 0.0037 0.0037 0.0037 0.0037	0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0	PASS FAIL	O XXXXXXX

M/T	TIME	DATA	+/	GPL	RES	GPH		
М				0.0037	0	C		
M				0.0037	0	C	5	
M				0.0037	0			
M				0.0037	0	C		
М				0.0037	0	C		
M				0.0037	Ŏ	C	7	
T				0.0037	0	C	LINE 3	
Ť				0.0037	0	C	GPH	0
Т				0.0037	0	C	PASS	XXXXXXX
T				0.0037	0	C	FAIL	

#### MONITORING SYSTEM CERTIFICATION

For Use By All Jurisdictions Within the State of California
Authority Cited: Chapter 6.7, Health and Safety Code; Chapter 16, Division 3, Title 23, California Code of Regulations

This form must be used to document testing and servicing of monitoring equipment. A separate certification or report must be prepared for each monitoring system control panel by the technician who performs the work. A copy of this form must be provided to the tank system owner/operator. The owner/operator must submit a copy of this form to the local agency regulating UST systems within 30 days of test date.

A. General Information	
Facility Name: Chet Holyfield Federal Building	Bldg. No.
Site Address: 24000 Avila Rd.	City: Laguna Niguel Zip: 92577
Facility Contact Person: Art Zandi	Phone: 949-279-4521
Make/Model of Monitoring System: Veeder Root TLS 300c	Date of Testing/Servicing: 4-28-14
<del> </del>	
B. Inventory of Equipment Tested/Certified	
Check the appropriate boxes to indicate specific equipment inspected/serviced:	
Tank ID: Diesel	Tank ID:
☐ In-Tank Gauging Probe. Model: 847390-104/722026	In-Tank Gauging Probe. Model:
Annular Space or Vault Sensor. Model: 794380-301/No#	Annular Space or Vault Sensor. Model:
☐ Piping Sump / Trench Sensor(s). Model: 794380-208/884394	Piping Sump / Trench Sensor(s). Model:
	Fill Sump Sensor(s). Model:
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:
Electronic Line Leak Detector. Model:	Electronic Line Leak Detector. Model:
☐ Tank Overfill / High-Level Sensor. Model: Drop Tube	Tank Overfill / High-Level Sensor. Model:
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).
Tank ID:	Tank ID:
In-Tank Gauging Probe. Model:	In-Tank Gauging Probe. Model:
Annular Space or Vault Sensor. Model:	Annular Space or Vault Sensor. Model:
Piping Sump / Trench Sensor(s).  Model:	Piping Sump / Trench Sensor(s). Model:
Fill Sump Sensor(s). Model:	Fill Sump Sensor(s). Model:
Mechanical Line Leak Detector. Model:	Mechanical Line Leak Detector. Model:
Electronic Line Leak Detector. Model:	Electronic Line Leak Detector. Model:
Tank Overfill / High-Level Sensor. Model:	Tank Overfill / High-Level Sensor. Model:
Other (specify equipment type and model in Section E on Page 2).	Other (specify equipment type and model in Section E on Page 2).
Dispenser ID:	Dispenser ID:
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:
Shear Valve(s).	Shear Valve(s).
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).
Dispenser ID:	Dispenser ID:
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:
Shear Valve(s).	Shear Valve(s).
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).
Dispenser ID:	Dispenser ID:
Dispenser Containment Sensor(s). Model:	Dispenser Containment Sensor(s). Model:
Shear Valve(s).	Shear Valve(s).
Dispenser Containment Float(s) and Chain(s).	Dispenser Containment Float(s) and Chain(s).
*If the facility contains more tanks or dispensers, copy this form. Include in	normation for every tank and dispenser at the facility.
C. Certification - I certify that the equipment identified in this do	cument was inspected/serviced in accordance with the manufacturers'
guidelines. Attached to this Certification is information (e.g. manufact	urers' checklists) necessary to verify that this information is correct and
	oment capable of generating such reports, I have also attached a copy of
the report; (check all that apply):  System set-up  A	larm history report
	(1/5 01
Technician Name (print): Brian Halfwassen	Signature:
Certification No.: A24602	License. No.: 734854
Testing Company Name: California Hazardous Services, Inc.	Phone: (714) 434-9995
Site Address: 2205 S Vale St Santa Ana CA 02704	Date of Testing/Servicing: 4.28.14

Page 1 of 3

#### D. Results of Testing/Servicing

Software Version Installed: 424.01

Complete the following checklist: X Yes ¬ No* Is the audible alarm operational? X Yes No* Is the visual alarm operational? X Yes No* Were all sensors visually inspected, functionally tested, and confirmed operational? X Yes □ No* Were all sensors installed at lowest point of secondary containment and positioned so that other equipment will not interfere with their proper operation? If alarms are relayed to a remote monitoring station, is all communications equipment (e.g. modem) operational? No* Yes N/A Yes □ No* For pressurized piping systems, does the turbine automatically shut down if the piping secondary containment N/A monitoring system detects a leak, fails to operate, or is electrically disconnected? If yes: which sensors initiate positive shut-down? (Check all that apply) Sump/Trench Sensors; Dispenser Containment Sensors. Did you confirm positive shut-down due to leaks and sensor failure/disconnection? Yes No ☐ No* Yes For tank systems that utilize the monitoring system as the primary tank overfill warning device (i.e. no N/A mechanical overfill prevention valve is installed), is the overfill warning alarm visible and audible at the tank fill point(s) and operating properly? If so, at what percent of tank capacity does the alarm trigger? Yes* No. Was any monitoring equipment replaced? If yes, identify specific sensors, probes, or other equipment replaced and list the manufacturer name and model for all replacement parts in Section E, below. Yes* ⊠ No Was liquid found inside any secondary containment systems designed as dry systems? (Check all that apply) Product Water If yes, describe causes in Section E, below. No* Was monitoring system set-up reviewed to ensure proper settings? Attach set up reports, if applicable X Yes X Yes □ No* Is all monitoring equipment operational per manufacturer's specifications? * In Section E below, describe how and when these deficiencies were or will be corrected. E. Comments:

Page 2 of 3

F.	In-Tank G	Sauging / SIR Equipment:	Check this box if tank gauging is used only for inventory control.		
~ *		and a strand and a strand	Check this box if no tank gauging or SIR equipment is installed.		
•					
This section must be completed if in-tank gauging equipment is used to perform leak detection monitoring.					
Comple	ete the followi	ng checklist:			
Yes	□ No*		proper entry and termination, including testing for ground faults?		
Yes	□No*		respected for damage and residue buildup?		
Yes	□ No*	Was accuracy of system product level re			
Yes	No*	Was accuracy of system water level reac			
			umgs tested?		
Yes		Were all probes reinstalled properly?	1.10		
Yes			acturer's maintenance checklist completed?		
* In the	Section H, be	elow, describe how and when these defi	ciencies were or will be corrected.		
G.	Line Leak	Detectors (LLD):	Check this box if LLDs are not installed.		
		,	_		
Compl	ete the followi	ng checklist:			
Yes	No*		nent certification, was a leak simulated to verify LLD performance?		
1 1 63	□ N/A		ate: 3 g.p.h. 0.1 g.p.h. 0.2 g.p.h.		
Yes	No*		nd accurate within regulatory requirements?		
-					
Yes	□ No*	Was the testing apparatus properly calib			
Yes	□ No*	For mechanical LLDs, does the LLD res	strict product flow if it detects a leak?		
	□ N/A				
Yes Yes	□ No*	For electronic LLDs, does the turbine an	utomatically shut off if the LLD detects a leak?		
	□ N/A				
Yes			utomatically shut off if any portion of the monitoring system is disabled		
	□ N/A	or disconnected?			
Yes Yes			utomatically shut off if any portion of the monitoring system		
	□ N/A	malfunctions or fails a test?			
Yes		For electronic LLDs, have all accessible	e wiring connections been visually inspected?		
	N/A_				
Yes	☐ No*	Were all items on the equipment manuf	acturer's maintenance checklist completed?		
* In the	e Section H, be	elow, describe how and when these defi	ciencies were or will be corrected.		
H.	Comments	s: Suction system no leak detect	tor		
71.	Comments	5. Suction system no leak detect	101.		

Page 3 of 3 11/06

Check this box if tank gauging is used only for inventory control.

### **UST Monitoring Site Plan**

Date:	4/28/2014
-------	-----------


Site Location:

AMB Engineering ( Chet Holifield Federal Bldg)

24000 Avila Rd.

Laguna Niguel, CA

92577



#### **INSTRUCTIONS**

If you already have a diagram that shows all required information, you may include it, rather than this page, with your Monitoring System Certification. On your site plan, show the general layout of tanks and piping. Clearly identify locations of the following equipment, if installed; monitoring system control panels; snesors monitoring tank annular spaces, sumps, dispenser pans, spill containers, or other secondary containment areas; mechanical or electronic line leak detectors; and in-tank liquid level probes (if used for leak detection). In the space provided, note the date this Site Plan was prepared.



**INSPECTION REPORT** 

y of Orange, Health Care Agency, Environ 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611

(714) 433-6000 ochealthinfo.com/eh **DACX5UTER** Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 **LAGUNA NIGUEL, CA 92677** 

Mailing Address: **GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION** 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 05/30/2017 **Reinspection Date:** N/A

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-REINSPECTION - OFF-SITE

al Health

Bri Dewey, REHS

HAZARDOUS WASTE SPECIALIST III

(657) 622-9434 6:30-9:00 a.m.

#### **OPENING COMMENTS**

Received and reviewed monitoring certification results from testing on 5/11/2017. All components passed at that time.

Received and reviewed SB989 testing from testing done on 5/11/17. Sumps and lines passed at that time.

#### SIGNATURE(S) OF ACKNOWLEDGEMENT

COPY MAILED TO OWNER

NAME: TITLE:

AND/OR

Signing for the receipt of the above report is not an appropriate the place of the violations set forth herein.

## OR ALLE OF THE STATE OF THE STA

#### **INSPECTION REPORT**

County of Orange, Health Care Agency, Environmental Health

1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

PR0024056

DA9323178

Page 1 of 2

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address:
GENERAL SERVICES ADMIN
GENERAL SERVICES ADMINSTRATION
24000 AVILA ROAD STE 4100
LAGUNA NIGUEL, CA 92677

Record ID: FA0023992
Inspection Date: 05/11/2017
Reinspection Date: N/A

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)
Service: A01-ROUTINE INSPECTION

Bri Dewey, REHS

HAZARDOUS WASTE SPECIALIST III

(657) 622-9434 6:30-9:00 a.m.

THE ITEMS NOTED BELOW WERE OBSERVED DURING COURSE OF THE SITE VISIT. ANY VIOLATIONS OBSERVED MUST BE CORRECTED

#### **OPENING COMMENTS**

Routine inspection conducted this date in regards to underground storage tank, consent to enter, inspect and take photographs was given by –Ardeshir Zandi

Monitoring system certification was conducted at this time. Brian Halfwassen, Cal Haz performed the monitor cert. Ensure submittal of monitor cert test results within 30 days.

Tester provided the following certifications: ICC Tech exp 7/16/17, Veeder-Root tech exp 6/4/17

Number of UST's -1 Sensor types -209 and 301

The Veeder-Root monitoring panel showed all functions normal. Sensors and sumps in good order this date.

The following documents were available for review:

CUPA Business Activities form, CUPA Business Owner / Operator Identification form
CUPA UST Facility Information form, CUPA UST Tank Information forms, CUPA UST monitoring plan, CUPA UST response plan,
Monitoring site map are available on-site.
SB989 test results dated 5/7/2014
Monitor Cert test results dated 4/29/16
DO reports
Financial responsibility statement not required
DO Statement showing Tim Hamm exp 7/16/17
Employee Training is current

Please log into your CERS account and update all UST forms within 30 days.

Please submit the monitoring system certification results within 30 days.

This facility is required and has been notified to electronically submit UST, DO and CFR forms within 30 days of this inspection.

A copy of this report was e-mailed

#### **VIOLATIONS OBSERVED**

I205 - Owner/Operator has tested and certified leak detection equipment annually Failure to certify leak detection equipment every 12 months and/or submit monitoring system certification to the CUPA within 30 days of the testing event. 23 CCR 16 2638

The monitor certification was due on or before 4/29/2016. Remember to schedule all future monitor certs within the allowable legal times. The violation was abated at the time of inspection.

1506 - Secondary containment testing conducted every 36 months in accordance with requirements Failure to conduct secondary containment testing at the required interval. 23 CCR 16 2637

The SB989 testing was due by 5/7/2017, it was performed this date. The violation was abated at the time of inspection. Please remember to schedule testing on or prior to the required dates.



#### **INSPECTION REPORT**

County of Orange, Health Care Agency, Environmental Health 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh DA9323178 Page 2 of 2

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 05/11/2017

Reinspection Date: N/A

COPY MAILED TO OWNER AND/OR

Signing for the receipt of the above report is not an admission of the facts of the violations set forth herein.

# OR OR OR

INSPECTION REPORT

of Orange, Health Care Agency, Environme...... Health
1241 EAST DYER ROAD, SUITE 120

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh DA5426206 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 06/02/2016 Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service: F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Lance Malis
HAZARDOUS WASTE SPECIALIST III
(714) 640-7122
Imalis@ochca.com

COPY MAILED TO OWNER
AND/OR
FACILITY OPERATOR

Received report for a UST system monitoring certification performed on 4-29-16. All monitoring equipment operational per manufacturer's specifications.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title		
Signature		Date

#### DA5396978 Page 1 of 1

## INSPECTION REPORT C_____y of Orange, Health Care Agency, Environmental Health 1241 EAST DYER ROAD, SUITE 120

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address:
GENERAL SERVICES ADMIN
GENERAL SERVICES ADMINSTRATION
24000 AVILA ROAD STE 4100
LAGUNA NIGUEL, CA 92677

 Record ID:
 FA0023992

 Inspection Date:
 04/29/2016

 Reinspection Date:
 05/29/2016

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service: A01-ROUTINE INSPECTION

Lance Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122 Imalis@ochca.com

THE ITEMS NOTED BELOW WERE OBSERVED DURING COURSE OF THE SITE VISIT. ANY VIOLATIONS OBSERVED MUST BE CORRECTED

I481 - Facility has a valid Permit to Operate from the CUPA Failure to obtain and maintain a valid operation permit from the CUPA. 23 CCR 16 2712(i); HSC 6.7 25284

Facility is currently operating the underground storage tank (UST) without a permit. The UST submittal (via CERS) has been declined the last four times. Refer to the inspector comments (on the submittal that was not accepted on 10-1-15) and modify the forms accordingly. Re submit after modifications have been performed.

On site for a routine compliance inspection. Brian Halfwassen of Cal Haz currently performing a UST system monitoring certification. Current ICC and Veeder-Root certifications provided.

Facility consists of one 4000 gallon diesel tank leading to a day tank in the generator room.

Both sumps were free of liquid. Sensors (208s) were located at the low areas of both sumps. Tank annular is liquid filled. Sensor is a "single" 301 which appears to be properly located.

Facility is exempt from certification of financial responsibility.

SB 989 testing valid through 5-7-17.

Reviewed monthly designated operator inspection reports. One fuel alarm documented during the past 12 months. Documentation for corrective action available for review. Employee training by the designated operator provided to six employees on 11-13-15.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

Signature

Date

#### **INSPECTION REPORT** DA5211952



Cc...... of Orange, Health Care Agency, Environmental Health 1241 EAST DYER ROAD, SUITE 120

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

Record ID:

PR0024056

Page 1 of 1

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 **LAGUNA NIGUEL, CA 92677** 

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Inspection Date: 10/01/2015 **Reinspection Date:** 

FA0023992

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Lance Malis HAZARDOUS WASTE SPECIALIST III (714) 640-7122 lmalis@ochca.com

### COPY MAILED TO OWNER AND/OR **FACILITY OPERATOR**

Reviewed and declined submittal in CERS. The UST Tank Information/Monitoring Plan needs to be modified. There are a few blank or incorrect fields filled out on the tank information page. Specifically, No overfill protection or protection corrosion is listed. Construction information for the piping secondary, piping containment sump and riser is blank. UDC construction type is listed as single wall. There is no UDC. leave this blank.

The monitoring procedure must be completed in the user defined fields (cannot accept a copy of a "hand filled out" monitoring form).

Re submit after modifications have been performed.  I declare that I have examined and received a copy of this inspection report.		
Print Name and Title		
Signature	Date	

#### INSPECTION REPORT

Co...., of Orange, Health Care Agency, Environm 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611

TA ANA, CA 92705-56 (714) 433-6000 ochealthinfo.com/eh DA5143762 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 07/20/2015

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

I Health

Service: F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Lance Malis HAZARDOUS WASTE SPECIALIST III (714) 640-7122 Imalis@ochca.com

## COPY MAILED TO OWNER AND/OR FACILITY OPERATOR

Received results for a UST monitoring certification performed on 6-22-15.	All monitoring equipment
operational per manufacturer's specifications.	

I declare that I have examined and received a copy of this inspection report.

Print Name and Title	
Signature	Date



#### **INSPECTION REPORT** Cour

i Orange, Health Care Agency, Environme

1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

DA5136839 Health Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 07/09/2015 **Reinspection Date:** 

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-F0LLOW-UP INSPECTION - OFF-SITE

L Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122

Reviewed and declined submittal in CERS. The UST tank and monitoring page were basically blank. Fill out the information that is requested on the forms.

Also the actual UST response plan and designated operator forms need to be filled out. We cannot accept copies of old/previous forms.

Please complete these forms and re submit.

I declare that I have examined and received a copy of this inspection report.	
Print Name and Title	
Signature	<u>Date</u>

of Orange, Health Care Agency, Environr 1241 EAST DYER ROAD, SUITE 120

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

DAP91WH6P Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 06/22/2015 07/22/2015 Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

al Health

Service: A01-ROUTINE INSPECTION

Lance Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122 Imalis@ochca.com

THE ITEMS NOTED BELOW WERE OBSERVED DURING COURSE OF THE SITE VISIT. ANY VIOLATIONS OBSERVED MUST BE CORRECTED

1582 - UST Operating Permit Application for Facility information and Tank information submitted/maintained Failure to prepare, maintain, and submit an accurate CUPA UST Operating Permit Application. 23 CCR 16 2711; HSC 6.7 25286(a)

CUPA UST forms need to be submitted electronically. Spoke with the contact listed on the business owner/operator identification form (Samantha). Explained what forms need to be submitted.

## COPY MAILED TO OWNER AND/OR **FACILITY OPERATOR**

On site for a routine compliance inspection. Brian Halfwassen of Cal Haz currently performing a UST system monitoring certification. Current ICC and Veeder-Root certifications provided.

Facility consists of one 4000 gallon diesel tank leading to a day tank in the generator room.

Both sumps were free of liquid. Sensors (208s) were located at the low areas of both sumps. Tank annular is liquid filled. Sensor is a "single" 301 which appears to be properly located.

Facility is exempt from certification of financial responsibility.

SB 989 testing valid through 5-7-17.

> Declined CERS submittal on 6-10-15. Need to resubmit completely filled out UST facility page, tank and monitoring pages, leak response plan, plot plan and designated operator forms. * A permit to operate will not be renewed on 7-1-15 unless these are submitted and complete.

Reviewed monthly designated operator inspection reports. One fuel alarm documented during the past 12 months (4-12-15). Documentation for corrective action available for review. Employee training by the designated operator provided to six employees on 11-14-14.

1	declare that I	have	examined	and	received	l a coi	ov of	this i	inspecti	on rei	oort.
,	acciare triat i	1140	O/Carrini To G	4114	70001100	- u - u - u	~, ~,			$\circ$	

Print Name and Title	
Signature	Date



f Orange, Health Care Agency, Environme

Health 1241 EAST DYER ROAD, SUITE 120

DA5113906 Page 1 of 1

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 **LAGUNA NIGUEL, CA 92677** 

Cou

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 06/10/2015 Inspection Date:

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-FOLLOW-UP INSPECTION - OFF-SITE

L Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122

Reviewed and declined submittal in CERS. Please address the following:	
Applicant certification is blank on the application page.	
Several items are missing on the tank page including information regarding of secondary construction and vent/vapor/riser information.	overfill, piping and sump
Most of the required information on the monitoring plan is missing.	
Leak response plan, plot plan and designated operator forms were not subm	itted.
* Resubmit after the above items have been added.	
I declare that I have examined and received a copy of this inspection report.	
Print Name and Title	
Signature	Date



## Cour

#### **INSPECTION REPORT** f Orange, Health Care Agency, Environme

1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000

DA8691887 Page 1 of 1

ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 04/29/2015

**Reinspection Date:** 

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-F0LLOW-UP INSPECTION - OFF-SITE

**lealth** 

L Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122

Reviewed and declined UST submittal in CERS. UST facility page is missing the applicant certification.

Tank page and monitoring page are missing required information. Many boxes were left blank.

Still need to submit leak response plan, plot plan and designated operator information pages.

* Resubmit after modifications and additions have been performed.

I declare that I have examined and received a cop	ov of this inspection report.
Print Name and Title	
Signature	Date



#### **INSPECTION REPORT** Cour

f Orange, Health Care Agency, Environme

1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000

DA8927611 Page 1 of 1

ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 10/29/2014

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR) Service: F04-FOLLOW-UP INSPECTION - OFF-SITE

Health

L Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122

Received SB 989 testing results. All five tested components passed on 5-7-14 (liquid filled annular). Deleted violation TF02. No violations noted at this time.

I declare that I have examined and received a copy of this inspection report.	
Print Name and Title	
Signature	<u>Date</u>



of Orange, Health Care Agency, Environm 1241 EAST DYER ROAD, SUITE 120

SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh DA9883870 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 05/19/2014

**Reinspection Date:** 

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

ıl Health

Service: F04-F0LLOW-UP INSPECTION -

**OFF-SITE** 

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677 Lance Malis HAZARDOUS WASTE SPECIALIST III (714) 640-7122 Imalis@ochca.com

#### **COMMENTS**

#### **ZZZ9 - INSPECTOR COMMENTS**

Received reports for the following:

- > Monitoring system certification performed on 4-28-14. All monitoring equipment operational per manufacturer's specifications.
- > Primary tank and and product line integrity testing performed on 4-28-14. Both components passed.
- > Secondary containment testing performed on 5-7-14. All tested components passed.

# COPY MAILED TO OWNER AND/OR FACILITY OPERATOR

Print Name and Title
declare that I have examined and received a copy of this inspection report.

# OR ACE

#### **INSPECTION REPORT**

Co...., of Orange, Health Care Agency, Environm ..... Health

1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh DA9864264 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address:
GENERAL SERVICES ADMIN
GENERAL SERVICES ADMINSTRATION
24000 AVILA ROAD STE 4100
LAGUNA NIGUEL, CA 92677

Record ID: FA0023992
Inspection Date: 04/28/2014
Reinspection Date: 05/28/2014

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service: A01-ROUTINE INSPECTION

Lance Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122 lmalis@ochca.com

THE ITEMS NOTED BELOW WERE OBSERVED DURING COURSE OF THE SITE VISIT. ANY VIOLATIONS OBSERVED MUST BE CORRECTED

TF02 - TANK Secondary containment systems have not been tested every 3 years. (CA Code of Regulations 2637(a))

SB-14 testing performed and passed on 8-12-10. * Triennial testing was due again on 8-12-13.

Provide current testing results/report to Health Care Agency. If testing has not been performed within the past 36 months, immediately schedule the testing and provide results/report to health Care Agency within 30 days.

#### **COMMENTS**

#### **ZZZ9 - INSPECTOR COMMENTS**

On site for a routine compliance inspection. Brian Halfwassen of Cal Haz currently performing a UST system monitoring certification. Current ICC and Veeder-Root certifications provided. Primary tank and product line integrity testing also to be performed today. Tank testing license provided.

Facility consists of one 4000 gallon diesel tank leading to a day tank in the generator room.

Both sumps were free of liquid. Sensors (208s) were located at the low areas of both sumps. Tank annular is liquid filled. Sensor is a "single" 301 which appears to be properly located.

CUPA forms submitted and available for review in the binder kept on site.

Facility is exempt from certification of financial responsibility.

Reviewed monthly designated operator inspection reports. No alarms documented during the past 12 months. Five employees provided UST training by the designated operator on 11-8-13.

COPY MAILED TO OWNER
AND/OR
FACILITY OPERATOR

I declare that I have examined and received a copy of this inspection report.	
Print Name and Title	
Signature	Date



of Orange, Health Care Agency, Environm 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611

DA9599956 Page 1 of 1

(714) 433-6000 ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 07/01/2013

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

I Health

Service: F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Lance Malis Mailing Address: **GENERAL SERVICES ADMIN** HAZARDOUS WASTE SPECIALIST III GENERAL SERVICES ADMINSTRATION (714) 640-7122 24000 AVILA ROAD STE 4100 lmalis@ochca.com LAGUNA NIGUEL, CA 92677

#### COMMENTS

#### **ZZZ9 - INSPECTOR COMMENTS**

Received report for monitor certification performed on 6-24-13. Monitoring equipment operational per manufacturer's specifications.

> COPY MAILED TO OWNER AND/OR **FACILITY OPERATOR**

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

<u>Signature</u>

<u>Date</u>



of Orange, Health Care Agency, Environi 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611

(714) 433-6000

ochealthinfo.com/eh

al Health

DA9592794 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 06/24/2013

**Reinspection Date:** 

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service: A01-ROUTINE INSPECTION

Lance Malis

HAZARDOUS WASTE SPECIALIST III

(714) 640-7122 Imalis@ochca.com

#### **COMMENTS**

#### **ZZZ9 - INSPECTOR COMMENTS**

On site for a compliance inspection. Frank Newsom of Cal-Haz currently performing a UST system monitor inspection. Current Veeder-Root and ICC certifications provided.

Facility consists of one diesel tank for a back up generator. Tank annular is liquid filled. Both sumps were free of liquid. Sensors were located at the low area of both sumps.

Designated operator inspection reports reviewed for the past 12 months. One alarm recorded in June of 2012. * Corrective action documentation was not included with the reports. Make sure follow-up comments and/or corrective action documentation for fuel alarms are kept with the designated operator inspection reports. Training provided to employees on 10-22-12. Training log reviewed on site (5 employees).

Monitoring procedure kept on site and available for review (5-4-10).

Secondary containment testing due August 12th of this year.

> Make sure a copy of the report for today's certification is provided to Health Care Agency.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title PICK NORWOOD ENGINEER

7552 (v3.01) 6/24/2013



Cot of Orange, Health Care Agency, Environme 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611

Health

DA9483035 Page 1 of 1

(714) 433-6000 ochealthinfo.com/eh

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 06/01/2012

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service: F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Joyce Krall, REHS HAZARDOUS WASTE SPECIALIST III (714) 433-6236 jkraij@cchca.com

Mailing Address: **GENERAL SERVICES ADMIN** GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

#### **COMMENTS**

#### **ZZZ9 - INSPECTOR COMMENTS**

This Agency received the facility's UST monitoring system certification and spill bucket testing report for activities conducted on 5-4-12. All tested components passed.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

COPY MAILED TO OWNER

AND/OR

**Date** 

**Signature** 

**FACILITY OPERATOR** 

7552 (v3.01) 6/1/2012



___nty of Orange, Health Care Agency, Envirc.....ntal Health 1241 EAST DYER ROAD, SUITE 120

41 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000 ochealthinfo.com/eh DAX000009 Page 1 of 1

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 05/04/2012 Reinspection Date: 06/03/2012

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service A01-ROUTINE INSPECTION

Joyce Krall, REHS

HAZARDOUS WASTE SPECIALIST III

(714) 433-6236 jkrall@ochca.com

Mailing Address:
GENERAL SERVICES ADMIN
GENERAL SERVICES ADMINSTRATION
24000 AVILA ROAD STE 4100
LAGUNA NIGUEL, CA 92677

THE ITEMS NOTED BELOW WERE OBSERVED DURING COURSE OF THE SITE VISIT. ANY VIOLATIONS OBSERVED MUST BE CORRECTED

TO04 - TANK Monitoring system is not operational. (CA Code of Regulations 2632(c)(2))

Piping sump sensor failed testing. While on site, the testing technician replaced the failed sensor and tested the new. The new sensor passed festing. Violation was abated

#### COMMENTS

#### **ZZZ9 - INSPECTOR COMMENTS**

On site to conduct a routine UST inspection and witness the annual UST monitoring system certification. The testing technician was Brian Halfwassen of CA Hazardeas Services. His testing credentials were reviewed and were current.

Monitoring System Certification.

UST sensors (UST annular, fill sump_piping_sump) tested and passed. Alarms responded. UST has flapper valve for overfill protection. Fill bucket located within sump was tested 1-2 to cooling passed.

Routine inspection:

D

The UST documentation maintained on site and available for review included: valid UST operating permit, UST monitoring plan, UST response plan, designated UST operator (DO) monthly inspection reports, DO facility employee training records, UST test records, and UST monitoring plot plan.

The DO conducting the monthly inspections was Torn Ross. His ICC certification was current with an expiration date of 10-15-12.

SB989 testing was most recently conducted on 8-12-10. Testing is required once every 3 years. Testing will become due 8-12-13.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

Signature

A. The Morana mongers

<u>Date</u>

7552 (v3.01) 5/4/2012



County of Orange, Health Care Agency, Environmental Health 1241 EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 05/23/2011

**Reinspection Date:** 

Type of Facility: 7095-UNDERGROUND STORAGE TANK (PR)

Service:

F04-FOLLOW-UP INSPECTION -

**OFF-SITE** 

Joyce Krall, REHS

HAZARDOUS WASTE SPECIALIST III

(714) 433-6236

Mailing Address: **GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION** 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

LU	$1 \mathrm{MM}$	10

#### **ZZZ9 - INSPECTOR COMMENTS**

This Agency received the facility's UST monitoring system certification and spill bucket testing report for activities conducted on 5-4-11. All tested components passed.

1	)	
1		

declare that I have examined and	d received a copy of this inspection report.		
Print Name and Title	COPY MAILED TO OWNER		
	AND/OR		
Signature	FACILITY OPERATOR	Date	

v 2.7





#### INSPECTION REPORT

County of Orange, Health Care Agency, Environmental Health 1241EAST DYER ROAD, SUITE 120 SANTA ANA, CA 92705-5611 (714) 433-6000

PR0024056

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: FA0023992 Inspection Date: 05/04/2011

Reinspection Date:

Type of Facility: 7095-UNDERGROUND STORAGE TANK

(PR)

Service:

A01-ROUTINE INSPECTION

Joyce Krall, REHS

HAZARDOUS WASTE SPECIALIST III

(714) 433-6236

Mailing Address:
GENERAL SERVICES ADMIN
GENERAL SERVICES ADMINSTRATION
24000 AVILA ROAD STE 4100
LAGUNA NIGUEL, CA 92677

#### COMMENTS

#### **ZZZ9 - INSPECTOR COMMENTS**

On site to conduct a routine UST inspection and witness the annual UST monitoring system certification. The testing technician's credentials were reviewed and were current.

Monitoring System Certification:

UST sensors (UST annular, fill sump, piping sump) tested and passed. Alarms responded. UST has flapper valve for overfill protection. Fill bucket located within sump was tested 1/2 hour and passed.

#### Routine inspection:

The UST documentation maintained on site and available for review included: valid UST operating permit, UST monitoring plan, UST response plan, designated UST operator (DO) monthly inspection reports, DO facility employee training records, UST test records, and UST monitoring plot plan.

The DO conducting the monthly inspections was Torn Ross. His ICC certification was current with an expiration date of 10-15-12.

I declare that I have e.	kamined and received a copy of this inspec	ction report.	
Print Name and Title	ANT	ZAM/	
Signature	fill fight	Date	
			5/4/2011



# COUNTY OF ORANGE HEALTH CARE AGENCY

PUBLIC HEALTH SERVICES ENVIRONMENTAL HEALTH

MARK A. REFOWITZ DIRECTOR

RICHARD SANCHEZ, MPH ASSISTANT DIRECTOR

DAVID M. SOULELES, MPH DEPUTY AGENCY DIRECTOR

DENISE FENNESSY, REHS
DIRECTOR
ENVIRONMENTAL HEALTH

MAILING ADDRESS: 1241 E. DYER RD., SUITE 120 SANTA ANA, CA 92705-5611

TELEPHONE: (714) 433-6000 FAX: (714) 754-1732 E-MAIL: ehealth@ochca.com

October 1, 2015

Mailing Address: GENERAL SERVICES ADMINSTRATION CHET HOLIFIELD FEDERAL BLDG 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677 CERTIFIED MAIL

Site Address:

24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

## NOTICE OF VIOLATION

On June 30, 2015, your underground storage tank (UST) operating permit expired and was not reissued due to outstanding violations. To date, this Agency has not received evidence indicating that you are in compliance with all of the required underground storage tank laws and regulations as mandated in the California Health and Safety Code (H&SC) Chapter 6.7 and the California Code of Regulations Title 23.

Section 25299 of the H&SC specifies that any operator who operates an underground storage tank system without a permit and any owner who fails to obtain a permit, or who knowingly fails to take reasonable and necessary steps to assure compliance, are liable for civil penalties of not less than five hundred dollars (\$500.00) or more than five thousand dollars (\$5,000.00) for each day the facility is in violation. Operating UST(s) by your facility without a permit will result in either Administrative Enforcement or a referral to the Orange County District Attorney's Office. If you have any questions, please contact your district inspector at the phone number found on the back of this letter.

Sincerely,

cc:

Liza Frias, REHS Assistant Director Environmental Health

Denise Fennessy, Director, Environmental Health

William Fallon, Deputy District Attorney

Inspector:

Staff # 294 Date: 410+

SUPV. INITIALS:

## **FACILITY INFORMATION**

Facility DBA: Chet Holifield Federal Building

FA # <del>0023993</del> 0023993

Site Address: 24000 Avila Rd.

City: Laguna Niguel

Zip: 92677

UST REMOVAL	SR#	
TA#	Contents	Size

. Complete: yes	Date Completed: 04/07/04  APR 1 3 2004
SERVICE REQUEST	SR # 0105050

TIERED PERMIT		PR#	PR#			
Unit Type Unit ID	Unit Name	Add	Close			



UST INSTALLATION/MODIFICATION PLAN CHECK LIST

FACILITY NAME: Chet Holifield Fed Glog	
ADDRESS: 24000 Avila Rd. Ste 4100	CITY: Laguna Niquel
CONTRACTOR NAME:MaH Thomas	COMPANY: Shirley Env.
CONTRACTOR PHONE NUMBER:	O
CHECK ONE: INSTALLATION MODIFICATION	
NUMBER, TYPE AND VOLUME OF TANKS INSTALLED	
MODIFICATION IS FOR: Repipe, New Fill & pip	sing sump spill buckets
erc.	

		DATE	
		COMPLETED	INITIAL
PLANS REVIEWED AND APPROVED		1/21/04	194
COPY OF PRIMARY CONTRACTOR AND SUBCONTRACTOR LICEN SUBSTANCE CERTIFICATION RECEIVED	ISE AND HAZ.	120g	
PASSED VACUUM TEST (IF APPLICABLE)		N/A	
PASSED HOLIDAY TEST (COMPOSITE TANKS ONLY)		NIA	
PASSED TANK PRESSURE TEST OR OTHER TEST AS	Primary	NIA	
SPECIFIED BY THE MANUFACTURER	Secondary	NIA	
PASSED PIPELINE PRESSURE TEST OR OTHER TEST AS	Primary	2504	76
SPECIFIED BY THE MANUFACTURER	Secondary	2/9/04	74
PASSED WATER TEST TURBINE AND/OR FILL SUMPS		2/9/04	14
PASSED WATER TEST - UNDER DISPENSER CONTAINMENT/SPIL	L BOXES	NIA	
PASSED MONITORING SYSTEM INSPECTION – SENSORS (ANNUL DISPENSERS, ETC.), LINE LEAK DETECTORS AND POSITIVE SHUAPPLICABLE) DEMONSTRATED OPERATIONAL		3/9/04	
PASSED FINAL INSPECTION - ALL INFO REQUESTED FOR OPERATING PE (INSTALLATION MATCHES PLANS - CONSTRUCTION IS COMPLET		4/7/04	14
SOIL SAMPLE RESULTS RECEIVED AND FORWARDED TO GROUN	IDWATER	2/13/04	14
SYSTEM PASSED TANK/LINE INTEGRITY TEST AND RECEIVED RE	SULTS	3/29/04	19
INSPECTION REPORT COMPLETED AND SUBMITTED TO SUPERV WITH UPDATED CUPA FORMS (IF APPLICABLE)	ISOR	3/9/04	36
INSTALLATION CERTIFICATION FORM RECEIVED, SIGNED BY OW	/NER	4/7/04	J6
INSTALLATION OF HIGH LEVEL ALARM (90%) AND OUTSIDE ENUM	NCIATOR	3/9/04	J4
DATE UST(S) REMOVED (SR#)		1/4	

INSPECTOR ON-SITE FOR INSTALLATION/MODIFICATION (PRINT NAME)







## COUNTY OF ORANGE CERTIFIED UNIFIED PROGRAM AGENCY - CUPA

HEALTH CARE AGENCY / ENVIRONMENTAL HEALTH
2009 E. EDINGER AVENUE, SANTA ANA, CA 92705-4720

Telephone: (714) 667-3600 / FAX: (714) 568-5116

#### **UST FACILITY MODIFICATION APPLICATION**

## SUBMIT A SEPARATE FORM FOR EACH TYPE OF CONSTRUCTION ACTIVITY

(e.g. Installations, Removal	s, System Modifications, Repairs, etc.)
SITE INFORMATION  CHET HOUPIEUD FEDERAL  ADDRESS: 29000 AVICA ROAD (2)	SUBMITTAL DATE: 01.13.09
CAGUNA NIGVEL	CITY CODE TELEPHONE NO: 949.643.1027  CONTACT NAME: TOM PHILLIPS
APPLICANT REQUESTOR  APPLICANT REQUESTOR  MATT THOMAS  ADDRESS: 1927 THEEL AUS, SUITE  CITY: SO BL MONTE  STATE: CAR ZIP: 91733  THERMONENO: 800 533 4030  ALTERNATE # (CELL, PAGER) 626 444 7017	COMPANY NAME: SHIPLET ENVIRONMENT  APPLICANTS SIGNATURE (TANK OWNER OR DESIGNEE)  UPC UST Forms are required to be submitted prior to pick up of approved UST plans. Forms provided at Plan Check Counter or at http://www.oc.ca.gov/hca/regulatory/cupa/forms.htm
TYPE OF CONSTRUCTION  UST PLAN TYPE:  CODE	CONTRACTOR INFORMATION  (Persons performing work on USTs must meet specific State Contractors Licensing Board requirements)
	CONTACT RERSON MATT THOMAS
☐ INSTALLATION (S) # T01  ☐ CLOSURE (S) – REMOVAL (S) # T02	BUSINESS NAME SHIPLEY ENU. ADDRESS 1927 THURK AND, SUITCE CITY SO EL MONTE
CSYSTEM MODIFICATION (REPIPE, REPAIR TO PIPING) T03	STATE CA ZIP 91733
☐ REPAIR (S) OR RELINE (S) USTs	TELEPHONE NO. 800 533 4030
OTHER (SPECIFY)	COINTRACTORS LICENSE TYPE A, HIC, 1487
OF (4) SETS OF PLANS TO THIS DIVISION. THESE PLANS MODIFICATION. ALL PLANS OR REPORTS REQUIRED MUST PLAN APPROVAL AND FEES ARE VALID FOR ONE YEAR. IF OF THE APPROVAL DATE, NEW PLANS AND FEES MUST BE:	TANKS HAVE NOT BEEN REMOVED, INSTALLED OR MODIFIED WITHIN ONE YEAR SUBMITTED  1450 # 184259  FICE USE ONLY  CHECK # 6790 RCVD.BY: M. 1-13-09

M/h.to OC OT IDA

Dink - Nata Entry

E042 00 4222

* Plan - vision



Testing & Tank Management Services

January 20, 2003

Mr. Jeremy Grant
Orange County Health Care Agency
2009 East Edinger Avenue
Santa Ana, California 92705

RE:

SB 989 Compliance Repair/Modification
Chet Holifield Federal Building
24000 Avila Road
Laguna Niguel, Ca

applicant.
In addition
permits repuilding

Dear Jeremy:

AP. ROVED

ORANGE COUNTY HEALTH CARE AGENCY
ENVIRONMENT HEALTH DIVISION
HAZARDOUS MATERIALS MANAGEMENT SECTION
THIS APPROVAL IS VALID FOR 12 MONTHS FROM
THE APPROVAL DATE

1.12

J. Lavart
Plan Reviewed By

320105050

2104 Date

This approval shall not be construed to permit the violation of any law, nor does it prevent further corrections of errors found on the plans. Plans must be resubmitted for approval if any additional changes are made by the applicant

In addition to this approval, all applicable permits required by the local fire department, building department, and the Air Quality Management District must be obtained.

Underground tank installation, removal, and repair inspections are required and must be

Enclosed please find the Shirley Environmental Workbland for an appointment.

Repair/Modification Project to be completed at the above referenced site.

A copy of these approved plans must be Based on the current site conditions, Shirley Environmental shall-painformal hierfollowing:

- Remove old underground fuel oil supply and fuel oil return piping
- · Provide and install new underground flexible fuel piping
- Provide and install new tank top dump
- Provide and install new tank monitoring console and leak sensors
- Perform SB 989 Re-test

In addition to the above scope of work, environmental sampling shall occur prior to the installation of the new piping. Shirley Environmental will provide a geologist onsite to collect, package and deliver the samples to an analytical laboratory. A final certified report including the results of laboratory testing shall be submitted to the Orange County Health Care Agency.

Shirley Environmental appreciates the opportunity to work with Orange County Health Care Agency. Should you have any questions or require additional information, please feel free to call.

Sincerely.

ORANGE COUNTY HEALTH CARE AGENCY
ENVIRONMENTAL HEALTH

Mall Thomas

Matt Thomas RME HAZARDOUS MATERIALS MANAGEMENT SECTION

Final inspection of the continuous leak detector system for the underground tanks at this facility is required. Contact this office to schedule an inspection 48 hours in advance. Telephone (714) 667 - 3600

1928 Tyler Avenue, Suite K South El Monte, CA 91733-3622 (626) 444-7447 (800) 533-4030 Fax (626) 444-7017

An integrity test is required per California Health & Safety Code Chapter 6.7



#### 1. INTRODUCTION

Currently the site operates (1) 550 gallon, fiberglass reinforced plastic (FRP), double wall underground storage tank. The tank supplies fuel to (1) emergency generator (see Figure 1). Information obtained by Shirley Environmental from the Chet Holifield Federal Building indicated that fuel piping associated with the underground storage tank system had problems with regard to passing an SB 989 secondary containment, pressure (hydrostatic) test.

#### 2. SCOPE OF WORK

Based on the current site conditions, Shirley Environmental shall perform the following tasks:

- Remove old underground fuel oil supply and fuel oil return piping
- Provide and install new underground flexible fuel piping
- Provide and install new tank top sump
- Provide and install new tank monitoring console and leak sensors
- Perform SB 989 Re-test

The following is a detailed description:

#### 2.1 REMOVAL OF OLD UNDERGROUND FUEL OIL SUPPLY AND RETURN PIPING

Shirley Environmental shall remove the surface asphalt, concrete and overburden soil using a backhoe tractor or Bobcat tractor. Once the old piping has been exposed, the entire underground run of fuel oil supply piping and fuel oil return piping will be drained, removed and disposed of as non-hazardous waste.

Work will be performed to characterize the old excavated soil for disposal. A new bedding of pea gravel will be placed prior to the new piping installation. New pea gravel will be used as backfill material to finish the project.

Prior to the exposure of the underground piping the Orange County Health Care Agency shall be contacted for onsite inspection and soil sample collection.

#### 2.2 PROVIDE AND INSTALL NEW FUEL OIL SUPPLY AND FUEL OIL RETURN PIPING

After pea gravel has been placed into the piping trench, Shirley Environmental shall provide new flexible product piping. One-inch Environ flexible, double wall (DW), high density polyethylene (HDPE) piping will be used as for the fuel oil supply and return piping. By using flexible product piping rather then black steel inside of HDPE, will eliminate the potential for line failure caused by abrasion from line torque while the pump is activated.



1/21/04 - Per conversation with Matt Schofild, contra - will replace existing sump and install a new sump on the fill side.

Two A new tank top piping sumpshall be fiberglass to the existing tank collar on the UST at the site. New piping penetration fittings shall be used to install new product piping and re-install existing electrical conduit for low voltage leak monitoring sensors.

Once the piping has been install a primary pressure test shall be scheduled with the OCHCA. Four-inch flexible piping will be used as containment for the one-inch piping. The one-inch piping satisfies the secondary containment requirement. The four-inch piping is being installed only for future maintenance, if necessary. This piping does not satisfy the secondary containment rule (see enclosed cut sheets).

Upon completion of the new piping pressure testing, all piping will be backfilled with a minimum of 18-inch cover of pea gravel with a minimum 6-inch concrete cover.

#### 2.3 PIPING AND INSTALL NEW TANK LEAK MONITORING SYSTEM

Shirley Environmental will provide and install a new continuous electric monitoring system (Veeder Root TLS 300) that will monitor the tank annulus, tank top piping sump and provide a tank overfill alarm at 95-per cent fill capacity. The system shall be installed using existing electrical conduit from the generator storeroom to the UST location. The existing electrical panel is also located in the generator storeroom adjacent to where the new monitoring system console will be located.

#### 3.0 TESTING AND CERTIFICATION

Upon completion of all field activities a final site test shall be performed and all site components and secondary piping modified under this permit shall be tested at one time inspection. At that time all of the leak monitoring system components shall be fail-safe tested. Shirley Environmental shall provide annual certification for the UST system at the site.



## **Cut Sheets**

## GeoVente-Piping



A single wall flexible pipe for vent line applications only. Designed for direct burial applications or installation within the GeoDuct flexible conduit for future replacement capabilities. The piping has a smooth inner bore to provide excellent sealing surface for the connection coupling.

PART NO.	SIZE	APPLICATION
GVP-1200	2"	Vent Piping
GVP-1300	3"	Vent Piping



## GeoFlex®-M Piping



GeoFlex-M is a smooth bore flexible doublewall piping system for pressure or suction systems used in marina applications. The outer stand-off containment jacket offers added UV protection and creates an interstitial space for optimum fluid migration, continuous monitoring and easy periodic pipe testing.

PART NO.	SIZE	MAX O.P.		
GFM-2150	1-1/2"	100 PSI		
GFM-2200	2"	75 PSI		
GFM-2300	3"	75 PSI		




## GeoDuct[™] Conduit



A 4"diameter corrugated flexible conduit used to permit the future replacement of the GeoFlex® piping if desired. Made of high density polyethylene, it is not intended for use as a secondary containment pipe.

PART NO.	SIZE	FOR USE WITH:
GDP-4500I	4"	3/4", 1",1-1/2"& 2" GeoFlex




## GeoDuct-M™ Conduit



A 4"diameter corrugated flexible conduit used to permit the future replacement of the GeoFlex piping if desired. Installation of GeoFlex-M double wall piping within GeoDuct-M conduit provides added UV protection for marina applications. Made of high density polyethylene, it is not intended for use as a secondary containment pipe.

PART NO.	SIZE	FOR USE WITH:
GDM-4500	4"	1-1/2"& 2" GeoFlex M




## GeoDuct" Entry Boots






Patent Granted Other Patents Pending

A double clamped, entry boot designed to seal the GeoDuct™ conduit entry into the wall of a tank sump or dispenser sump. This entry boot includes band clamps for sealing off the GeoDuct conduit as well as the GeoFlex Piping.







GDB-7450

## **Rubber Reducer Donuts**

PART NO.

GDB-4515

GDB-4520

GDB-4530

GDB-7450

SIZE

4" x 2"

4" × 3"

4"

4" × 1-1/2"




A rubber donut used to seal off GeoFlex pipe in various entry boots. Refer to chart below for various donut configurations.

DESCRIPTION

Seals 4" GeoDuct to 1-1/2" GeoFlex

Seals 4" GeoDuct to 2" GeoFlex

PART NO.	DESCRIPTION
RRD-3515-S	Used in GDB-4530 to reduce to 1-1/2" GeoFlex-S w/ Coax fitting
RRD-3515-D	Used in GDB-4530 to reduce to 1-1/2" GeoFlex-D, M w/ Coax fitting
SRD-1010	Used in GDB-7450 for fuel oil 1" supply and 1" return
SRD-1075	Used in GDB-7450 for fuel oil 3/4" supply and 1" return
SRD-4077	Used in GDB-7450 for fuel oil 3/4" supply and 3/4" return
DEP-0075	Reducer Donut Plug used to plug one opening in SRD-4077
RRD-4015-S	Used in GDB-7450 to seal 1-1/2" GeoFlex-S
RRD-4015-D	Used in GDB-7450 to seal 1-1/2" GeoFlex-D or M
RRD-4020-D	Used in GDB-7450 to seal 2" GeoFlex-D or M
RTD-4015-S	Used with GDB-7450 to seal 1-1/2" Geoflex-S (includes airstern)
RTD-4015-D	Used with GDB-7450 to seal 1-1/2" Geoflex-D (includes airstem)
RTD-4020-S	Used with GDB-7450 to seal 2" Geoflex-S (includes airstern)
RTD-4020-D	Used with GDB-7450 to seal 2" Geoflex-D (includes airstem)




GeoDuct with Double Entry Boots

#### Dimensions:

- A: Lid/Riser O.D.
- B. Sump Height
- C Panel Height
- Di Base Diameter



Cutaway of installed observation cap.
All tank sumps can be ordered with a factory installed observation cap (OC0008) by adding the suffix "O" to the part number.



#### Dimensions:

- A: Lid/Riser O.O.
- B: Sump Height
- C Panel Height
- D: Panel Width
- E. Base Diameter

## " Cylindrical Fiberglass Tank Sumps

		Dime	nsions			Burial	
Part #	A	В	C	D	Manhole	min	max
w/ Water Resistant	tids						- \
ACS230CWT	33,180	60"	48"	52	36"	24"	62"
AC4830CWT	33,15	60	48"	48	36"	74"	62"
AC4842CWT	40.00"	60"	48°	487	42"	24"	62"
AC4230CWT	33.150	60"	48"	42.5*	36"	24"	62*
AC4224CWT	26.75"	60"	4.54	42,5	30"	24-	52"
AC3630CWT	33.15	60"	48"	36"	36	24	52"
w/ Bottons & Wate	er-Resistant L	iels.					
AC\$2830CWT	33.15"	60"	481	53	36"	24"	62"
AC48B30CWT	33.15*	60"	4.8		36"		62*
AC42830CWT	53.15*	60*	48*	42.5*	36"	24"	62
AC36B30CWT	33.45*	60"	48"	36	36*	24"	62"
w/ Frietign Fit Liels			. Be				
ACS238CL:	38.00"	60"	48"	52	1 42-	24	62*
ACS230CL	32.00	60"	48"	52"	36"	24	62"
AC4840CL	40.00"	60*	48"	48*	42"	24"	62"
AC4838CL	38.00"	60"	48"	48	42*	24"	62"
AC4830CL	32.00	60"	48"	48*	36"	24*	62
AC4230CL	32:D0"	60"	48"	(2.57)	3.6		62
AC3630CL	\$2.00"	60"	48"	36*	36"	24	62
w/ Baltoms & Frict	ion Fit Lids						
ACS2B38CL	38.00"	60"	48*	52"	1 42"	24"	62
AC\$2B30CL*	32.00"	60"	48"	52"	36"	24"	62"
AC48B40CL	40.00*	60"	48	48"	42"	24"	62"
AC48838CL	38.00"	60"	4.8"	48"	42"	24"	62
AC48B30CL*	32.00"	60"	48"	48"	36"	24"	621
AC42B3OCL	32.00*	60°	48	42.5"	36"	24"	62"
AC36830CL	32.00"	60"	48"	36*	36*	- 24"	62"

Extendition Tank Sumps are nifered in "Offset" and "Full Offset" models. Consult Customer Service for Aradability.

## Multisided Fiberglass Tank Sumps

The state of the s		Dime	rsions			Manhole	Burial	
Part #	A	В	C	D.	E		min	- CERT
wir Water-Resistant Li	ds							
AM452430CWT	33.15"	50*	16"	12.60	47.0	36"	37.5"	52"
AM451630CWT	33.15	50	16"	12,25	45.8"	367	37.5	52"
AM451230CWT	33,15"	46	12"	12.25	45.8"	36"	33.5"	48*
w/ Boitoms & Motor	Resistant L	ids	2	•	.,		*	
AM4524B30CWT	33.15"	50"	16	12.60	47.0	36	37.5	52"
AM4.51 6830 CWT	33.15"	50*	16"	12.25	45.8*	36"	37.5	52"
AM4512830CWT	33.15"	46"	1:2"	12.25"	45.8	36"	33.5"	48"
w/ Eriction Fit Lids		2	*	*.		<i>5.</i> 2.		
AM452434CL	34.00"	50	16	12.60	47.0	36"	37.5	53"
AM452430CL*	30.00"	50	16	12.60"	47.0	36°	37.5"	52
AM451634CL3	34.00"	50°	16"	12,25"	45.8"	36	37.5*	521
AM451630CL	30.00	50	1.6	12.25"	45.8"	367	37.5	52
AM451234CL	34.00"	46"	12"	12.25"	45.8*	36"	33.5"	481
AM451230CL	30.00	46"	12"	12.25"	45.8"	36"	33.5"	48"
w/ Bottonis & Frictio	n Fit Lids			,				
AM4524834CL**	34.00	50*	16	12.60	47.04	36"	37.5"	52"
AM4524B30CL	30.00	50"	161	12.60	47.0"	36"	37.5"	52"
AM4516B34CL	34.00	50"	16	12.25	45.8"	36"	37.5"	52
AM4516B30CL	30.00*	50"	16"	12.25	45.8*	36"	37.3	52"
AM4512B34CL*	34.00"	46"	12"	12.25	45.8"	36"	33.5	48
AM4512830CL	30.00*	46"	12"	12.25	45.8"	36"	33.5	48


Multiplied Tank Symps nie offered in "Offset" models. Consult Costonier Service for Availability.

#### Faotnote:

- Requires field assembly using fiberglass adhesive kits; one kit for tank collar-to-sump base joint and one kit for sump base to top hat joint.
- Requires field assembly using fiberglass adhesive kit for sump base-to-top hat joint. Sump bottom glassed at factory.







# TLS-300C 0-2 Tank Configurable Console

#### **Product Overview**

Designed to provide the highest quality and most cost effective tank monitoring system for non-Retail Commercial, Industrial, and

Municipal tank owners, the new TLS-300C 2 Tank Configurable console offers the ultimate flexibility in one to two tank inventory control and in-tank leak detection systems.

Veeder-Root's TLS-300C Tank Monitoring System can be configured to provide in-tank leak detection for underground storage tank (UST) applications with either one to two leak detection <u>Series 8473 0.1 GPH Magnetostrictive Probes</u>, or one to two <u>8473 Magnetostrictive Inventory Measurement probes</u> to support Aboveground Storage Tank (AST) applications.

Additional configurable options are designed to provide printed documentation and remote monitoring flexibility. The optional Integral Printer provides fast, quiet continuos printouts. The optional SiteFax option can be programmed to transmit leak detection and inventory reports, as well as real-time alarm reporting to fax machines or other communications devices.

Standard features include back-up generator capabilities, as well as capacity to accept up to eight Veeder-Root Series 7943 float-switch sensors. This high quality, low cost family of sensors includes interstitial leak sensors for steel and fiberglass tanks, piping sump sensors, hydrostatic sensors, and discriminating dispenser pan and containment sump sensors.

## **Specifications**

#### Standard Features

- System monitors up to two tanks.
- RS-232 Communication Interface with Auxiliary Port provides two 25-pin D-connectors for data transmission to computers or point-of-sale terminals
- Automatic continuous leak sensing: tank interstitial space; piping sump.
- Audible alarm and display indicate leak location.
- In-tank warnings and alarms are activated for the following conditions: leak, overfill, low product, sudden loss, high water, delivery needed, test failure, tank test not performed.
- · Accepts up to eight interstitial / containment float sensors
- Interstitial and piping sump warnings and alarms are activated for the following conditions: fuel presence, low liquid, high liquid.
- Alarm relays can trigger alarm/security devices.
- Two built-in inputs provide for solid-state or switch input from external devices.
- Two built-in output relays provide for outputs to overfill alarms and external audible and visual warning devices.
- Either relay can shut down the submersible if power to the monitor is lost or a leak is detected.
- Emergency generator applications are selectable via programming.

Product Info

Features & Benefits

Manuals, Guides, & Certifications Ready to Buy Distributor Search

- One system handles a mix of standard and emergency generator tanks.
- · Records generator activity.
- Complete inventory reports before and after generator operation.

#### **Configurable Features**

- Continuous Statistical Leak Detection for in-tank leak detection without tank shutdown.
- Integral printer, which documents inventory leak detection, alarms and setup information.
- SiteFax modem for remote management of leak detection and inventory alarms and reports.
- One or two Veeder-Root Magnetostrictive Probes for 0.1 GPH in-tank leak detection with 4" float kit and 5" cable.
- One or two Veeder-Root Inventory Only Probes for Inventory Control with 4" float kit and 5" cable.

#### **Standard Models**


Console Form No	Description
848590-521	TLS-300C 0-2 Tank Configurable Console with Integral Printer
848590-511	TLS-300C 0-2 Tank Configurable Console without Integral Printer
Software Enhancement Modules	Note: Must be specified on order
330161-001	Static In-Tank Testing
330161-003	CSLD
Optional Site Fax Modem	Note: Must be specified on order
331398-001	Site Fax Modem Kit for TLS-300 Series Consoles

The following probes and sensors are compatible with the TLS-300C Monitoring System:

Form No.	Description
847390-1XX	0.1 GPH Magnetostrictive Probe
847391-XXX	0.1 GPH Magnetostrictive Probe for Alternative Fuels
847390-3XX	Magnetostrictive Probe for Inventory Measurement
794390-40X	Interstitial Sensor for Fiberglass Tanks
794390-420	Interstitial Sensor for Steel Tanks
794390-20X	Piping Sump Sensor
794380-301	Single-Float Hydrostatic Sensor
794380-302	Dual-Float Hydrostatic Sensor
794380-322	Discriminating Dispenser Pan Sensor
794380-352	Discriminating Containment Sump Sensor

Please refer to Veeder-Root Price List for required probe and sensor lengths and corresponding 3-digit Form Number suffix.





SINGLE PORT - OFFSET MANWAY 37-INCH (NEW) (POMECO 6511L-160037RT051)

UST SUMP RISER 42-INCH (NEW) (TOTAL CONTAINMENT ACL42) FILL CAP 4-INCH (NEW) W/ 42-INCH X 30-INCH REDUCER HAZARDOUS MATERIALS MANAGEMENT SECTION (MOR 305C-0100AC) & LID Final inspection of the continuous leak FILL ADAPTER 4-INCH (NEW) detector system for the underground tanks (MOR 305I-0200AA) at this facility is required. Contact this SPILL CONTAINMENT (NEW) office to schedule an inspection 48 hours MANHOLE 4-INCH in advance. Telephone (714) 667 - 3600 3-INCH TO 1-INCH REDUCER 5-GALLON **BOOT (ENVIRON RTR-6010)** (EMCO A1003-008) (NEW) MANWAY 18-INCH (EXISTING) (POMECO 6110-18WT) ELECTRIC J-BOX (EXISTING) (LOW VOLTAGE SENSOR WIRE) **GENERATOR** g. ROOM BASEMENT **FUEL SUPPLY PIPING (NEW)** 1-INCH PRIMARY FLEX. FRP PIPING W/ 3-INCH FLEX FRP SECONDARY PIPING FUEL RETURN PIPING (NEW) 7' 1-INCH PRIMARY FLEX. FRP PIPING W/ 3-INCH FLEX FRP SECONDARY PIPING SUMP PENETRATION FITTING (NEW) 3-INCH (ENVIRON FEB-6300) W/ 3-INCH TO 1-INCH REDUCER BOOT (ENVIRON RTR-6010) INTERSTITIAL SENSOR (EXISTING) (VEEDER ROOT 794390-420)

FOOT VALVE (EXISTING)

-

SUMP SENSOR & CABLE (VEEDER ROOT 794380-208) (EXISTING)

SUMP PENETRATION FITTING (NEW) (ENVIRON FEB-3157)

> All piping associated with underground storage tanks shall be removed and properly disposed

## SITE LOCATION

## CHET HOLIFIELD **FEDERAL BUILDING**

24000 AVILA ROAD LAGUNA NIGUEL, CA.

An integrity test is required per California Health & Safety Code Chapter 6 7

UST SUMP RISER 42-INCH (NEW) (TOTAL CONTAINMENT ACL42) W/ 42-INCH X 30-INCH REDUCER & LID

VENT RISER PIPING (EXISTING) **VENT PIPING 2-INCH** FRP PRIMARY W/ 3-INCH FRP SECONDARY (A.O. SMITH)

NOTICE

ORANGE COUNTY HEALTH CARE AGENCY

**ENVIRONMENTAL HEALTH** 

SUMP PENETRATION FITTING (NEW) 3-INCH (ENVIRON FEB-6300) W/ 3-INCH TO 2-INCH REDUCER **BOOT WITH TEST PORT** (ENVIRON RTR-3020)

42-INCH UST(NEW) SUMP COLLAR (JOOR OR EQUIVALENT) IF SUMP COLLAR DAMAGED OR NONE. USE TOTAL CONTAINMENT ACL42

3/4-INCH STEEL E-CONDUIT (EXISTING)

## APPROVED

ORANGE COUNTY HEALTH CARE AGENCY **ENVIRONMENT HEALTH DIVISION** HAZARDOUS MATERIALS MANAGEMENT SECTION APPROVAL IS VALID FOR 12 MONTHS FROM INE APPROVAL DATE

Carant Pian Reviewed By

SROIDS050

15 s approval shall not be construed to permit n of any law, nor does it prevent that corrections of errors found on the plans. Pla is must be resubmitted for approval if a y additional changes are made by the applicant.

permits required by the local fire department, building department, and the Air Quality Management District must be obtained.

Underground tank installation, removal, and repair inspections are required and must be scheduled 48 hours in advance. Contact (714) 667 - 3600 for an appointment.

A copy of these approved plans must be available at the site at all times.

UNDERGROUND FUEL TANK PIPING REPLACEMENT DETAIL

DATE: 12-10 PROJECT NO.

**FIGURE** 

## County of Orange, Health Care Agency, Environmental Health

2009 E. Edinger Ave., Santa Ana, CA 92705 (714) 667-3600

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID: FA0023992 Inspection Date: 01/29/2004

Type of Facility: UST PLAN CHECK - EACH TANK MODIFICAT

Service:

A08-TANK MODIFICATION INSPECTION

Reinspection Date:

Jeremy Grant, REHS (714) 667-3729

The purpose of this visit is to oversee a soil sampling and perform a 1998 UST upgrade inspection.

At this time I have met with Joe Wilson of Advanced Environmental Services, Inc. He was not aware of Orange County sampling protocol and does not have brass sleeves or a hand auger. The soil sampling will be postponed until tomorrow.

The tank pit and pipe run have been completely excavated and cleared of overburden on this date. I did not observe any metal fittings in contact with soil. The supply and return lines were double walled and a piping sump was present.

A corrosion proof spill bucket was present on the fill riser.

This tank system appears to have met 1998 upgrade requirements.

You may proceed with the tank demolition.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

Signature

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID:

FA0023992

Inspection Date: 01/30/2004

Type of Facility: UST PLAN CHECK - EACH TANK MODIFICAT

Service:

A08-TANK MODIFICATION INSPECTION

Reinspection Date: Jeremy Grant, REHS (714) 667-3729

The purpose of this visit is to oversee a soil sampling.

One soil sample was taken by Joe Wilson of Advanced Environmental Services, Inc.

The sample was logged onto a chain of custody form and packed in an ice chest for transport to a lab.

l declare that I have exan	nined and received	а сору	of this inspection	n report.			
Print Name and Title	Mailed	to	Josea	Pama	A	GSA.	
						-	
Signature						Date	

#### **CHAIN OF CUSTODY**

Orange County Health Care Agency Environmental Health Division 2009 E. Edinger Ave., Santa Ana, CA 92705 Telephone: (714) 667-3700

- 1. ALL SAMPLES ARE TO BE HANDLED AS COURT EVIDENCE, AND ARE TO BE PROPERLY STORED IN A SECURE LOCATION.
- 2. PLEASE WRITE LEGIBLY.
- 3. ATTACH THIS FORM TO THE <u>ORIGINAL</u> REPORT OF THE ANALYTICAL RESULTS AND RETURN THEM TO THIS OFFICE. LABORATORY RESULTS RECEIVED WITHOUT PROPER CHAIN OF CUSTODY DOCUMENTATION WILL NOT BE ACCEPTED.

4.	TO BE COMPLETED BY LABORATORY ANALYST	5.	TO BE COMPLETED BY SAMPLE COLLECT	OR
	LAB NO.:		SITE NAME ADDRESS: Chat Holifield F	20 BH
	DATE RECEIVED: 1/30/64		24000 Avila Rd, Lagura Nig	vel ]
	SAMPLE(S) CONDITION (PLEASE CHECK):		DATE OF COLLECTION: 1/30 04	
	CHILLED: COUNTY SEAL(S) INTACT:		SAMPLE COLLECTOR/COMPANY:	1:120n
	CONTAINER IN GOOD CONDITION: VES		Advanced Environmental Son	nces, Inc.
	DATE ANALYSIS COMPLETED: 4/7/64		TELEPHONE NO.: (800) 850-8680	
	ANALYST: GM		HCA REPRESENTATIVE Deveny Gran	
6.	Run listed Samples For TPH all Free Oxygenates 8260	4-1	> 8015, BTEX, MIDE an	4
0.	SAMPLE DETERMINATION NUMBER 11/2 REQUESTED		TIN	ME OF ECTION
	CH-1 TPH-D, BTEX, MTBE Ab		- 4 1/2 Feet below great the	E-ROA IIS
7.	CHAIN OF CHA		DDY Health 1/30/04.11.5	5 PM
		PANY/A	AGENCY INCLUSIVE DATES/TIMES	PM
	SIGNATURE COMI	PANY/A	AGENCY INCLUSIVE DATES/TIMES	- A A
	4. Forn locks DCM	PANY/A	AGENCY INCLUSIVE DATES/TIMES	
	5.		AGENCY INCLUSIVE DATES/TIMES	\$ ( )
	SIGNATURE COM 6.		AGENCY INCLUSIVE DATES/TIMES	
	SIGNATURE COM	PANY/A	AGENCY INCLUSIVE DATES/TIMES	3



## LABORATORY REPORT

Prepared For: Advanced Environmental Services, Inc.

Advanced Environmental Services, Inc. 7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project: CHET HOLIFIELD FED. BLDG.

Sampled: 01/30/04 Received: 01/30/04

Issued: 02/10/04

NELAP #01108CA CA

CA ELAP #1197

The results listed within this Laboratory Report pertain only to the samples tested in the laboratory. All soil samples are reported on a wet weight basis unless otherwise noted in the report. This Laboratory Report is confidential and is intended for the sole use of Del Mar Analytical and its client. This report shall not be reproduced, except in full, without written permission from Del Mar Analytical. The Chain(s) of Custody, 2 pages, are included and are an integral part of this report.

This entire report was reviewed and approved for release.

#### SAMPLE CROSS REFERENCE

LABORATORY ID
INA1651-01

**CLIENT ID** 

CH-1-4 1/2'

**MATRIX** 

Soil

Del Mar Analytical, Irvine

Pat Abe

Project Manager

RECEIVED HCA/RH

FEB 17 2004

**ENVIRONMENTAL HLTH** 



Advanced Environmental Services, Inc.

Project ID: CHET HOLIFIELD FED. BLDG.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson

Report Number: INA1651

Sampled: 01/30/04

Received: 01/30/04

## **EXTRACTABLE FUEL HYDROCARBONS (CADHS/8015 Modified)**

Analyte	Method	Batch	Reporting Limit	Result	Factor	Extracted Extracted	Analyzed	Qualifiers
Sample ID: INA1651-01 (CH-1-4 1/2) Reporting Units: mg/kg	- Soil)							
EFH (C8 - C40)	EPA 8015 MOD.	4B03058	5.0	27	1	2/3/2004	2/7/2004	CR
Surrogate: n-Octacosane (50-125%)				69 %				

Del Mar Analytical, Irvine Pat Abe



Advanced Environmental Services, Inc.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

#### BTEX/OXYGENATES by GC/MS (EPA 8260B)

Analyte	Method	Batch	Reporting Limit	Sample Result		Date Extracted	Date Analyzed	Data Qualifiers
Sample ID: INA1651-01 (CH-1-4 1/2 Reporting Units: ug/kg	' - Soil)							
Benzene	EPA 8260B	4B04025	2.0	ND	1	2/4/2004	2/5/2004	
Ethylbenzene	EPA 8260B	4B04025	2.0	ND	1	2/4/2004	2/5/2004	
Toluene	EPA 8260B	4B04025	2.0	ND	1	2/4/2004	2/5/2004	
o-Xylene	EPA 8260B	4B04025	2.0	ND	1	2/4/2004	2/5/2004	
m,p-Xylenes	EPA 8260B	4B04025	2.0	ND	1	2/4/2004	2/5/2004	
Xylenes, Total	EPA 8260B	4B04025	4.0	ND	1	2/4/2004	2/5/2004	
Di-isopropyl Ether (DIPE)	EPA 8260B	4B04025	5.0	ND	1	2/4/2004	2/5/2004	the same of
Ethyl tert-Butyl Ether (ETBE)	EPA 8260B	4B04025	5.0	ND	1	2/4/2004	2/5/2004	
tert-Amyl Methyl Ether (TAME)	EPA 8260B	4B04025	5.0	ND	1	2/4/2004	2/5/2004	
Methyl-tert-butyl Ether (MTBE)	EPA 8260B	4B04025	5.0	ND	1	2/4/2004	2/5/2004	
tert-Butanol (TBA)	EPA 8260B	4B04025	100	ND	1	2/4/2004	2/5/2004	
Surrogate: Dibromofluoromethane (80	)-125%)			108 %				
Surrogate: Toluene-d8 (80-120%)				102 %				
Surrogate: 4-Bromofluorobenzene (80	-120%)			88 %				

Del Mar Analytical, Irvine Pat Abe



Advanced Environmental Services, Inc.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

### METHOD BLANK/QC DATA

## EXTRACTABLE FUEL HYDROCARBONS (CADHS/8015 Modified)

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC	RPD	RPD Limit	Data Qualifiers
Batch: 4B03058 Extracted: 02/03/	04									
Blank Analyzed: 02/04/04 (4B030	58-BLK1)									
EFH (C8 - C40)	ND	5.0	mg/kg							
Surrogate: n-Octacosane	5.04		mg/kg	6.67		76	50-125			
LCS Analyzed: 02/04/04 (4B0305	8-BS1)									
EFH (C8 - C40)	25.7	5.0	mg/kg	33.3		77	45-115			
Surrogate: n-Octacosane	4.86		mg/kg	6.67		73	50-125			
Matrix Spike Analyzed: 02/04/04	(4B03058-N	<b>AS1</b> )			Source: I	NA1621	-01			
EFH (C8 - C40)	582	25	mg/kg	33.3	300	847	35-115			M- $HA$
Surrogate: n-Octacosane	10.2		mg/kg	6.67		153	50-125			Z3
Matrix Spike Dup Analyzed: 02/04	4/04 (4B030	)58-MSD1)			Source: I	NA1621	-01			
EFH (C8 - C40)	451	25	mg/kg	33.3	300	453	35-115	25	30	M- $HA$
Surrogate: n-Octacosane	9.37		mg/kg	6.67		140	50-125			Z3

Del Mar Analytical, Irvine Pat Abe



Advanced Environmental Services, Inc.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

#### METHOD BLANK/QC DATA

## BTEX/OXYGENATES by GC/MS (EPA 8260B)

		Reporting		Spike	Source		%REC		RPD	Data
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Qualifiers
Batch: 4B04025 Extracted: 02/04	/04									
Blank Analyzed: 02/04/04 (4B040	25-BLK1)									
Benzene	ND	2.0	ug/kg							
Ethylbenzene	ND	2.0	ug/kg							
Toluene	ND	2.0	ug/kg							
o-Xylene	ND	2.0	ug/kg							
m,p-Xylenes	ND	2.0	ug/kg							
Xylenes, Total	ND	4.0	ug/kg							
Di-isopropyl Ether (DIPE)	ND	5.0	ug/kg							
Ethyl tert-Butyl Ether (ETBE)	ND	5.0	ug/kg							
tert-Amyl Methyl Ether (TAME)	ND	5.0	ug/kg							
Methyl-tert-butyl Ether (MTBE)	ND	5.0	ug/kg							
tert-Butanol (TBA)	ND	100	ug/kg							
Surrogate: Dibromofluoromethane	51.3		ug/kg	50.0		103	80-125			
Surrogate: Toluene-d8	53.3		ug/kg	50.0		107	80-120			
Surrogate: 4-Bromofluorobenzene	51.2		ug/kg	50.0		102	80-120			
LCS Analyzed: 02/04/04 (4B0402	5-BS1)									
Benzene	48.7	2.0	ug/kg	50.0		97	70-120			
Ethylbenzene	50.0	2.0	ug/kg	50.0		100	75-125			
Toluene	48.2	2.0	ug/kg	50.0		96	75-120			
o-Xylene	50.9	2.0	ug/kg	50.0		102	75-125			
m,p-Xylenes	103	2.0	ug/kg	100		103	75-125			
Xylenes, Total	154	4.0	ug/kg	150		103	75-125			
Di-isopropyl Ether (DIPE)	53.0	5.0	ug/kg	50.0		106	65-135			
Ethyl tert-Butyl Ether (ETBE)	50.0	5.0	ug/kg	50.0		100	60-140			
tert-Amyl Methyl Ether (TAME)	47.4	5.0	ug/kg	50.0		95	60-140			
Methyl-tert-butyl Ether (MTBE)	47.1	5.0	ug/kg	50.0		94	55-145			
tert-Butanol (TBA)	269	100	ug/kg	250		108	70-140			
Surrogate: Dibromofluoromethane	50.1		ug/kg	50.0		100	80-125			
Surrogate: Toluene-d8	53.6		ug/kg	50.0		107	80-120			
Surrogate: 4-Bromofluorobenzene	53.5		ug/kg	50.0		107	80-120			

Del Mar Analytical, Irvine

Pat Abe

Alton Ave., Irvine, CA 92606 (949) 261-1022 FAX (949) 261-1228 1014 E. Cooley Dr., Suite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1046 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 (858) 505-8596 FAX (858) 505-9689 9830 South 51st St., Suite B-120, Phoenix, AZ 85044 (480) 785-0043 FAX (480) 785-0851 2520 E. Sunset Rd. #3, Las Vegas, NV 89120 (702) 798-3620 FAX (702) 798-3621

Advanced Environmental Services, Inc.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

#### METHOD BLANK/QC DATA

### BTEX/OXYGENATES by GC/MS (EPA 8260B)

		Reporting		Spike	Source		%REC		RPD	Data
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	<b>RPD</b>	Limit	Qualifiers
Batch: 4B04025 Extracted: 02/04	1/04									
Matrix Spike Analyzed: 02/04/04	(4B04025-M	S1)			Source:	INA1477	-10RE1			
Benzene	44.4	2.0	ug/kg	50.0	ND	89	65-130			
Ethylbenzene	46.4	2.0	ug/kg	50.0	ND	93	70-130			
Toluene	44.3	2.0	ug/kg	50.0	ND	89	70-125			
o-Xylene	47.7	2.0	ug/kg	50.0	ND	95	70-125			
m,p-Xylenes	95.0	2.0	ug/kg	100	ND	95	70-125			
Xylenes, Total	143	4.0	ug/kg	150	ND	95	70-125			
Di-isopropyl Ether (DIPE)	47.9	5.0	ug/kg	50.0	ND	96	65-145			
Ethyl tert-Butyl Ether (ETBE)	44.0	5.0	ug/kg	50.0	ND	88	60-145			
tert-Amyl Methyl Ether (TAME)	39.2	5.0	ug/kg	50.0	ND	78	60-145			
Methyl-tert-butyl Ether (MTBE)	41.5	5.0	ug/kg	50.0	3.5	76	50-150			
tert-Butanol (TBA)	282	100	ug/kg	250	ND	113	65-140			
Surrogate: Dibromofluoromethane	49.7		ug/kg	50.0		99	80-125			
Surrogate: Toluene-d8	52.4		ug/kg	50.0		105	80-120			
Surrogate: 4-Bromofluorobenzene	51.6		ug/kg	50.0		103	80-120			
Matrix Spike Dup Analyzed: 02/0	04/04 (4B0402	25-MSD1)			Source:	INA1477	-10RE1			
Benzene	54.4	2.0	ug/kg	50.0	ND	109	65-130	20	20	
Ethylbenzene	55.7	2.0	ug/kg	50.0	ND	111	70-130	18	20	
Toluene	54.7	2.0	ug/kg	50.0	ND	109	70-125	21	20	R
o-Xylene	56.6	2.0	ug/kg	50.0	ND	113	70-125	17	20	
m,p-Xylenes	115	2.0	ug/kg	100	ND	115	70-125	19	20	
Xylenes, Total	171	4.0	ug/kg	150	ND	114	70-125	18	20	
Di-isopropyl Ether (DIPE)	59.6	5.0	ug/kg	50.0	ND	119	65-145	22	20	R
Ethyl tert-Butyl Ether (ETBE)	54.6	5.0	ug/kg	50.0	ND	109	60-145	22	25	
tert-Amyl Methyl Ether (TAME)	52.1	5.0	ug/kg	50.0	ND	104	60-145	28	25	R
Methyl-tert-butyl Ether (MTBE)	52.2	5.0	ug/kg	50.0	3.5	97	50-150	23	25	
tert-Butanol (TBA)	35.4	100	ug/kg	250	ND	14	65-140	155	30	M2, R-3
Surrogate: Dibromofluoromethane	51.2		ug/kg	50.0		102	80-125			
Surrogate: Toluene-d8	52.8		ug/kg	50.0		106	80-120			
Surrogate: 4-Bromofluorobenzene	52.4		ug/kg	50.0		105	80-120			

Del Mar Analytical, Irvine

Pat Abe

Project Manager



Alton Ave., Irvine, CA 92606 (949) 261-1022 FAX (949) 261-1228 1014 E. Cooley Dr., Suite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1046 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 (858) 505-8596 FAX (858) 505-9689 9830 South 51st St., Suite B-120, Phoenix, AZ 85044 (480) 785-0043 FAX (480) 785-0851 2520 E. Sunset Rd. #3, Las Vegas, NV 89120 (702) 798-3620 FAX (702) 798-3621

Advanced Environmental Services, Inc.

7 Amato

**R-3** 

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

#### DATA QUALIFIERS AND DEFINITIONS

CR The carbon range of the fuel found in the sample = C8-C38

M-HA Due to high levels of analyte in the sample, the MS/MSD calculation does not provide useful spike recovery information. See Blank Spike (LCS).

M2 The MS and/or MSD were below the acceptance limits due to sample matrix interference. See Blank Spike (LCS).

R The RPD exceeded the method control limit due to sample matrix effects. The individual analyte QA/QC recoveries, however, were within acceptance limits.

The RPD exceeded the method control limit due to sample matrix effects.

The sample required a dilution due to the nature of the sample matrix. Because of this dilution, the surrogate spike concentration in the sample was reduced to a level where the recovery calculation does not provide useful information.

ND Analyte NOT DETECTED at or above the reporting limit or MDL, if MDL is specified.

RPD Relative Percent Difference

#### ADDITIONAL COMMENTS

#### For 8260 analyses:

Due to the high water solubility of alcohols and ketones, the calibration criteria for these compounds is <30% RSD. The average % RSD of all compounds in the calibration is 15%, in accordance with EPA methods.

#### For Extractable Fuel Hydrocarbons (EFH, DRO, ORO):

Unless otherwise noted, Extractable Fuel Hydrocarbons (EFH, DRO, ORO) are quantitated against a Diesel Fuel Standard.

**Del Mar Analytical, Irvine**Pat Abe
Project Manager



Alton Ave., Irvine, CA 92606 (949) 261-1022 FAX (949) 261-1228 1014 E. Cooley-Or., Suite A, Colton, CA 92324 (909) 370-4667 FAX (909) 370-1046 9484 Chesapeake Dr., Suite 805, San Diego, CA 92123 (658) 505-8596 FAX (658) 505-9689 9830 South 51st St., Suite B-120, Phoenix, AZ 85044 (480) 785-0043 FAX (480) 785-0851 2520 E. Sunset Rd. #3, Las Vegas, NV 89120 (702) 798-3620 FAX (702) 798-3621

Advanced Environmental Services, Inc.

7 Amato

Mission Viejo, CA 92692 Attention: Joe Wilson Project ID: CHET HOLIFIELD FED. BLDG.

Report Number: INA1651

Sampled: 01/30/04 Received: 01/30/04

#### **Certification Summary**

#### Del Mar Analytical, Irvine

Method	Matrix	NELAP	CA
EPA 8015 MOD.	Soil	X	X
EPA 8260B	Soil	X	X

NV and NELAP provide analyte specific accreditations. Analyte specific information for Del Mar Analytical may be obtained by contacting the laboratory or visiting our website at www.dmalabs.com.





#### INSPECTION REPORT

#### County of Orange, Health Care Agency, Environmental Health

2009 E. Edinger Ave., Santa Ana, CA 92705 (714) 667-3600

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

Record ID:

FA0023992

Inspection Date: 02/05/2004

Type of Facility: UST PLAN CHECK - EACH TANK MODIFICAT

Service:

A08-TANK MODIFICATION INSPECTION

Reinspection Date:

Jeremy Grant, REHS (714) 667-3729

The purpose of this visit is to perform a primary inspection.

At this time the primary supply and return piping is holding at 78 PSI. The vent line is holding at 28 PSI.

All primary fittings were soap tested on this date, no bubbles were observed.

After 30 minutes time elapsed, the pressures remain unchanged.

You have passed the primary inspection.

The secondary inspection has been scheduled for 02/09/04 at 7:30 AM.

I declare that I have examined and received a copy of this inspection report.

Print Name and Title



#### INSPECTION REPORT

#### County of Orange, Health Care Agency, Environmental Health

2009 E. Edinger Ave., Santa Ana, CA 92705 (714) 667-3600

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677 Record ID: F.

FA0023992

Inspection Date: 02/09/2004

Type of Facility: UST PLAN CHECK - EACH TANK MODIFICAT

A08-TANK MODIFICATION INSPECTION

Service: A08
Reinspection Date:

Jeremy Grant, REHS (714) 667-3729

The purpose of this visit is to perform an inspection of the secondary piping and sumps. At this time the secondary return, supply, and vent piping is holding at 5 PSI. Both UST sumps are filled with water to 2 inches above the highest penetrations.

All secondary clamshell fittings were soap tested on this date, no bubbles were observed.

After 30 minutes time elapsed the pressure remains unchanged. The water level in the sumps remains unchanged.

You have passed the secondary inspection.

You must provide 48 hours notice to schedule the final inspection

I declare that I have examined and received a copy of this inspection report.

Print Name and Title

Signature

Date 2

Environmental Health One Copy

F272-09.373Ae

DISTRIBUTION:

Operator One Copy



#### INSPECTION REPORT

### County of Orange, Health Care Agency, Environmental Health

2009 E. Edinger Ave., Santa Ana, CA 92705 (714) 667-3600

CHET HOLIFIELD FEDERAL BLDG 24000 AVILA RD STE 4100 LAGUNA NIGUEL, CA 92677

Mailing Address: GENERAL SERVICES ADMIN GENERAL SERVICES ADMINSTRATION 24000 AVILA ROAD STE 4100 LAGUNA NIGUEL, CA 92677

FA0023992 Record ID: Inspection Date: 03/09/2004

Type of Facility: UST PLAN CHECK - EACH TANK MODIFICAT

Service:

A08-TANK MODIFICATION INSPECTION

Reinspection Date:

Jeremy Grant, REHS (714) 667-3729

The purpose of this visit is to perform a final inspection. A mechanical inspection will also be performed on this date.

The following sensors were tested on this date....

One fill sump sensor (liquid) One piping sump sensor (liquid) One annular sensor (brine)

All three sensors triggered an audible/visual alarm when inverted on this date.

An overfill probe was also tested on this date. The probe triggered an audible/visual alarm on an outside annunciator when overfill conditions were simulated. The probe was set to alarm at 90%.

UPC forms A & B were provided on this date.

You have passed the final inspection. You have been approved to operate the UST however you must submit the following documents with in 30 days....

- 1. Pipeline integrity test results for the new supply and return lines.
- 2. Updated monitoring procedure and leak response plan.
- 3. Certification for the new Veeder-Root 300C tank monitor.
- 4. UPC form C (Certification of installation)
- 5. UST/Facility plot plan with sensor and monitor locations (example provided).
- * Post construction SB989 tests must be completed by 09/09/04.

I declare that I have examined and received a copy of this inspection report.	
Print Name and Title ANT ZAM I WILL ENC-	
Signature	Date

Environmental Health One Copy Operator One Copy





TOM URAM DIRECTOR

L. REX EHLING, M.D. HEALTH OFFICER

ENVIRONMENTAL HEALTH DIVISION ROBERT E. MERRYMAN, R. S. MPH DEPUTY DIRECTOR

MAILING ADDRESS: P.O. BOX 355 SANTA ANA, CA 92702

## FACILITY MODIFICATION **APPLICATION** (INSTALLATION/REMOVAL/REPAIR)

## **HEALTH CARE AGENCY PUBLIC HEALTH SERVICES**

**ENVIRONMENTAL HEALTH DIVISION** 2009 E. EDINGER AVENUE SANTA ANA, CALIFORNIA 92705

(COMPLETE PAGES 1 & 2)	ANTA ANA, CALIFORNIA 92705 (714) 667-3700	DATE: 1-15-93
FACILITY INFORMATION , , ,	TYPE OF CONSTRUCTION	
NAME: Fedra Build.  STREET ADDRESS: 24000 BUILA Auc  CITY: LAGUNA Wigel  TOTAL NUMBER OF TANKS (AFTER INSTALLATION/REMOV	INDICATE NO. OF TANK(S) PAIRED/INSTALLED BELOW: (COMPLETE PAGE 2 - INDIC BE INSTALLED/REMOVED, OR REPAIR)	ATING THE TANKS TO
AT THIS LOCATION:	INSTALLATION(S)	*
GASOLINE STATIONFAR	REPAIR(S)/RELINE(S	) TO USTs
GOVERNMENT OTH	IER CLOSURE(S)/REMOVAL	.(S)
TANK OWNER	SYSTEM MODIFICATIO	N (E.G., REPIPE, REPAIR TO
NAME (CORP. , INDIVIDUAL PUBLIC AGENCY):	PIPING)	
Same-	OTHER (SPECIFY)	
STREET ADDRESS:	24 HOUR EMERGENCY CONTAC	T PERSON
CITY:	DAYS: X. LOWSO	on 310 4395964 TELEPHONE
TELEPHONE NO.: 2/3-894-6060	NIGHTS: //	/ / TELEPHONE
BILL TO NAME: T. T. M.S.  BILL TO ADDRESS: 100 COPDIALE P	APPLICANT  NAME: KOCIEC / PLEASE PRINT	in Lawson
CITY: Culver C.Ly	SIGNATURE:	Jans
STATE: ZIP: 40236	COMPANY NAME:	T.M.S.
TELEPHONE NO.: 1.800 660 TTMS	TELEPHONE NO.: / Sc	0,660 TTMS.
	FACILITY OPERATOR (CONT.	ICT PERSON)
	NAME:	
	BUSINESS TELEPHONE NO.:	213-8946060.
NOTE: NEW INSTALLATIONS, CLOSURES, REPAIRS SUBMITTAL OF (4) SETS OF PLANS TO THIS CONSTRUCTION OR MODIFICATION. ALL F SUBMITTAL.	DIVISION. THESE PLANS MUST BE APP	PROVED PRIOR TO THE INITIATION OF ANY
PLAN CHECK NO.: 93-010 FEES PLAN APPROVAL DATE: BY:		D. BY:K
NUMBER OF TANKS TO RECEIVE A SURCUARGE BULL.	MINNOCD OC TANKS TO DE	ADDED TO BILLING.



PROVIDE THE INFORMATION BELOW FOR ALL TANKS AND PIPING SYSTEMS TO BE INSTALLED, REMOVED OR REPAIRED. ALSO INDIÇATE THE UPGRADE/CHANGES TO BE MADE TO EACH TANK SYSTEM.

	TANK I.D.		#1	#2	#3	#4
	MATERI AL	CURRENT	LY 3- EM!	S Z-Diesel	1- w.oil.	1. Sul Furn
Ş	OR WASTE STO	PROPOSE	D			
STORED	MASIC SIG	PREVIOU	SLY			
	ı	, I.E., UNLEADE	D CC			
Т	YPE (TANK,	SUMP, OTHERS)				
; [D	OUBLE WALL/	SINGLE WALL				
, <u>u</u>	L NUMBER					
•	EAR INSTALL	ED .				
۱ ۷	AULTED/NOT	AULTED				_
- [	MANUFAC	TURER				
	R CAPACIT	(GALLON)				
\	CAPACIT CONSTRU	CTION MATERIAL				
		SS (UNITS)				
ı	INTERIO	RLINING				
	N CAPACIT	(GALLON)				
≀	X -	CTION MATERIAL				
	1	SS (UNITS)				
	ORROSION PR					
7	YPE OF LEAK	DETECTION FOR	USTs			
	LIQUID PROB					
<del></del>	MANUFACTURES OCATION	OF LEAK DETEC	TOR			<del></del>
	UNDER/ABOYE	GROUND)				
- 1	CUCTION/PRES					
1	MAN TITO NECES	CONSTRUCTION				
,   _b	RIMARY	MATERIAL.				
-		MANUFACTURER				
۱ ا		CONSTRUCTION MATERIAL				
;   ^s	ECONDARY	MANUFACTURER				
- 1		DETECTION FOR	ı			
12	PRESSURE LO	SS DEVICE, ETC.	.)		.	
1	VANUFACTURER	OF LEAK DETECT	ror			
ERF	ILL PROTECT	ON (TYPE)				

FORM #86







#### General Services Administration

T. le # 1471

FACILITY SUPPORT CENTER DESIGN & CONSTRUCTION BRANCH, 9PXC 350 S. FIGUEROA STREET, SUITE 301 LOS ANGELES, CA 90071

May 10, 1993

Mr. James C. Strozier, Hazardous Waste Specialist Hazardous Materials Management Section County Of Orange 2009 E. Edinger Ave., Santa Ana, CA 92702

Project Name: Removal of 7 Storage Tanks Re:

Project No: RCA21418

Project Site: Chet Holifield Federal Building

24000 Avila Road, Laguna Niguel, CA 92677

Dear Mr. Strozier:

The approval letter as attached, from Mr. Scott Crail of Integrated Waste Management Department, indicated that the non-hazardous contaminated soil (excavated from tank 7 site) may be disposed to the County Class III landfills. The removal of the Soil is scheduled for 5-12-93.

As discussed with TTMS, we decided to backfill the excavated 2 sites with clean and compactable materials as specified. After the water monitoring wells and boring tests are performed, we will forward the test reports for your review. The recommendation will be included if any contamination needs to be remediated.

Should you have any questions, please call me at 213-894-6329.

Sincerely,

Project Director

cc: 9PXC(Official, Reading File)

Jerry Chang, J.C. Chang & Associates; Chris Thixson, TTMS

Michele Feher, 9L; Ed Wasielewski, 9PXM7

Roger Wiesnoski, 9PXP

05/10/1993 07:05

714568

WASTE MANAGEMENT

PAGE 01



VICKI L WILSON Assistant Director



#### INTEGRATED WASTE MANAGEMENT DEPARTMENT

1200 N. Main Street, Suite 201 Sente Ana, California 92701 (714) 568-4160 FAX (714) 834-0754

May 10, 1993

Ms. Elsa Wong Facility Support Center Design and Construction Branch, 9PXC 350 S. Figueroa Street, Suite 301 Los Angeles, CA 90071


#### Dear Ms Wong:

I am writing you to confirm the acceptance of your department's excavated soil, from the Chet Holifield Federal Building, into County Class III landfills. While the soil is slightly contaminated, it is acceptable for disposal as a non-hazardous material. Please contact me when you have a hauling date, so we may ensure a smooth disposal.

since yely,

Material Regulation Supervisor





# **GENERAL NOTES**

#### SCOPE OF WORK .


- 1 REMOVE SIX (6) EXISTING UNDERGROUND STORAGE TANKS AND ASSOCIATED PIPING, AND ONE (1) ABOVE GROUND ACID STORAGE TANK, ASSOCIATED PIPING, CONCRETE SLAB AND BERN WALLS, STEEL STAIRS AND CATWALK ETC.
- 2 TANK REMOVAL AND DISPOSAL SHALL BE IN ACCORDANCE WITH ALL RELEVANT LOCAL, STATE AND FEDERAL REGULATIONS.
- THE LOCATION OF EXISTING UNDERGROUND UTILITIES IS APPROXIMATE ONLY, THE CONTRACTOR SHALL FIELD VERIFY EXACT LOCATION AND DEPTH OF EXISTING UTILITY LINES WITHIN THE AREA OF WORK. PROTECT IN PLACE ALL EXISTING UTILITY LINES AND APPURTENANCES TO REMAIN. IF DAMAGED THEY SHALL BE REPAIRED BY THE CONTRACTOR AT HIS OWN EXPENSE.
- 4 FILL EXCAVATIONS IN **INCH**EFFFS AND COMPACT TO 90% OF MAXIMUM DENSITY. REPAIR SURFACE TO MATCH EXISTING FOLLOWING TANK REMOVAL.
- CONTRACTOR SHALL APPLY AND PAY FOR ALL REQUIRED PERMITS, INCLUDING COUNTY OF ORANGE, ENVIRONMENTAL HEALTH DIVISION (714) 667-3700, COUNTY FIRE DEPARTMENT (714) 249-2749 AND SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT (714) 396-2000. THE CONTRACTOR SHALL COMPLY WITH THE REQUIREMENTS OF THE COUNTY ENVIRONMENTAL HEALTH DIVISION FORM NUMBER 36 "GUIDELINES FOR THE REMOVAL OF AN UNDERGROUND STORAGE TANK". ALL TESTING, MONITORING, INSPECTIONS ETC. REQUIRED WILL BE PERFORMED BY THE CONTRACTOR. THIS SHALL INCLUDE BUT NOT NECESSARILY BE LIMITED TO CONTINUOUS ON SITE MONITORING READINGS, SOIL SAMPLING AND DELIVERY TO A STATE CERTIFIED LABORATORY, A REPORT FROM THE LABORATORY WILL BE FURNISHED TO THE OWNER AND TO THE AGENCIES NOTED ABOVE. THE CONTRACTOR SHALL PAY ALL FEES, COST ETC. ASSOCIATED WITH THE MONITORING, TESTING, REPORT ETC.
- 6 ALL TANKS TO BE REMOVED ARE CURRENTLY NOT IN USE. CONTRACTOR SHALL DETERMINE IF THEY CONTAIN PRODUCT, AND IF SO SHALL REMOVE AND DISPOSE OF IT IN A LEGAL MANNER.
- 7 ALL ITEMS TO BE DEMOLISHED SHALL BECOME THE PROPERTY OF THE CONTRACTOR AND SHALL BE REMOVED AND DISPOSED OF OFF-SITE IN A LEGAL MANNER.
- 8 CONTRACTOR SHALL PROVIDE TEMPORARY SHORING FOR EXCAVATIONS, AS REQUIRED.
- 9 IN AC PAVED AREAS, REPAVE IN ACCORDANCE WITH DETAIL 1 ON DRAWING C-3 SLOPE NEW PAVING TO DRAIN.
- THE SOIL TESTS PERFORMED ON SOIL SAMPLES TAKEN FROM BORING AT THE THREE SITES INDICATE THAT THE SITES HAVE NOT BEEN CONTAMINATED. THESE RESULTS SHALL NOT RELAX THE TESTING AND MONITORING REQUIREMENTS OF THE CONTRACTOR DURING TANK REMOVAL.
- THE BORINGS FOUND THAT GROUND WATER WAS NOT ENCOUNTERED TO A DEPTH OF 20 FEET AT THE ENERGY PLANT SITE, WAS NOT ENCOUNTERED TO A DEPTH OF 15 FEET AT THE SOUTH ENTRANCE, GROUND WATER WAS ENCOUNTERED AT A DEPTH OF 15 FEET AT BUILDING 502. THESE FACTS ARE NOTED FOR CONTRACTOR INFORMATION ONLY AND NO GUARANTEE, EXPRESSED OR IMPLIED, IS GIVEN WITH RECARD TO THE DEPTH OF GROUND WATER AT THE TIME OF REMOVAL OF THE TANKS.
- 12 DEGASSING OF GASOLINE TANKS AND LOWER EXPLOSION LEVEL TESTING SHALL BE PERFORMED BY A CONTRACTOR LICENSED TO DO SO IN THE STATE OF CALIFORNIA.


PLAN:	GENERAL NO	TES					
SITE:	FEDERAL BU 24000 AVILA LAGUNA NIGI		100 CORPO CULVER CIT 1-(800)-6	RATE POINTE SU Y, CA 90230 60-TTMS	ITE <b>≸</b> 220		
DATE:	JAN 1993	REV.Δ\	SCALE: SEE PLAN	J08 ∳ 11875	DWG 4		

# DESCRIPTION OF TANKS TO BE REMOVED

TANK NO.	ABOVE OR	APPROXIMATE	APPROXIMATE	CONST.	PRODUCT	YEAR
	BELOW	CAPACITY	SIZE			INSTALLED
	GROUND	(GALLONS)			ļ	
	BELOW GROUND		8' DIAMETER			
3	(APPROX 4' COVER)	10,418	28' LONG	STEEL	DIESEL	1969
	BELOW GROUND		8' DIAMETER			
4	(APPROX. 4' COVER)	10,418	28' LONG	STEEL	DIESEL	1969
			6.5' DIAMETER		SULFURIC	
4A	ABOVE GROUND	5,000	21'LONG	STEEL	ACID	1969
	BELOW GROUND	A supl	4' DIAMETER			
5	(APPROX. 4' COVER)	500	6 1/2' LONG	STEEL	WASTE OIL	1969
an market of a selection of the second terror of th	BELOW GROUND		8' DIAMETER			
6	(APPROX. 4' COVER)	10,100	28' LONG	STEEL	GASOLINE	1969
	BELOW GROUND		8' DIAMETER			
7	(APPROX. 4' COVER)	10,100	28' LONG	STEEL	GASOLINE	1969
	BELOW GROUND		4' DIAMETER			
8	(APPROX. 6' COVER)	500	6 1/2' LONG	STEEL	GASOLINE	1969

PLAN: SHOWING TO BE RE	LIST OF TANKS DIOVED	779	777MF			
SITE: FEDERAL 24000 AV LAGUNA 1		CULVER CITY	100 CORPORATE POINTE SUITE \$220 CULVER CITY, CA 90230 1-(800)-660-TTMS			
DATE: JAN 1993	REŸ.Z∆	SCALE:	J08 #	DWC #		
REV.	REV_A	SEE PLAN	118/5	2-2		






SECTION A


PLAN:	SHOWING SECON TANK #4	CTION VIEW	575	<b>PM</b>	7
SITE:	FEDERAL BUI 24000 AVILA LAGUNA NICE		100 CORPORATE POINTE SUITE \$22 CULVER CITY, CA 90230 1-(800)-660-TIMS		
DATE:	JAN 1993	REV.Δ\ REV.Δ\	SCALE: SEE PLAN	JOB # 11875	DWG 4 3-1


# **DEMOLITION NOTES**

- EXISTING UNDERGROUND DIESEL FUEL STORAGE TANKS TO BE REMOVED SEE DRAWING C-1 FOR DESCRIPTION.
- EXISTING ABOVE GROUND SULFURIC ACID STORAGE TANK TO BE REMOVED SEE DRAWING C-1 FOR DESCRIPTION.
- SAWCUT FULL DEPTH EXIST. 3" AC PAVEMENT.
- EXIST 8'-6" X 5'-0" X 18" REINF. CONCRETE SLAB WITH MANHOLE FRAME AND COVER TO BE DEMOLISHED.
- REMOVE EXISTING COMP. AIR AND WATER PIPING AS REQUIRED TO FACILITATE REMOVAL OF TANKS. CAP PIPES TO REMAIN.
- REMOVE ALL ABOVE AND BELOW GROUND 1 1/2" FUEL OIL-SUPPLY AND 1" FUEL OIL RETURN PIPING AND ASSOCIATED VALVES AND FITTINGS. CAP PIPES 6" ± FROM FACE OF WALL. COVER ON UNDERGROUND PIPES 24" +.
- REMOVE EXIST. GUARD RAIL AROUND PUMPS.
- 8 REMOVE EXIST. PUMPS AND CONC. PADS.
- RELOCATE 3' X 4' X 5' HIGH ENCLOSURE WITH PORTABLE FIRE HOSE TO SOUTH WALL OF BUILDING AS SHOWN.
- DEMO. ALL CONCRETE SLABS AND WALLS, ALL STREE PLATFORMS, STAIRS AND SUPPORTS, ALL WATER PIPING, EYEWASH STAND AND HOSE BIBB, ALL AIR PIPING, AIR OUTLETS, VALVING ETC. ALL PROCESS PIPING ETC. WITHIN THE SAWCUT LINES. NOT ALL ABOVEGROUND PROCESS PIPING IS SHOWN. CAP PIPING TO REMAIN AT PERIMETER OF DEMOLITION AREA.
- DISCONNECT AND REMOVE WIRE FROM EXISTING CONDUIT BACK TO PANEL.

PLAN:	DEMOLITION I		575	TTTMF				
SITE:	FEDERAL BUIL 24000 AMILA LAGUNA NIGE	RO.	CULVER CITY,	ORPORATE POINTE SUITE \$22 CCITY, CA 90230 S)-660-TTMS				
DATE:	JAN 1993	REV.∆\ REV.∆\	SCALE: SEE PLAN	J08 <b>#</b> 11875	DWG #			







£ .

NOTE: DETAIL AT EXISTING CONCRETE PAVING SHALL BE THE SAME EXCEPT TACK COAT SHALL NOT BE REQUIRED.

DETAIL 1

PLAN:	SHOWING SAY		575	7	
SITE:	FEDERAL BUI 24000 AVILA LAGUNA NIGE	RD.	100 CORPOR CULVER CITY, 1-(800)-560		220
DATE:	JAN 1993	REV.Z∆	SCALE:	10B #	DWG #
REV.∡	7	REV.Δ\	SEE PLAN	11875	4-2

# **DEMOLITION NOTES**



EXISTING UNDERGROUND WASTE OIL TANK TO BE REMOVED. SEE DRAWING C-1 FOR DESCRIPTION.



EXISTING UNDERGROUND GASOLINE STORAGE TANKS TO BE REMOVED. SEE DRAWING C-1 FOR DESCRIPTION.



T. . . . . REMOVE EXISTING UNDERGROUND FUEL SUPPLY AND RETURN PIPING, VENT PIPING, CONCRETE ISLAND INCLUDING ALL APPURTENANCES (FUEL DISPENSER, LIGHT STANDARD, VENT PIPES, ETC.)


#### SOUTH ENTRANCE SITE



EXISTING UNDERGROUND DIESEL TANK TO BE REMOVED. SEE DRAWING C-1 FOR DESCRIPTION. THIS TANK COULD NOT BE LOCATED DURING FIELD INVESTIGATION. CONTRACTOR SHALL EXCAVATE FUEL LINE INTO BUILDING AND TRACE BACK TO THE TANK.

5 EXIST. FUEL LINE TO BE REMOVED.

PLAN:	SHOWING DI FOR TANKS	MOLITION NOTES 46 & 47	$\frac{1}{2}$	7 M	
SITE:	FEDERAL BUI 24000 AVILA LAGUNA NIGE		100 CORPOR CULVER CITY 1-(800)-66	RATE POINTE SUITI CA 90230 0-TINS	<b>‡</b> 220
DATE:	JAN 1993	REV.∠∆	SCALE:	JOB #	DWG
REV_		REV.Δ\	SEE PLAN	11875	4-3



# **DEMOLITION NOTES**



EXISTING UNDERGROUND GASOLINE STORAGE TANKS TO BE REMOVED. SEE DRAWING C-1 FOR DESCRIPTION. . .

REMOVE EXISTING UNDERGROUND FUEL SUPPLY AND RETURN PIPING, VENT PIPING, CONCRETE ISLAND INCLUDING ALL APPURTENANCES (FUEL DISPENSER, LIGHT STANDARD, VENT PIPES, ETC.)

#### SOUTH ENTRANCE SITE

EXISTING UNDERGROUND DIESEL TANK TO BE REMOVED. SEE DRAWING C-1 FOR DESCRIPTION. THIS TANK COULD NOT BE LOCATED DURING FIELD INVESTIGATION. CONTRACTOR SHALL EXCAVATE FUEL LINE INTO BUILDING AND TRACE BACK TO THE TANK.

EXIST. FUEL LINE TO BE REMOVED.

	SHOWING DE FOR TANK #	MOLITION NOTES 8	775	7 M	F
	Federal Bui 24000 Avila Aguna Nige			RATE POINTE SU (, CA 90230 (0-1TINS	TE #220
DATE:	IAN 1993	REV.∆ REV.∆	SCALE: SEE PLAN	J08 # 11875	DWG #

#### Orange unty Health Care Agency

Environmental Health Division, Hazardous Materials Management Mailing Address: P.O. Box 355, Santa Ana, CA 92702 Office: 2009 E. Edinger, Santa Ana, CA 92705 Telephone: (714) 667-3700

Section

HAZARDOUS WASTE & UNDERGROUND ST	
FILE NO: 00/43/ ACCOUNT NO: 1	0237 - (EPA #:
FACILITY: (het Holifield Bldg	PERMIT:
STREET: 24000 Avila Rd.	MAP COORDINATES:
STREET: 24000 Avila Rd.  CITY: 158 Laguna Niguel, CAZIP: 9	92677 DISTRICT: 401
Jelle	
NEAREST CROSS STREET:	TSD FACILITY?
NEW DBA? NEW BUSINESS? NEW ADDRESS	
NEW INFO:	
HW INSPECTION TYPE: NO OF UST ON	SITE: 7-1 UST INSPECTION TYPE: #7
NUMBER OF EMPLOYEES: # TANKS TO B	
	LAST DATE UST INSPECTED:
HW EXEMPT CODE:	UST EXEMPT CODE:
HW STATUS CODE:	UST STATUS CODE:
BUSINESS OWNER:	PHONE: ()
	PHONE: ()
	PHONE: ()
CONTACT:	
HW BILLING (NAME & MAILING ADDRESS):	UST BILLING (NHME & MAILING ADDRESS)
PHONE: (	PHONE: ()
PROPERTY OWNER (NAME & MAILING ADDRESS):	TANK OWNER (NAME & MAILING ADDRESS):
PHONE: ()	PHONE: ()
EMERGENCY CONTACTS	
DAY: NIGHT. I LENTERED	PHONE: ()
TO LOTTE STATE OF THE PARTY OF	PHONE: ()
ACTIVE ICR: VVFEB 2 1993	
INSPECTOR #: 233 NAME: Brendo	Jo Rienke DATE: 1/29/9:
	PAGE 1 OF 3



# **COUNTY OF ORANGE • HEALTH CARE AGENCY ENVIRONMENTAL HEALTH DIVISION** 2009 EAST EDINGER AVENUE

SANTA ANA. CA 92705-4722

(714) 667-3700
DBA: Chet Holefield BBO.
ADDRESS: 24000 Avila Rd
Laguna Niguel, CA97617
ACCOUNT NUMBER: 10737 FILE NUMBER:
UNDERGROUND STORAGE TANK INSPECTION
VIOLATION DESCRIPTION
196 Failure to submit a "Permit to Operate" application for the USTs at the site 197 Failure to implement/select/develop an approved monitoring system/plan 198 Failure to obtain/show evidence of financial responsibility 291 Failure to submit a diagram showing the location of UST(s) 120 Failure to report changes in the usage of UST(s) within 30 days 125 Failure to report an unauthorized release 130 Failure to develop a response plan to remove the unauthorized release from the secondary container
155 Failure to monitor visually at required frequency 165 Continuous monitoring devices/equipment/tank level monitors/line leak detectors inoperable 180 Failure to annually test and/or submit proof of installation of pipeline leak detectors 185 Failure to submit tank integrity test results within 30 days of test completion 195 Failure to follow procedures when inventory reconciliation/tank gauging exceeds allowable variations 270 Failure to report changes in monitoring alternative procedures within 30 days 275 Failure to properly close UST(s) 280 Failure to properly repair UST(s) 281 Failure to perform tightness/integrity test on tank(s)/pipelines 282 Pressurized line leak detectors are not designed to resist unauthorized tampering
288 Underground storage tank(s) not secured to prevent unauthorized inputs or withdrawals  290 Other
- Witnessed removal of le USTs at this location this date 17 Samples taken at 3 locations at this
property. Contamination noted at south entrance and at maintenance area. Case to be referred to
Cleanup group.
I declare that I have examined and received a copy of this page inspection report.
INSPECTOR #: SIGNATURE:
RECEIVED BY: DATE RECEIVED: PAGE NUMBER OF TOTAL PAGES

Orange Junty Health Care Agency
UNDERGROUND STORAGE TANK INSPECTION REPORT

ADDRESS: 24000 Hvila Rd.

: Laguna Niguel, CA 97677

FILE NO:	AC	COUNT NO		EPA/#	4	
	157		1811	AX	atl.	M
	(X)/	Mh	Ma	1115	110	()())
!HCA TANK ID#	!CODE!TANK #	W	!CODE!TANK	101	CODE! YANK #	1000
!FACILITY TANK ID	! ! 002	1003	1 1004	005	1006	008 !
!MATERIAL STORED	1 1	00000	! !	mana!	man	2000
!Currently	99999	99999	99999	99999	99999	99999
!Proposed	!!!		!!!	3	!	1
!Previously	!!!!		!!!		!	!
!Waste or Product			! !	!	!	1
!FUEL TYPE	!!!		!!!	. !		1
!Trade Secret	!!!		! !	8	!	1
!EXEMPT TYPE	!!!		!!!	· ·	1	!
!	!		! !	1	1	!
!Double/Single Wall	!!!		§ .	1	!	1
!Compartment No.	!!!		1 1	!	1	1
!Year Installed	!!!		1 1	1	!	1
!Vault/Not Vaulted	! !		1		Į.	1
!Primary Wall:	1 1		!!!	1	1	1
!Manufacturer	1 1		1 1		: 500	
!Capacity / Gallons	1 10,000	10,000	1 10,000	10,000!	1	500
!Construct Material	1 1	1,000	1 1	1	1	1
!Thickness & Units	1 1		1 1	1	1	1
!Interior Lining	1 1		1 1	1	i	1
!Secondary Wall:	1 1		1 1	1	i	1
!Manufacturer	1 1		1			
!Capacity / Gallons	1 1		1 1	i	1	1
!Construct Material			5 1	1	1	l l
!Thickness & Units	1		1 1	i	1	-
!Corrosion Protectn	1 1		1 1	1	1	1
!Leak Detect: Type	1 1		1	1	i	1
!Manufacturer	1 1		ş ş	1	i	1
!PIPING: Location	1 1		i i .	1	1	1
!Dispensr/Tank Fill	i i i i		1	1	i	1
'Double/Single Wall			1 1		i	1
!Primary Wall:	1 1		1 1	1	1	1
!Construct Material	1					
!Manufacturer	1		1 1	1	1	1
!Secondary Wall:				1		1
!Construct Material	1 1					
	1 1		: :	<u> </u>		
!Manufacturer	1 1				:	:
!Leak Detect: Type						<u> </u>
!Manufacturer			: :			:
!TYPE OF OVERFILL						
!PROTECTION						1
!SPILL						
!CONTAINMENT						
MONITORING	:35 Powwood	35	35	35	35	35
!METHOD	35 Removed			00!		00
!LAST TANK TEST				!	1	

INSPECTION DATE: 1,29,93

PAGE 3 OF 3

UNDERGROUND	TANK REMOVAL FORM		
(Net Hultield Billy - 24000 Fracility Name	Ivila Road	Lag Niquel, CH	-
,			
Inspector: Devida lueple	LUSI #	IK #	
Inspector: Nevilla Rueplle	Date:	97) Time: 0:00am	
La Paz Cross Street		(7/4) Site Telephone Num	har
115 CSA - 7440C 11 1/2	$\Gamma \mathcal{A}$	Site le replione Mulli	Jei
Owner Carried Parity I	Address		
US GSA - 24000 Hila P Owner Edgar Gray / Mark Grippi Contact Person			
		Telephone Numb	ber
Operator (if different than owner)		Telephone Num	hor
	TTMS		
Chris Roger Lawson Consultant or Contractor Company	Contact Name	Telephone Num	ber
Tank #1: 10 // Cliese Size Const. Mat. Mat. Store	/ Tank #4:		
			red
Tank #2: 1012 diese / Size Const. Mat. Store	Tank #5:	Const. Mat. Mat. Sto	<u>rad</u>
			eu
Tank #3: Size Const. Mat. Store	ed Size	Const. Mat. Mat. Stor	red
Depth to Groundwater: ? unk. ?	ate of Piping:v	emoved	
Proposition 65 Required? p Submitted p	rop. 65 Form Submit	ted on:	
Fire Dept. Personnel On-site: Stace	Lambeta		
Ambient Air Readings on Field Instrument:			
Other Information:			
o ener 1010 mg e ron.			

Rev: 11/04/91



Chef Holfield Bla	lg. 24:00 Avil	a Rd - La	iguna Niguel, ('+1 92677
Facility Name			
PC # 9319010 PT			IR #
Inspector: Brenda.			1-29-93 Time: 8:00am
Field Activity: 4/4	ressed remov	10/0-1 Z.	10,000 gal diesel tank
Tank sat en	Concrete,	Dails. So	umples taken atend
of pads, bene	atntanks	. Sand	fill material appeared
to be fairly co	lean. No	holes	observed in the Z
			ulturic acid tank
			ncrete Containment
area with no &	il exposed.	No San	sples taken near the
and Suturic tank.	,		
1			

(Energy Station) Building Removed SST38 55573-45

Page 2 of 2

Rev: 11/04/91

FORM #1

	TIELD ACTIVITY DESCRIPTION	· Carrier
1 doiling hame	- 2400 Alv. la Rol Lag	una Niguel, CH 92477
PC # 93PC10 ##	92000 LUST #	IR #
	<u>ple</u> Date: 1-2	
	ssectionical of 1-500	
located at south	entionce to Chet Holill	eld 2 samples taken.
1- from spoils, 1- from	excavation. Tankresembles	Swiss cheese with many
whole's observed - pra-sized which appeared to be con	ato an stanination	Swiss cheese with many ectark patches of soil observed
& Witnessed removal o	Topraye adark clay layer ne	* 1-550 gallon waste oil or bottom of facts ere evident. Waste o. Hankazia
where sample the stund of the excapor with an	Juns taken Groundwate	sul observed at the location was observed in the bottom water.
of the execution with an silver of the execution with an silver of the s	ten	
555 5C) (557 6C) (557 6C) (557 6C) (557 6C) (557 6C)	Some groundur with a smalla appears to be	ater observed mount of what gascline
		South Entrance  Figure Sients  Seodiesel  SST 8C  9:05an
Rev: 11/04/91	Page 2 of 2	FORM #1

# UNDERGROUND TANK REMOVAL FORI

Chet Holifield Blog 24000 A	Avika RI		
Facility Name	Address		,
PC # 93/2 1C XI # 92.008 LUS	ST #	IR #	
Inspector: Brema & Pueste	Date: 1-29-93	_ Time: @:c	Pain
La la Z Cross Street			
Cross Street	12/	Site lelep	hone Number
USGSA - 24000 Avila	ress		
_		(714)	643401:
Edgar Gray Contact Person		Telep	643486.
N/A Operator (if different than owner)			
Operator (if different than owner)	=/	Telep	hone Number
Chris Rick Pilat To Consultant or Contractor Company	Contact Name	( <b>310</b> ) 5	68-8290 hone Number
Roger Lawson	Tank #4: 500	Stool	under
Tank #1: 500 Steel diesel 1 Size Const. Mat. Mat. Stored	Size	Const. Mat.	Mat. Stored
Tank #2: 10,000 & Steel gas Size Const. Mat. Met. Stored	Tank #5: Size	Const. Mat.	Mat. Stored
Tank #3: 10 coo Steel gas Size Const. Mat. Mat. Stored	Tank #6: Size	Const. Mat.	Mat. Stored
Depth to Groundwater: 10 ft? Fate of	of Piping: Pen	noval	
Proposition 65 Required? Prop.	65 Form Submitted	on:	
Fire Dept. Personnel On-site: Stacey La	ambeter		
Ambient Air Readings on Field Instrument:	ppm		
Other Information:	/ /		

Rev: 11/04/91

#### 2. 1.1993 11 HATCHY ANALTSIA MESCL

Chart: T.T. M.S. Project No.: 41875

Project Name: CHET HOLLFIELD FEDERAL BULLDLAG

Sample Matrix: SOIL

Method: EPA 9020(BTEX)/8015M(GAS.)/(DIEBEL)

IEL:

AA Project No.:

Date Sampled: #1-29-93 Date Received: #1-39-93

Date Reported: 01-31-93

Date Analyzed:	01-30-93	01-30-93	21-30-95	01-30-83	Reporting	
AA I.D. No.:	15308	13309	133 11	13312	Detection	
Client I.D. No.:	\$\$18C	\$ 35PQC	8 33 196-76	\$35P6-7#	Limits	Units
Compounds						
Benzene	45	25	<b>45</b>	45	5	Mg/Kg
Toluene	45	45	25	45	5	Mg/ Kg
Ethylbenzene	45	45	25	45	5	ug Kg
Xylenes	<5	25	34	45	10	rg/ Kg
Gasoline Range Organics			42	<b>4</b> 2	2.	mg/Kg
Date Analyzed			•			
Diesel Range Organics						

MATCHT ANALTOID REQUE

Chara: T.T. M.S. Project No.: 41875

Project Name: CHET HOLLFIELD FEDERAL BUILDING

Soumple Matrix: 501L

Method: EPA 8020(8YEX)/8015M(GAS.)/(DIESEL)

AA Project No.:

Date Received: 01-29-93 Date Received: 01-30-93 Date Reported: 01-31-93

Date Analyzed:	01-30-93	01-30-93	01-30-43	81-30-95	Reporting	
AA I.D. No.:	13313	13314	13315	13366	Detection	
Client I.D. No.:	SSSP6-7W	3 3 396-71	SST63	33T6V	Links	Units
Compounds						
Benzene	45	45	45	<b>45</b>	5	149 Kg
Toluene	45	۷5-	25	25	5	14/14
Ethylbenzene	25	25	45	£5	5	48/Kg
Xylenes	210	23	260	210	10	19/119
Gasoline Range Organics	<b>42</b>	42	42	42	2	mg/Kg
Date Analyzed						
Diesel Range Organics						

( . US NU . UU1 F . U4

AL MICHI ANALIGID ALGOLI

Chara: T.T. M.S. Project No.: 11875

Project Name: CHET HOLIFIELD FEDERAL BULLDING

Sample Mairle: SOIL

Method: EPA 8020/BTEX/8015M(GAS.)/(DIESEL)

166:

AA Project Na.:

Data Received: 01-29-93 Data Received: 01-30-93

Date Reported: 01-31-47

Date Analyzed:	01-30-93	01-30-93	01-30-93	01-30-41	Reporting	
AA I.D. No.:	13317	13318	13319	13320	Detection	<b>{</b> ·
Client I.D. No.:	SSTIN	89778	533P3-4N	59593-45	Limits	Units
Compounds						
Benzene	45	11	45	45	5	43/29
Toluene	45	48	45	45	5	141/Kg
Ethylbenzene	45	14	<b>L</b> 5	25	5	145/Kg
Xylenes	<10	91	40	210	10	Mg/Kg
Gasoline Range Organics	42	<b>42</b>			2	sug   Kg
Date Analyzed						
Diesel Range Organics					,	-

Feb 02 93

7:03 No.001 P.05

2. 1.1993 9

Chara: T.T.M.S Project Name: CHET HOLIFIELD FEDRAL BUILDING Project No.: 11875

Sample Matrix: Sail

' FROM' (818) 998-7258

Method: EPA 9018M(DIESEL)

AA Project No.:

Date Sampled: 1/24/93 Date Received: 1/30/93

Date Reported: Units: mg | Kg

. . . . . . . . . .

AA ID No.	Client ID	Date Extracted	Date Analyzed	Results	Reporting Detection Limits	
13308	SSTRC	12/30/93	12/30/93	220	10	
13309	SSSPRC		, r	210	10	
13319	5993-4N			<10	10	
13320	SS\$P3-4S			<10	10	
13321	SS\$ 3 N			610	10	
13322	537 3S			L10	10	
13323	SSTAN			210	10	
13324	SSTAS			410	10	
Vot detected at d					<u> </u>	

TEL:

L.

Feb 02 93

7:03 No.001 P.06

P. 2

FROM (818) 998-7258

2. 1.1993 1: THATOHY ANALYSIS HESUL

AA Project No.:

Cate Samplett. 11-29-93

Date Received: 01-30-93

Date Reported: Mr. 36-43

Project Name: CHET HOLLFIELD FEDERAL BULLDENG

Client: T.T. M.S. Project No.: 11875

Sample Matrix: SOIL

Method: EPA 8020(BTEX)/9015M(GAS.)/(DIESEL)

Date Analyzed:	01-30-95	01-30-93	01-30-13	01-30-2	Reporting	
AA I.D. No.:	13321	13322	8323	13324	Detection	
Client I.D. No.:	SSTSN	33725	SSTYN	5374 S	Limits	Units
Compounds						
Benzene	25	45	45	45	5	119/Kg
Toluene	45	45	45	45	5	14 Kg
Ethylbenzene	45	45	45	45	5	14/14
Xylenes	210	410	210	210	10	19/16
Gasoline Range Organics					,	
Date Analyzed						
Diesel Range Organics						

Jethod: EPA 418.1 (TRPH)

AA Project No.:
Date Simpled: 1/39/93
Date Received: 1/30/93
Date Analyzed: 2/8/93

Date Reported: Units: mg / Kg

. AA 10 No.	Client ID	Results	Reporting Detaction Limits
133/0	557.5C ×	10	.5-
* *** * * * * * * * * * * * * * * * * *			
<i>•</i>	-		
		i	······································
	4		
	:		
		1	

Environmental Health Division, Hazardous Materials Management Section
Mailing Address: P.O. Box 355, Santa Ana, CA 92702
Office: 2009 F. Edicate Telephone: (714) 667-3700

HAZARDOUS WASTE & UNDERGROUND STOR	A set
FACILITY: (het Holified Blog.	EPA #: UST PERMIT NO: PERMIT:
STREET: 24000 Avila Kol.	MAP COORDINATES:
STREET: 24000 Avila Kol.  SITY: 150 1 Laguna Niguel, CAZIP: 92	7677 DISTRICT: 40/
NEAREST CROSS STREET:	TSD FACILITY?
NEW DBA? NEW BUSINESS? NEW ADDRESS?	NEW OWNER? PUBLIC AGENCY?
NEW INFO:	
	-
HW INSPECTION TYPE: NO OF UST ON S	ITE: / UST INSPECTION TYPE: #93
NUMBER OF EMPLOYEES: # TANKS TO BIL	UST COMPLIANCE CODE: 97
	LAST DATE UST INSPECTED:
W EXEMPT CODE:	UST EXEMPT CODE: /
	UST STATUS CODE: /
W STATUS CODE:	
BUSINESS OWNER:	PHONE: ()
	PHONE: ()
	PHONE: ()
W BILLING (NAME & MAILING ADDRESS):	UST BILLING (NAME & MAILING ADDRESS):
HONE: ()	PHONE: ()
PROPERTY OWNER (NAME & MAILING ADDRESS):	TANK OWNER (NAME & MAILING ADDRESS):
DUONIC: /	DOLLAR . ( )
PHONE: () ENTERED	FRUNCE: ()
EMERGENCY CONTACTS FEB 1 6 199	
DAY:	PHONE: ()
NIGHT:	PHONE: ()
ACTUE ICO.	
INSPECTOR #: 233 NAME: Brenda	6 Dipole 2,39
INSPECTOR #: NAME: NAME:	JO PUEJA DATE: 2/2/1
	PAGE 1 OF 2

Grans G sty Health Care Agency

Manifold Address: P.O. Bu to Sant the LA 92.00

Office: 2009 E. Edinger: Santa An. CA 92705

HAZARDOUS WASTE & UNDERGROUND STORAGE TANK INSTRUCTION REPORT

ACTILE NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. Edinger: Santa An. CA 92705

ARCANO NO: 2007 E. CA

HA BIRING CODE:

HAS INDECTORS:

TANK OFERATORS:

CONTACT:

THE DILLIAG.

MAINTERS OF A PARTIE OF THE LINE OF THE

ENTERENCY CONTROLLS

FOR FOREST

FOR FORES

ACTIVE ICE;

HEY EXEMBI CADE

.AST BATE HW TMSMLCJUTA

MUMBER OF SPREAMEN

IN THREE CLIPN INCH

SPINE L

1005

ER SECTION

THE NUMBER OF THE PASSECT DE

ATTOMIC AND COMBINED TOP LAKE

STATE COMMENTANCE CODE:

PAGE 4 0

Oran ( nty Health Care Agency UNDERGROUND STORAGE TANK INSPECTION REPORT  DBA: Chet Holitie & Blog.
ADDRESS: 24000 Avila Rd.
: Laguna Niquel, CA 971077
FILE NO: ACCOUNT NO: EPA #:
VIOLATION DESCRIPTIONS
FACILITY
105 OPERATING UNDERGROUND STORAGE TANKS (UST) WITHOUT A PERMIT  115 FAILURE TO REPORT THE CHANGE IN OWNERSHIP WITHIN 30 DAYS  135 FAILURE TO ENTER INTO A WRITTEN CONTRACT BETWEEN OWNERS AND OPERATORS  140 METERS NOT INSPECTED BY THE COUNTY DEPARTMENT OF WEIGHTS AND MEASURES OR A DEVICE REPAIRMAN  145 FAILURE TO MONITOR THE TANKS USING THE METHOD SPECIFIED ON THE PERMIT  150 FAILURE TO MAINTAIN WRITTEN RECORDS OF ALL MONITORING, EQUIPMENT CALIBRATION, AND MAINTENANCE ON SITE  170 FAILURE TO CORRECT PREVIOUS VIOLATIONS WITHIN 30 DAYS  190 FAILURE TO SUBMIT INVENTORY RECONCILIATION QUARTERLY/ANNUAL REPORT  196 FAILURE TO SUBMIT A "PERMIT TO OPERATE" APPLICATION FOR THE USTS AT THE SITE  197 FAILURE TO IMPLEMENT/SELECT/DEVELOP AN APPROVED MONITORING SYSTEM/PLAN  198 FAILURE TO OBTAIN/SHOW EVIDENCE OF FINANCIAL RESPONSIBILITY  291 FAILURE TO SUBMIT A DIAGRAM SHOWING THE LOCATION OF UST
TANK
126 FAILURE TO REPORT THE CHANGES IN THE USAGE OF UST MITHIN 30 DAYS  125 FAILURE TO REPORT AN UNAUTHORIZED RELEASE  130 FAILURE TO DEVELOP A RESPONSE PLAN TO REMOVE THE UNAUTHORIZED RELEASE FROM THE SECONDARY CONTAINER  155 FAILURE TO MONITORING DEVICES/GRUPMENT/TANK LEVEL MONITORS/LINE LEAK DETECTORS INOPERABLE  180 FAILURE TO ANNUALLY TEST AND/OR SUBMIT PROOF OF INSTALLATION OF PIPELINE LEAK DETECTORS  185 FAILURE TO SUBMIT TANK INTEGRITY TEST RESULTS WITHIN 30 DAYS OF TEST COMPLETION  195 FAILURE TO FOLLOW PROCEDURES WHEN INVENTORY RECONCILIATION/TANK GAUSING EXCEEDS ALLOWABLE VARIATIONS  270 FAILURE TO REPORT CHANGES IN MONITORING ALTERNATIVE PROCEDURES WITHIN 30 DAYS  275 FAILURE TO PROPERLY CLOSE USTS  286 FAILURE TO PROPERLY REPAIR USTS  286 FAILURE TO PROPERLY REPAIR USTS  287 PRESSURIZED LINE LEAK DETECTORS ARE NOT DESIGNED TO RESIST UNAUTHORIZED TAMPERING  288 UNDERGROUND TANK (S) NOT SECURED TO PREVENT UNAUTHORIZED INPUTS OR WITHDRAMLS  290 OTHER
- Received lab results for the samples taken during
- Received lab results for the samples taken during the tank removal project at this site.  - Sample results show some levels of TPH & BTXE above the transfer levels of TPH-10ppm & BTXE0.3ppm.  - Transfer to cleanup group
DECLARE THAT I HAVE EXAMINED AND RECEIVED A COPY OF THIS Z PAGE INSPECTION REPORT.
GIGNATURE: DATE: Z/3 PB

### Orange County Health Care Agency



Environmental Health Division, Hazardous Materials Management Section Mailing Address: P.O. Box 355, Santa Ana, CA 92702

Way Office: 2009 E. Edinger, Santa Ana, CA 92705

Telephone: (714) 667-3700

HAZARDOUS WASTE & UNDERGROUND STORAGE TANK INSPECTION REPORT

FILE NO: 00/13/ ACCOUNT NO: 10.  FACILITY: Chet Holifield Blog.  STREET: 24000 Avila Rd  CITY: [58] Laguna Niguel, CA ZIP:	PERMIT:
NEAREST CROSS STREET: NEW ADDRESS? NEW ADDRESS? NEW ADDRESS? NEW INFO:	
HW INSPECTION TYPE: NO OF UST ON NUMBER OF EMPLOYEES: # TANKS TO BI LAST DATE HW INSPECTED: HW EXEMPT CODE: HW STATUS CODE: BUSINESS OWNER: TANK OPERATOR: CONTACT: HW BILLING (NAME & MAILING ADDRESS):	LAST DATE UST INSPECTED:  UST EXEMPT CODE: /  UST STATUS CODE: /  PHONE: ()  PHONE: ()  PHONE: ()
PHONE: () PROPERTY OWNER (NAME & MAILING ADDRESS):	PHONE: ()  TANK OWNER (NAME & MAILING ADDRESS):
PHONE: ()  EMERGENCY CONTACTS	PHONE: ()
PAY: ENTERED NIGHT: APR 2 1 1993 ACTIVE ICR: 233 NAME: Brenda	PHONE: (_) PHONE: (_)  Jo Puepke DATE: 4/5/93

287 PRESSERIZED LINE LEAK DETECTORS ARE NOT DESIGNED TO PRESIDE TO TRESIST UNAUTHORIZED TAMPERING

288 UNDERGROUND TANK (S) NOT SECURED TO PREVENT UNAUTHORIZED INPUTS OR NITHDRAWLS

290 OTHER

- Received Closure report for the removal of 1-500 gallon

diese tank this past Oecember. Information includes

tank destruction into cinseate manifest lab results a disposal

manifests for the contaminated spoils pile. Discussed case with

Lim Strozier-cleanup and he agreed that this case could be closed.


Lase closed this oute.

I DECLARE THAT I HAVE EXAMINED AND RECEIVED A COPY OF THIS Zafz PAGE INSPECTION REPORT.

PRINT NAME & TITLE: Copy mailed to Cheef Holifield

SIGNATURE:

DATE: 415.93



Puepke

TOM URAM DIRECTOR

L. REX EHLING, M.D. HEALTH OFFICER

ENVIRONMENTAL HEALTH DIVISION ROBERT E. MERRYMAN, R. S. MPH DEPUTY DIRECTOR

> MAILING ADDRESS: P.O. BOX 355 SANTA ANA, CA 92702

FACILITY MODIFICATION

APPLICATION

(INSTALLATION/REMOVAL/REPAIR)

(COMPLETE PAGES 1 & 2)


## HEALTH CARE AGENCY PUBLIC HEALTH SERVICES


ENVIRONMENTAL HEALTH DIVISION 2009 E. EDINGER AVENUE SANTA ANA, CALIFORNIA 92705 (714) 667-3700

400 FT FTT DAGES 4 8 61	DATE:
FACILITY INFORMATION	TYPE OF CONSTRUCTION
NAME: CHET HOLIFIELD FEDERIAL BUILDING	INDICATE NO. OF TANK(S) BEING REMOVED/RE-
	PAIRED/INSTALLED BELOW:
STREET ADDRESS: 24000 AVIL4 ROAD	(COMPLETE PAGE 2 - INDICATING THE TANKS TO
CITY: LAGUNA NIGUEL (A 92656	BE INSTALLED/REMOVED, OR AFFECTED BY THE REPAIR)
TOTAL NUMBER OF TANKS (AFTER INSTALLATION/REMOVAL)  AT THIS LOCATION:	
TYPE OF BUSINESS:	INSTALLATION(S)
GASOLINE STATION FARM	REPAIR(S)/RELINE(S) TO USTs
GOVERNMENT OTHER	1 CLOSURE(S)/REMOVAL(S)
TANK OWNER	SYSTEM MODIFICATION (E.G., REPIPE, REPAIR TO
NAME (CORP., INDIVIDUAL, PUBLIC AGENCY):	PIPING)
UNITED STATES OF AMERICA	OTHER (SPECIFY)
STREET ADDRESS: 24006 AUILA ROAD 5.4100	24 HOUR ENERGENCY CONTACT PERSON
CITY: LAGUNA NIGUEL CA 92656	DAYS: EDGAR M GRAY JR 714-643-4863
STATE: CA ZIP: 92656	NAME TELEPHONE
TELEPHONE NO.: 714-643-4863	NIGHTS: SAME TELEPHONE
BILLING ADDRESS INFORMATION	
BILL TO NAME: SAME AS ABOVE	APPLICANT
BILL TO ADDRESS:	NAME: CHARLES IN BENTLE!
CITY:	SIGNATURE: Charle Us Benetter
STATE: ZIP:	COMPANY NAME: UST COMPLIANCE GROUP
TELELPHONE NO.:	TELEPHONE NO.: 2(3-773-6437
	FACILITY OPERATOR (CONTACT PERSON)
	NAME: EDGAR IN GRAY JR.
	BUSINESS TELEPHONE NO.: 714-643-4863
SUBMITTAL OF (4) SETS OF PLANS TO THIS DIVISION	TEM MODIFICATIONS OF UNDERGROUND STORAGE TANKS REQUIRE THE INTERPORT OF THE INITIATION OF ANY REPORTS REQUIRED MUST ACCOMPANY THIS FORM AT THE TIME OF
PLAN CHECK NO.: 92-308 FEES PAID: PLAN APPROVAL DATE: 12-21-92 BY: BJP NUMBER OF TANKS TO RECEIVE A SURCHARGE BILL:	NUMBER OF TANKS TO BE ADDED TO BILLING:
REV:12/05/91 HSU# 118099 Pag	ge 1 of 2 FORM #86

PROVIDE THE INFORMATION BELOW FOR ALL TANKS AND PIPING SYSTEMS TO BE INSTALLED, REMOVED OR REPAIRED. ALSO INDICATE THE UPGRADE/CHANGES TO BE MADE TO EACH TANK SYSTEM.

TANK 1.D	,		£1	<b>#</b> 2	#3	#4
MATERI AL	CUR	RENTLY	DIESEL			
S OR WASTE STO	PRO	POSED				
P 1	l l	VIOUSLY	DIESEL			<del> </del>
_	. I.E., UN	LEADED				· • · · · ·
TYPE (TANK.	SUMP, OTHER	es)	TANK			
DOUBLE WALL	SINGLE WALL	•	SINGLE			
UL NUMBER			ulk			
YEAR INSTALL	ED		UK			
YAULTED/NOT	YAULTED		NOT VAULTED	·		
MANUFAC	TURER		ulk			
CAPACIT	Y (GALLON)		500			
CONSTRU	CTION MATER	RIAL.	STEEL			
	SS (UNITS)		414			
INTERIO	RLINING		NONE			
S MANUFAC	TURER		N/A			
MANUFACTURER CAPACITY (GALLON)					-	
RIAI	CTION MATER	RIAL.				
THICKNE	SS (UNITS)					
CORROSION PR	OTECTION		uK			
TYPE OF LEAK		FOR USTs				· · ·
(LIQUID PROE	-		UK			
MANUFACTURE LOCATION	R OF LEAK D	ETECTOR	NONE			
(UNDER/ABOVE			UNDER			
P SUCTION/PRES			SUCTION			
GOTTITONA	CONSTRUCT	ON	30000			
PRIMARY	MATERIAL.		STEEL			
	MANUFACTU	RER				
1	CONSTRUCT	ON				<u> </u>
SECONDARY	CONDARY MATERIAL		NOWE			
TYPE OF LEAR	MANUFACTU					,
(PRESSURE L			NONE	.		
MANUFACTURE			NONE			<del></del>
ERFILL PROTECT			NONE			<del> </del>
PILL CONTAINMEN	······································		NONE			





#### UNDERGROUND TANK REMOVAL FOR

Chet Holifield Building - 24000 A Facility Name Address	Avila Rd. [N
Facility Name Address  PC # 91-308 TI # LUST #  Inspector: Brenda Jo Pueplle Date: 12-23-  La Paz	921 CB
Inspector: Brenda Jo Puesle Date: 12-23.	92 Time: 3:00 p.m
La Paz Cross Street	(714) 643-4663
Cross Street	Site Telephone Number
Owner Blog 74000 Avila Address	
Ed Gray Contact Person	Telephone Number
Operator (if different than owner)	
	Telephone Number
Consultant or Contractor Company   Contact Name	Telephone Number
Tank #1: 500 Steel Ciesel Tank #4: Size Const. Mat. Mat. Stored Size	
Size Const. Mat. Stored Size	Const. Mat. Mat. Stored
Tank #2: Tank #5: Size Const. Mat. Stored Size	Const. Mat. Mat. Stored
Tank #3: Tank #6: Size Const. Mat. Stored Size	
Depth to Groundwater: 7	
Proposition 65 Required? Prop. 65 Form Submit	ted on:
Fire Dept. Personnel On-site: None	
Ambient Air Readings on Field Instrument: Dpm	
Other Information:	

Rev: 11/04/91

Factity Name Road Bklg - 24000 Address	•,
PC # 92-308 TI # LUST # IR #	•
Inspector: Brenda Pueple Date: 12-22-92 Time: 3.15pm	
Field Activity: Witness removal Of 1-500 gallon chese I fan	K
No fire inspector from the county was on site at that	
time. I questioned Larry Harlan as to why this was. He	
State of that the individual who he talked to at OCF, resad that is	-
was not nece fravy to have them engite. Tank had small peasure	$\sqrt{}$
holes near bottomed bottom side. Contamination of soil	
was evident under fank & toward NW side. Visual contamio	rate
removed and sample 553.11 taken 3ft. Below tank. Sample	2
SS-1 is representative of contaminated spoils sile. Samo	16
SS-1 is representative of contaminated spoils sile. Samp (SSZ 10) sidewall is what appears to be dark organic material.	
255-1) - 08 ppin	
Pretiniment 2360-1PH +08 ppin	
SS3-11  ND TOHORE  SS4-11  ND-TPH & BTXE  Chiefly  AD-TPH & BTXE  Chiefly  AD-TPH & BTXE	apri
<b>3</b> 8	12/6

Rev: 11/04/91 Dave-home MI-480 Page 2 of 2

FORM #1

TO



#### PRELIMINARY DATA CERTIFIED ENGINEERING PROJECT # A10598 24000 AVILA ROAD

922 6254

#### TEG PROJECT #921223CK

TPH (DOHS Mod. EPA 8015) & BTEX (EPA Method 8020) ANALYSES OF SOILS (MG/KG)

SAMPLÉ NUMBER	DATE ANALYZED	TPH-DIESEL (mg/kg)	BENZENE (mg/kg)	TOLUENE (mg/kg)	EBENZ (mg/kg)	XYLENES (mg/kg)
METHOD BLANK	12/23/92	ND	ND	ND	ND	ND
SS-1 SS-2 @ 10' SS-3 @ 11' SS-3 @ 11' DUP SS-4 @ 11' SS-5	12/23/92 12/23/92 12/23/92 12/23/92 12/23/92 12/23/92	2360 ND ND ND 25 28	ND ND ND ND ND	O.09 ND ND ND ND ND	0.36 ND ND ND ND ND	0.12 ND ND ND ND
DETECTION LIMITS	3	10	0.05	0.05	0.05	0.05

ND INDICATES NOT DETECTED AT LISTED BETECTION LIMITS

SSI: is "Drity" soil pile. S-Z-10: 15 N. East sidewall of excavation at 10 (2- below total depth of tank) 55-3-11: is middle of excavation directly below (3') dress! storage tank. Taken at a depth of 11. SS.4-11: is S. Wall of excavation at a depth of 11: ( The west side of excavation is fronted w/ a

10' retaining wall). SS-S: "clean" soil pile.

site was really "over excavated"

1 1/23 Orange Sounty Health Care Agency

Environmental Health Division, Hazardous Materials Management Section
Mailing Address: P.O. Box 355, Santa Ana, CA 92702
Office: 2009 E. Edinger, Santa Ana, CA 92705
Telephone: (714) 667-3700

HAZARDOUS WASTE & UNDERGROUND STORAGE TANK INSPECTION REPORT ACCOUNT NO: FACILITY: PERMIT: MAP COORDINATES: CITY: 1503 Laguna Niquel CA ZIP: 97477 DISTRICT: TSD FACILITY? NO NEAREST CROSS STREET: __ NEW DBA? ___ NEW BUSINESS? ___ NEW ADDRESS? ___ NEW OWNER? ___ PUBLIC AGENCY? NEW INFO: HW INSPECTION TYPE: NO OF UST ON SITE: 8-7 UST INSPECTION TYPE: NUMBER OF EMPLOYEES: # TANKS TO BILL : 7 UST COMPLIANCE CODE: LAST DATE UST INSPECTED: ____ LAST DATE HW INSPECTED: HW EXEMPT CODE: UST EXEMPT CODE: HW STATUS CODE: _ UST STATUS CODE: PHONE: (___) BUSINESS OWNER: PHONE: (___) TANK OPERATOR: CONTACT: PHONE: (___) HW BILLING (NAME & MAILING ADDRESS): UST BILLING (NAME & MAILING ADDRESS): PHONE: (__) PHONE: (___) TANK OWNER (NAME & MAILING ADDRESS): PROPERTY OWNER (NAME & MAILING ADDRESS): PHONE: (____) PHONE: (____) ____ EMERGENCY CONTACTS PHONE: (___) PHONE: (___) ___ ACTIVE ICR:

Oran bunty Health Care Agency
UNDERGROUND STORAGE TANK INSPECTION REPORT
, DBA: Chet Holitield Bldg.
ADDRESS: ZYCCO Avila Rd.
: Laguna Niguel, CA 92617
FILE NO: ACCOUNT NO: EPA #:
VIOLATION DESCRIPTIONS .
FACILITY
105 OPERATING UNDERGROUND STORAGE TANKS (UST) WITHOUT A PERMIT
115 FAILURE TO REPORT THE CHANGE IN OWNERSHIP WITHIN 30 DAYS 135 FAILURE TO ENTER INTO A WRITTEN CONTRACT BETWEEN OWNERS AND OPERATORS
140 METERS NOT INSPECTED BY THE COUNTY DEPARTMENT OF WEIGHTS AND MEASURES OR A DEVICE REPAIRMAN
145 FAILURE TO MONITOR THE TANKS USING THE METHOD SPECIFIED ON THE PERMIT
150 FAILURE TO MAINTAIN WRITTEN RECORDS OF ALL MONITORING, EQUIPMENT CALIBRATION, AND MAINTENANCE ON SITE
176 FAILURE TO CORRECT PREVIOUS VIOLATIONS WITHIN 36 DAYS
190 FAILURE TO SUBMIT INVENTORY RECONCILIATION QUARTERLY/ANNUAL REPORT 196 FAILURE TO SUBMIT A "PERMIT TO OPERATE" APPLICATION FOR THE USTS AT THE SITE
176 FAILURE TO IMPLEMENT/SELECT/DEVELOP AN APPROVED MONITORING SYSTEM/PLAN
198 FAILURE TO OBTAIN/SHOW EVIDENCE OF FINANCIAL RESPONSIBILITY
291 FAILURE TO SUBMIT A DIAGRAM SHOWING THE LOCATION OF UST
TANK
120 FAILURE TO REPORT THE CHANGES IN THE USAGE OF UST WITHIN 30 DAYS
125 FAILURE TO REPORT AN UNAUTHORIZED RELEASE 136 FAILURE TO DEVELOP A RESPONSE PLAN TO REMOVE THE UNAUTHORIZED RELEASE FROM THE SECONDARY CONTAINER
155 FAILURE TO MONITOR VISUALLY AT REQUIRED FREQUENCY
165 CONTINUOUS MONITORING DEVICES/EQUIPMENT/TANK LEVEL MONITORS/LINE LEAK DETECTORS INOPERABLE
180 FAILURE TO ANNUALLY TEST AND/OR SUBMIT PROOF OF INSTALLATION OF PIPELINE LEAK DETECTORS
185 FAILURE TO SUBMIT TANK INTEGRITY TEST RESULTS WITHIN 30 DAYS OF TEST COMPLETION
195 FAILURE TO FOLLOW PROCEDURES WHEN INVENTORY RECONCILIATION/TANK GAUGING EXCEEDS ALLOWABLE VARIATIONS
276 FAILURE TO REPORT CHANGES IN MONITORING ALTERNATIVE PROCEDURES WITHIN 36 DAYS
275 FAILURE TO PROPERLY CLOSE USTS 286 FAILURE TO PROPERLY REPAIR USTS
286 FAILURE TO PERFORM TIGHTNESS/INTEGRITY TEST ON TANKS/PIPELINES
287 PRESSURIZED LINE LEAK DETECTORS ARE NOT DESIGNED TO RESIST UNAUTHORIZED TAMPERING
288 UNDERGROUND TANK (S) NOT SECURED TO PREVENT UNAUTHORIZED INPUTS OR WITHDRAWLS
29Ø OTHER
- Without and comment of 1 and the direct to the Comment was
- Witnessed removal of 1-300 gallen diesel tank (previously reported
as 500 gallons). Pea-sized holes observed near bottomot
tank and contamination observed below tank. Contamine
removed to visually clean a samples taken of dirty spoils
Clean spoils of excavation. Mobile laborisite, Contaminated son
I DECLARE THAT I HAVE EXAMINED AND RECEIVED A COPY OF THIS 3 PAGE INSPECTION REPORT.
PRINT NAME & TITLE: Copy sent to Chet Holitield Blog. Edgar Gray
SIGNATURE: DATE: 12,7392

```
r March 21 Car Land
                                                           "可是我们的我们的,我们就是我们的,我们就是一个有一个人,我们就是我们的一个人的。"
                                                           THE REST OF THE YEAR MEET TO A TO BE SEEN AND A STANDARD OF THE PARTY 
                                                               BOSET A SCHOOL TENNESSEE THE ALLESS OF MAN LIFE DESIGNATION
                                                             THE RESERVE OF THE PARTY OF THE
                                                                      COLUMN THE RESERVE SERVER STORY OF THE STORY WITH STORY
                                                                    AR STORE COTTON PETERAL SERVICE SERVICE STORE OF SERVICE SANDERS OF SERVICE SERVICE SERVICES.
                                                      THE DWINE AS MOST OF AS THE MANNEY OF THE PARTY OF THE PARTY OF THE PARTY.
                                                                    ST HELDER TO WALLOW ASSESSED TO PETERSON.
                                                                        CHIEF TO LETTER OF THE PARTY OF
                                                                      TARREST TO SERVER AND AND AND THE STATE OF THE SERVER OF T
                                                      THE RESTRICT OF THE PROPERTY O
                                                             THE RESIDENCE TO THE RESIDENCE OF THE PARTY OF THE PARTY
                                                                 是 BETTER A TENNE TO THE A TENNE TO THE BETTER BY AND A TENNE
                                                 THE ASSESSED LIVER THE NEW YORK IN A STATE OF THE
                                                      A MALLON MARTINE OF A SECURITY AND A SECURITY OF THE PARTY.
  THE BUILT IS A CONTROL OF A DAY BY AND A CONTROL OF THE PARTY OF THE PARTY OF
THE RELIGIOUS SPECIAL SHOP TO THE PROPERTY OF THE PROPERTY OF THE PERSON OF THE PERSON
                                             THE LAND SHELL WITH THE PART OF THE PROPERTY OF THE PARTY OF THE PARTY
                                                 THE THE PROPERTY OF THE PARTY O
                               THE RESIDENCE OF THE PARTY OF T
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                TED IN FROM JOE 1904 INC. ED.
                                                                                                                                                                                                                                                                                                                                                                                                                                               CHADELS
```

ANAL HERRELL CALL HENDE

1 1 1 14 14 3 as			alth Care Agen		
	П	NDERGROUND STORE	AGE TANK INSPE	CITON REPORT	
('h)	nd 1	LICON KW	5		
DBA:	VIT	WITTER	1 .	o designative address in the delivery law is the purpose annual medical and the state parameters and release of	The state of the s
ADDRESS: 2400	OA	vila Rd.		a personal translation beneficially and the analysis and the analysis of the a	
100		Niquel, Cti	92677		
: cagi	will	rugues, Cri	12411		and planting parts. In . I and makeline one as his continue the first continue the second district the second
		/			
FILE NO:		ACCOUNT NO		EPA #:	
FILE NO.			M	CFH #:	
		Removal	AU		
!HCA TANK ID#	! CODE	! TANK # 007	!CODE!TANK #	!CODE!T	ANK #
!FACILITY TANK ID	!	1	!!!	!!!	!
!MATERIAL STORED	!	!	!!!	!!!	t
!Currently	1	99999	1 1	1 1	1
!Proposed	!		!!!	!!!	!
!Previously	1	!	1 1	1 1	
!Waste or Product	1/	!	!!!	!!	!
!FUEL TYPE	! 4	! diesel	!!!	!!!	!
!Trade Secret	:8			!!	
!EXEMPT TYPE	10	1		!!!	!
177	1 2				1
!Double/Single Wall				!!!	
!Compartment No.	!	1969 ?	1 1	1 1	
!Year Installed !Vault/Not Vaulted	12	1 / 141 .	1 1		1
!Primary Wall:	1	1	1 1	1 1	
!Manufacturer	99		1 1	1 1	i
!Capacity / Gallons	1	500	1 1	1 1	1
!Construct Material	1/	steel	1 1	1 1	1
!Thickness & Units	199	1	1 1	1 1	1
!Interior Lining	196	! ,	1 1	1 !	
!Secondary Wall:	! 00	!	! !	!!!	!
!Manufacturer	191	1	ŧ .	!!!	!
!Capacity / Gallons	:97	!	t t	!!!	Į.
!Construct Material	191	!	!	!!!	1
!Thickness & Units	19/	1	!!!	1 1	!
!Corrosion Protectn	196		!!!	!!!	
!Leak Detect: Type	:96		1 1		
!Manufacturer	19/	4	! !	!!!	
!PIPING: Location !Dispensr/Tank Fill	: 1	1			
!Double/Single Wall	12	1	i		:
!Primary Wall:	1	1	1 1	1 1	
!Construct Material	1	i	1 1	1 1	· i
!Manufacturer	99	1	1 1	ļ I	1
!Secondary Wall:	1	1	1 1	1 1	1
!Construct Material	: 97		1 1		i
!Manufacturer	137	!	! !	!!!	!
!Leak Detect: Type	: 94	!	!!!	!!!	1
!Manufacturer	197	!	1 1	!!!	_!
!TYPE OF OVERFILL	! 0.	1	!!!	!!!	Į.
PROTECTION	196		! !	!!!	!
!SPILL		1/-	!!!	!!!	!
!CONTAINMENT	!	NO	!!!	!!!	1
!MONITORING	25	Paramond Las	6/		!
!METHOD		Removed, legal			!

INSPECTION DATE: 12 23,92

FACILITY TANK ID MATERIAL STORED Tede Seers Late a len 2\ai Uil ALM THOUS ENGINE helinia t say TIEN YARN YO Tagglest Land Tar rates James and glebe Parkets Secondary Walls Letter ted doubletted BILL S MEMTS 24 7 nd sale perganna Leak Detect: Type and action and PIPING: Location Lispener Tank Fill Tisk elevel a Compo Primary Wall! secondary Malls Leak Detect! (vpe Darw Tank melt TYPE OF GUERRILL PROTECTION THE MALL OF MORESTORING MELIOD AST THE TEST


TOM URAM DIRECTOR

L. REX EHLING, M.D. HEALTH OFFICER

ENVIRONMENTAL HEALTH DIVISION ROBERT E. MERRYMAN, REHS MPH

MAILING ADDRESS: P.O. BOX 355 SANTA ANA, CA 92702

**DEPUTY DIRECTOR** 



CENTENNIAL

FACILITY MODIFICATION

(INSTALLATION/REMOVAL/REPAIR)

APPLICATION

(COMPLETE PAGES 1 & 2)

ENTERED JAN 3 1 1990

#### **HEALTH CARE AGENCY PUBLIC HEALTH SERVICES**

**ENVIRONMENTAL HEALTH DIVISION** 2009 E. EDINGER AVENUE SANTA ANA, CALIFORNIA 92705 (714) 667-3700

	/	1	/
DATE:		25/	40
		L	

FACILITY INFORMATION	TYPE OF CONSTRUCTION
NAME: CHET HOLLIFIELD FEDERAL BLD	
STREET ADDRESS: 24000 AVILA ROAP	INSTALLATION(S) (COMPLETE PAGE 2)
CITY: LAGUNA NIGUEL, CA 92677	
TOTAL NUMBER OF TANKS -LAFTER -INSTALLATION/REMOVAL)	CLOSURE(S)/REMOVAL(S)
AT THIS LOCATION: 8	SYSTEM MODIFICATION (E.G., REPIPE)
TYPE OF BUSINESS:	OTHER (SPECIFY) F.M.A. (8 THNKS)
GASOLINE STATION FARM	24 HOUR ENERGENCY CONTACT PERSON
GOVERNMENT (U.S.) OTHER	DAYS: MARK GRIPPI 714-643-4260
TANK OWNER	THE TOTAL
NAME (CORP., INDIVIDUAL, PUBLIC AGENCY):	NIGHTS: MARK GRIPPI 714-361-2030
GENERAL SERVICES ADMINISTRATION	NAME TELEPHONE
STREET ADDRESS: 24000 AVILA ROAD	APPLICANT
CITY: LAGUNA NIGUEL	NAME:
STATE: CA ZIP: 92677	PLEASE PRINT
TELEPHONE NO .: 714 - 643 - 4260	SIGNATURE:
BILLING ADDRESS INFORMATION	COMPANY NAME:
BILL TO NAME: (SAME AS TANK OWNER)	TELEPHONE NO.:
BILL TO ADDRESS:	FACILITY OPERATOR (CONTACT PERSON)
CITY:	NAME: MATRK GRIPPI, CHAN. TUCKER
STATE: ZIP:	BUSINESS TELEPHONE NO .: 714-643-4260
TELELPHONE NO.:	
	TEM MODIFICATIONS OF UNDERGROUND STORAGE TANKS REQUIRE THE N. THESE PLANS MUST BE APPROVED PRIOR TO THE INITIATION OF ANY
OFFIC	E USE ONLY
ACILITY PERMIT NO.: 10237 PLAN APPROVAL DATE	BY: ALLEN NO.: 222
LAN CHECK NO.: FEES:	
INSER OF TANKS TO BE ADDED TO BUILDING.	NUMBER OF TANKS TO RECEIVE A SURCHARGE BILL:
The state of the s	DUT DIA ALL L
	uso closes out PLAN CHECK#
88-PC-349.	

	= "N			HEW	AT3-0/	E	auripi	99	M 1
		HKHOWH	10237 NK	INFORM.	ATIONA	A Lant)	J.	aup,	pper .
		TANK I.D.	NOON 1 P	MAL #XOOLST	#2 002	303#3		5005	mb
M _	1		CURRENTLY	1993-1	1993.Fo	1997-F0	2138 W	2138.W	2070.W
<b>バーのかいひ</b>	CA	OR	PROPOSED						
Y E	WAS	TE I.D.	PREVIOUSLY				GAS 1203	GAS 1203	
Š	FUEL	TYPE (IF TRA	DE SECRET,	DISE 4	PIESE 4	4	GAS 1 UNL	GAS 2	WASTE 5
F	YPE TA	NK SUMP. OT	HERS)	TANK-					>
×	OUBLE W	ALL/SINGLE W	ALL :	DOUBLE	SINGLE-				>_
c <u> </u>	L NUMBE	:R		UHENOUN 99					2
, YI	EAR INS	TALLED		1989	1969 -				>_
V	AULTED/	VAULTED		NOT -					2
·   p	MANUF	ACTURER		0/0 1	UNKNOWS 99-				>
R	CAPAC	ITY (GALLON)		4000	10000	10,000	10,000	10,000	500
R	CONST	RUCTION MATE	RIAL	F/G 3	51772 1	(	1		
	THICK	NESS (UNITS)		3/8 "	1/8"	18"	99-		<del>-&gt;</del>
<u> </u>	INTER	HOR LINING		99 -	0.7	0.0			>
N SE	MANUF	ACTURER		0/C 1	97	97-			>
DEOCH	CAPAC	ITY (GALLON)		4,000	97	97-			3
A	CONST	RUCTION MATE	RIAL	FG 3	97	97 -			>
Y	THICK	NESS (UNITS)		3/8"	97	97-			>
		N PROTECTION	?	FG 5 OC LiquiD:5	16	16	96	96	16
	APOR, E			HYDROSTANC?		10	10	(6)	5
		URER OF LEAK		1	97 -				
۳.	CATION	GROUND)	E	unlosse -					2
	STIPH!	PRESSURE UNKNOWN		SUCTION	sucrow!	1			GRAVIT
PE	RIMARY	CONSTRUCT I O	N	BLACK 1	steal	1 -			2
•		MANUFACTURE	R	V055" 99	UNKHOWN 99	99 -			>
SEC	CONDARY	CONSTRUCTION MATERIAL	CONSTRUCTION MATERIAL		97	97_			<u>A</u>
N		MANUFACTURE	R	A. O. SMITH 23	97	97			$\geq$
<b>₹</b>	PE OF	LEAK DETECTION	ON (LIQUID,	SENISTR 5	97	97-			<b>→</b>
		URER OF LEAK		OC -1	97	97			<b>&gt;</b> _
OVERF	FILL PRO	OTECTION (TY	PE)	O FLOAT VENT	99	99 -			P
SPILL	CONTA	INMENT		POMETO YES	40	160 -			<b>→</b>

II. ATTACH A DIAGRAM (8 1/2" X 11") INCLUDE THE LOCATIONS OF THE UNDERGROUND STORAGE TANK(S). PIPING, AUXILIARY EQUIPMENT, BUILDINGS AND OTHER LANDMARKS.

OFFICE USE ONLY

33 MONITORING SYSTEM/ALTERNATIVE

I.

**TOM URAM** 

L. REX EHLING, M.D. **HEALTH OFFICER** 

**ENVIRONMENTAL HEALTH DIVISION** ROBERT E. MERRYMAN, REHS MPH DEPUTY DIRECTOR

MAILING ADDRESS: P.O. BOX 355

SANTA ANA, CA 92702



## **County of Orange**

#### **HEALTH CARE AGENCY**

#### **PUBLIC HEALTH SERVICES**

ENVIRONMENTAL HEALTH DIVISION

(COMPLETE PAGE 1 8/2) SANTA ANA, C	INGER AVENUE CALIFORNIA 92705 667-3700  DATE:
ACILITY INFORMATION	FACILITY OPERATOR (CONTACT PERSON)
INE:	NAME:
STREET ADDRESS:	BUSINESS TELEPHONE NO.: ( )
CITY:	
TOTAL NUMBER OF TANKS AT THIS LOCATION:	24 HOUR EMERGENCY CONTACT PERSON DAYS:
YPE OF BUSINESS:	NAME TELEPHONE
GASOLINE STATION FARM	NIGHTS:
GOVERNMENT OTHER	NAME TELEPHONE
ANK OWNER	BILLING ADDRESS INFORMATION
NAME (CORP., INDIVIDUAL, PUBLIC AGENCY)	BILL TO (NAME):
	BILL TO (ADDRESS):
STREET ADDRESS:	CITY:
CITY:	STATE: ZIP:
STATE: ZIP:	TELEPHONE NO.: ( )
TELEPHONE NO.: ( )	
	AGE TANK LAW STATES THAT THE OPERATOR OF THE FACILITY SHALL OF MONITORING PERFORMED AT THE FACILITY USING AN APPROVED

MONITORING METHOD. IF THE OPERATOR IS NOT THE OWNER OF THE TANK(S), THE OWNER SHALL PROVIDE A COPY OF THE PERMIT TO THE OPERATOR, ENTER INTO A WRITTEN CONTRACT WITH THE OPERATOR TO MONITOR THE UNDERGROUND STORAGE TANK(S) AS SPECIFIED, AND PROVIDE THE OPERATOR WITH A COPY OF SECTION 25299 OF IT IS THE RESPONSIBILITY OF THE OWNER TO ENSURE THAT THE OPERATOR UNDERSTANDS THE THIS LAW. MONITORING AND REPORTING REQUIREMENTS SET FORTH.

THIS APPLICATION MUST BE SIGNED BY: THE OWNER OF THE UNDERGROUND STORAGE TANK(S); A PRINCIPAL EXECUTIVE OFFICER AT A LEVEL OF VICE-PRESIDENT OR AN AUTHORIZED REPRESENTATIVE; A GENERAL PARTNER PROPRIETOR; OR A PRINCIPAL EXECUTIVE OFFICER, RANKING ELECTED OFFICIAL, OR AUTHORIZED REPRESENTATIVE OF A PUBLIC AGENCY.

(APPLICANT)	OMNER OR	AUTHORIZING PERS	50N:	Please	Print Fu	ıll Name	ти	TLE:						_
(APPLICANT)	OWNER OR	AUTHORIZING SIG	ATURE:			<del> </del>		<u> </u>	_	DATE: _				_
TIF 0000 CT						COMPTITUTE	THE 1/	CCUANCE	~	-	TO	~~~~	DUT	

THE COMPLETION AND SUBMITTAL OF THIS APPLICATION DOES NOT CONSTITUTE THE ISSUANCE OF A PERMIT TO OPERATE BUT IS REQUIRED BY LAW. PLEASE BE ADVISED THAT DETAILED COMPLIANCE AND MONITORING INFORMATION MUST ALSO BE SUBMITTED AND APPROVED BY THIS AGENCY, AND VERIFIED BY ON-SITE INSPECTION, PRIOR TO THE ISSUANCE OF A PERMIT.

I.

ANK INFORMATIO OUT - 2 -

SOUTH SIDE OF MAIN BUNDING

use - Possiby Full OF SAND WATER TES. #4 #3 TANK I.D. CURRENTLY 1993-FO MATER-ALIS CAS NO. PROPOSED OR PREVIOUSLY WASTE I.D. 1993-FO FUEL TYPE ( IF TRADE SECRET. DIESTE DIESEL PLEASE STATE) -TANK TYPE (TANK, SUMP. OTHERS) SINGUE DOUBLE WALL/SINGLE WALL UL NUMBER YEAR INSTALLED 0 No VAULTED/NOT VAULTED MANUFACTURER 500 500 CAPACITY (GALLON) STORE STEEL CONSTRUCTION MATERIAL THICKNESS (UNITS) 99 INTERIOR LINING MANUFACTURER N CAPACITY (GALLON) CONSTRUCTION MATERIAL R THICKNESS (UNITS) CORROSION PROTECTION TYPE OF LEAK DETECTION (LIQUID, VAPOR, ETC.) 97 97 MANUFACTURER OF LEAK DETECTOR LOCATION (UNDER/ABOVE UNDER P SUCTION/PRESSURE GRAVITY/UNKNOWN 1 STEEL CONSTRUCTION PRIMARY P MANUFACTURER I CONSTRUCTION SECONDARY N MANUFACTURER TYPE OF LEAK DETECTION (LIQUID, VAPOR, ETC.) MANUFACTURER OF LEAK DETECTOR 99 OVERFILL PROTECTION (TYPE) NO

ATTACH A DIAGRAM (8 1/2" X 11" ) INCLUDE THE LOCATIONS OF THE UNDERGROUND STORAGE TANK(S). PIPING, AUXILIARY EQUIPMENT, BUILDINGS AND OTHER LANDMARKS.

OFFICE USE ONLY

USED OR MONNORED YEARS KOTIB

MONITORING SYSTEM/ALTERNATIVE REV /04/04/88

SPILL CONTAINMENT

ILLEGALLY . -

9-	· 7	= " N	I/A"		Hen			MISOV		purip	or and or	M
9	à	= " u	NKHOWH	" A N K			ATIOI	EDISO	A \	کمبر ا	art.	soon!
					V-2		(343)	P	cont )	V	VOR	10
			TANK I.D.		#1		#2		3 #3	4	5 #4	6
	اء	٠,	AS NO.	CURRENTLY	1	993-Pt	199	13-E0	1997-FD			2070.W
MATHIX-ALM	M-OKMD		OR	PROPOSED						( - 1	600	
Ā	Đ		TE I.D.	PREVIOUSLY	750				,		GAS 1203	
		FUEL	TYPE (IF TRA	STATE)	N BSEC	4	PIETE	4	4	UNL	GAS 2	oi L 5
	TY	PE TA	SUMP. OT	HERS)	TAN	<u> </u>						<b>&gt;</b>
	DO	UBLE W	VALL/SINGLE W	ALL	Dous		SAN G	LE-				>
c	ՄԼ	NUMBE	R		UHENON		10.0					2
	YE	AR INS	TALLED			1989	1969					>_
.	VA	ULTED/	VAULTED		NOT			0.0				
N	2	MANUF	ACTURER		0/0		WAKINO		10	10	10,000	7
т	RIM		ITY (GALLON)		4000	3	1000	,	10,000	10,000	10,000	500
A	Ŗ		RUCTION MATE	RIAL	F/G 3/8"		1/8"		18"	99-		>
,			ONESS (UNITS)		70_	99 -	7.0		- 8	, ,		-
.			ACTURER		0/0	1	97		97-			<u> </u>
N	DZOOM		ITY (GALLON)		4,000		97		97-			<b>&gt;</b>
E			RUCTION MATE		FG	3	97		97 -			
R	₿	THICK	NESS (UNITS)		3/8"		97		97-			->
	<u> </u>	RROSIC	N PROTECTION		FG	5	99					>_
l	TY VÀ	PE OF POR. E	LEAK DETECTI	ON (LIQUID,	OC LITHY DROSTAY	162 3	14	0	16	96	96	16
			URER OF LEAK		50	1	27					>
	م	CATION	(UNDER/ABOV	E	UNDER							
P			PRESSURE UNKNOWN			1	Suchibi	, l	1	1		GRAVIT
1	GR	AVITY	1		BLACK	1		1	,			2
P	PR	IMARY	CONSTRUCTIO		STEEL	99	stee	99	99 -			>
, }			MANUFACTURE		V055"		UNKNOWN					
5	SEC	ONDARY	CONSTRUCTION MATERIAL	N	FG	3		17	97_			2
"			MANUFACTURE	R	A.O. SMI?			77	97			
G	VA	PE OF POR, E	TC. DETECTI	ON (LIQUID,	>644	. 5	9	7-	97-			->
	MA	NUFACT	URER OF LEAK	DETECTOR	0C	BALL		7	97-			
OVE	ERF	ILL PR	OTECTION (TY	PE)	OFLOAT	VENT	-	ι (	99 -			P
SPI	LL	CONTA	INMENT		Pomeco	当	74	.0	160 -			<b>├</b>

I.

II. ATTACH A DIAGRAM (8 1/2" X 11") INCLUDE THE LOCATIONS OF THE UNDERGROUND STORAGE TANK(S), PIPING, AUXILIARY EQUIPMENT, BUILDINGS AND OTHER LANDMARKS.

OFFICE USE ONLY

MONITORING SYSTEM/ALTERNATIVE 33 7 7 96 96 7

ABANDONED

Ī.

SPILL CONTAINMENT

\$2 8 # 7 #4 TANK I.D. CURRENTLY 1993-FO MATERIALU CAS NO. PROPOSED OR WASTE I.D. PREVIOUSLY 1993-FO DIESEL 4 DIESTE FUEL TYPE (IF TRADE SECRET, PLEASE STATE) TANK TYPE (TANK, SUMP. OTHERS) SINGUE DOUBLE WALL SINGLE WALL UL NUMBER C 70 YEAR INSTALLED Nog VAULTED NOT VAULTED MANUFACTURER 500 500 CAPACITY (GALLON) T STEEL STEEL CONSTRUCTION MATERIAL THICKNESS (UNITS) 1 INTERIOR LINING MANUFACTURER CAPACITY (GALLON) E CONSTRUCTION MATERIAL R THICKNESS (UNITS) **>** CORROSION PROTECTION 96 TYPE OF LEAK DETECTION (LIQUID, VAPOR, ETC.) 97 97 MANUFACTURER OF LEAK DETECTOR LOCATION (UNDER/ABOVE UNDER P SUCTION 1 SUCTION/PRESSURE GRAVITY/UNKNOWN 1 STEEL CONSTRUCTION MATERIAL PRIMARY P MANUFACTURER 1 SECONDARY N MANUFACTURER TYPE OF LEAK DETECTION (LIQUID, VAPOR, ETC.) G MANUFACTURER OF LEAK DETECTOR OVERFILL PROTECTION (TYPE) NO

II. ATTACH A DIAGRAM (8 1/2" X 11") INCLUDE THE LOCATIONS OF THE UNDERGROUND STORAGE TANK(S), PIPING, AUXILIARY EQUIPMENT, BUILDINGS AND OTHER LANDMARKS. Vota 2000

	OFFICE USE ONLY	USED OR HOW	10 TEARS
MONITORING SYSTEM/ALTERNATIVE	171	96	
EV /04/04/88		ABANDONED	

SUBSURFACE INVESTIGATION REPORT

#### REPORT FOR

PRELIMINARY SUBSURFACE INVESTIGATION AT THREE (3) UNDERGROUND STORAGE TANK (UST) AREAS CHET HOLLIFIELD FEDERAL BUILDING LAGUNA NIGUEL, CALIFORNIA

#### Prepared For:


J.C. Chang & Associates, Inc. 357 Van Ness Way, #178
Torrance, CA 90501-1435

#### Prepared By:

Unitech Engineering, Inc.
16331 Gothard Street, Suite D
Huntington Beach, CA 92647
TEL (714) 842-8888
FAX (714) 848-6338

Project No. EI2009 File No. 20992

June 1992




#### TABLE OF CONTENTS

- 1.0 BACKGROUND
- 2.0 SAMPLING LOCATIONS, PROCEDURES, AND PROTOCOL
- 3.0 LABORATORY ANALYSIS
- 4.0 DATA INTERPRETATION
- 5.0 CONCLUSIONS
- 6.0 LIMITATIONS

#### **APPENDICES**

- I. FIELD BORING LOGS
- II. SOIL SAMPLE CHAIN-OF-CUSTODY RECORDS
- III. RESULTS OF LABORATORY ANALYSES



#### 1.0 BACKGROUND

Unitech Engineering, Inc. (Unitech) was retained by J.C. Chang & Associates, Inc. (JCCA) to conduct a preliminary subsurface investigation at three (3) UST areas at Chet Hollifield Federal Building, Laguna Niguel, California. The objective of this investigation is to characterize whether the subsurface soils of the subject areas have been impacted by UST operations and provide recommendation on mitigation measures of subsurface soil contamination, if identified present.

The target areas of investigation include three (3) UST areas at the site. The first UST area is to the south of the energy plant where two (2) 10,000-gallon diesel tanks (tank No. 3 and 4) are located. The second UST area is to the north of the maintenance shop where one (1) 500-gallon abandoned (in place) waste oil tank (tank No. 5) and two (2) 10,000-gallon abandoned (in place) gasoline tanks (tanks No. 6 and 7) are located. The third UST area is the berm next to the western side of the southern entrance of the Building where one (1) 500-gallon abandoned (in place) diesel tank (tank No. 8) is located. There are two (2) other UST's (tank No. 1 and 2) at the site are still in use and are not targets of this investigation.

A site location map is provided as Figure 1 and the site plan is shown as Figure 2. Figure 2 also marks approximate locations of UST's under study and borings drilled during this investigation.



#### 2.0 SAMPLING LOCATIONS, PROCEDURES, AND PROTOCOL

In order to characterize whether subsurface soils of the subject areas have been impacted by operations of six (6) UST's under study, one (1) vertical and five (5) slant (approximately 30 degrees to vertical) borings were drilled (by hollow stem auger rig), one (1) underneath or next to each tank (with boring number corresponding to tank number).

Borings SB5 and SB8 were drilled to a total depth of 15 feet. The rest of borings were drilled to a total depth of 20 feet. Boring locations were selected based on the following criteria:

- o No identified underground utilities or obstructions; and
- o Convenient access for the drilling equipment.

SB4 is a vertical boring instead of slant boring due to above constraints limits the possibility of slant boring drilling to underneath tank No. 4.


Each of the borings was logged and sampled from ground surface to total depth. The soils were logged using the Unified Soils Classification System. Soil samples were collected at 5 foot intervals minimum. The samples were monitored in the field for organic vapor readings with a TLV sniffer. The sample descriptions, depths, and the TLV sniffer readings were recorded on the field logs attached as Appendix I.

Based on boring logs, the subsurface stratigraphy of the site is identified mainly consisting of silty clay, clayey silt, and silt. Groundwater was encountered at an approximately total depth of 17 feet (corresponding to an approximate vertical depth of 15 feet) in boring SB6 and SB7.

Soil samples were obtained using a split-barrel modified California sampler, which was lowered through the center of the hollow-stem auger to the desired sampling depth and driven into the soil using a 140-pound drop hammer. This and other sampling equipment was washed with Alconox solution and rinsed with clean water before each soil sample is collected. The soil samples were collected in six-inch long, 2-inch diameter, brass-lined tubes that had been cleaned with Alconox solution. Soil samples were immediately sealed, labeled, and chilled in a cooler. The samples were numbered sequentially with increasing depth from the top of the boring.


One sample with the highest organic vapor reading or collected at the total depth from each boring was shipped to a state-certified laboratory for analysis the same day of sample collection. Proper chain-of-custody procedures were followed. Chain-of-custody records of soil samples are attached as Appendix II.

The boring and sampling activity was completed on May 28, 1992. The boreholes were backfilled with native soils upon completion of sampling.



#### 3.0 LABORATORY ANALYSIS

Soil samples selected for analysis from borings SB3, SB4, SB8 drilled underneath or next to diesel USTs were analyzed for total petroleum hydrocarbon - diesel (TPH-D) using modified EPA Method 8015 and benzene, toluene, ethylbenzene, and xylenes (BTEX) using EPA Method 8020. The soil sample selected for analysis from boring SB5 drilled underneath the waste oil UST was analyzed for total recoverable petroleum hydrocarbon (TRPH) using EPA Method 418.1 and BTEX using EPA Method 8020. Soil samples selected for analysis from borings SB6 and SB7 drilled underneath gasoline USTs were analyzed for total petroleum hydrocarbon - gasoline (TPH-G) using modified EPA Method 8015 and BTEX using EPA Method 8020. Laboratory analytic reports for soil sample are attached as Appendix III.



#### 6.0 LIMITATIONS


The samples collected and used for analysis and the observations presented here are considered to be representative of the site conditions; however, soil and geologic conditions as well as groundwater conditions may vary significantly from area to area. If conditions are revealed which vary from finding of this project, the newly revealed conditions must be evaluated by the project engineer or geologist and conclusions adjusted as needed.

The opinion expressed herein is based on information collected during our investigation, our present understanding of the site conditions, and our professional judgment in light of such information at the time of preparation of this opinion. The report is an opinion worker, and no warranty is either expressed, implied or made as to the conclusions, advice, and recommendations offered in this report. The findings and conclusions of this report are valid as presented, at the date presented. Changes in regulations or property conditions may invalidate the findings and discussions of this report.


Report prepared by: UNITECH ENGINEERING, INC.

S. Robin Chang, Ph.D., R.G.

Project Manager








SCALE IN MIL

UNITECH ENGINEERING, INC. 16331 Gothard Street, Suite D Huntington Beach, CA 92647

SITE LOCATION MAP

FIGURE 1



# APPENDIX I FIELD BORING LOGS

## UNITECH ENGINEERING, INC.

			-				
EET	4POR	01			BORING  PIELD ENGINEER ROBIN CHANG		05/28/92
Z	) ( ) ( ) ( )	APLE 5/F0	SS	PROFILE	PIELD ENGINEER ROBIN CHANG	DATE BEGAN	05/28/92
	ORGAN (pr	SAMPLE BLOWS/FOOT	SOSO	PRO	CHECKED BY ROBIN CHANG	GROUND SURFACE E	L
0					3° Thick Asphalt		
_			ML		Clayey Silt, Biege, Moist, Medium Stiff		
5 —	20				Silty Clay, Brown, Moist, Very Stiff		
10-	15						
_			CL				
15 —	15						
_							
20	20						
_					Note: T.D. = 20', No Groundwater Encounte	red	Ab mark Way 2
 25_					Slant (approx. 30° from vertical) B	oring to Undernea	th Tank No. 3
=							
 30 <i>-</i> _							
_	1						
30							
_	†						
40 -	]						
- -	1						
45-	1						
45-							
_ _ 50_	1						
50 <i>-</i> -	1						
_	]						
55-							
_	1						
60 —						•	
_							
65	1						
_	]						
70-	1						-
_	1						
75 -						*	_
, s =							

	~				BORING NO. SB4
V PEE I	VAPOR (د	LE F00T		u l	PIELD ENGINEER ROBIN CHANG DATE BEGAN 05/28/92
DEPTH IN PEET	ORGANIC VAPUR (ppm)	SAMPLE BLOWS/FOOT	NSCS	PROFILE	CHECKED BY ROBIN CHANG GROUND SURFACE EL.
• 🚽					3° Thick Asphalt
7			ML		Clayey Silt, Biege, Moist, Stiff
5	15				Silty Clay, Brown, Moist, Very Stiff
.0-	20		CL		
5 —	15				
20					
	20				Note: T.D. = 20°, No Groundwater Encountered  Vertical Boring Next to Tank No. 4
5					
•					
35					
.0					
15-					
-					
50-					
55					
					·
55					
55-					
5					,

~			BORING NO. SB5
ORGANIC VAPOR (ppm) SAMPLE BLOWS/FOOT	SOSO	PROFILE	FIELD ENGINEER ROBIN CHANG  DATE BEGAN  DATE FINISHED  O5/28/92  CHECKED BY ROBIN CHANG  GROUND SURFACE EL.
	SW		3° Thick Asphalt Gravelly Sand, Brown, Moist, Medium Dense
30	ML		Clayey Silt, Biege, Moist, Very Stiff
20	CL		Silty Clay, Black, Moist, Very Stiff
20	ML		Silt, Brown, Moist, Very Stiff
			Note: T.D. = 15', No Groundwater Encountered Slant (approx. 30° from vertical) Boring Underneath Tank No. 5

	~				BORING NO. SB6
DEPTH IN FEET	ORGANIC VAPOR (ppm)	SAMPLE BLOWS/FOOT	SOSO	PROFILE	PIELD ENGINEER ROBIN CHANG DATE BEGAN DATE PINISHED 05/28/92 CHECKED BY ROBIN CHANG GROUND SURFACE EL.
- 0 			SW		3° Thick Asphalt Gravelly Sand, Brown, Moist, Medium Dense
- 10	10		ML		Clayey Silt, Trace Gravels, Biege, Moist, Very Stiff  Black, Moist, Very Stiff  Biege, Very Moist  Pine Sand Silt, Biege, Wet
					Note: T.D. = 20', Groundwater Encountered at 17' Depth Slant (approx. 30' from vertical) Boring Underneath Tank No. 6

	T					DODYNI		D.7
DEPTH IN FEET	ORGANIC VAPOR (ppm)	E 30T			FIELD ENGINEER	BORING ROBIN CHANG	DATE BEGAN	05/28/92
≧ I	NIC \	AMPL VS/F(	nscs	PROFILE	_		DATE FINISHED	05/28/92
OEPT	ORGA (	SAMPLE BLOWS/FOOT	n	PR	CHECKED BY R	OBIN CHANG	GROUND SURFACE 1	EL
- ° -					3" Thick Asphalt			
= =			ML		Clayey Silt, Biege,	Moist, Stiff		
5 	10		SM		Silty Fine Sand, Bl	ack, Moist, Dense		
10-	10		CL		Silty Clay, Black,	Moist, Very Stiff		
	15		ML		Clayey Silt, Black, Trace Gravels, Wet	Very Moist, Very Sti	ff	
- 10	10				Note: T.D. = 20', ( Slant (approx	Groundwater Encountere	ed at 17' Depth Boring Underneath	Tank No. 7
35-								
45 								
50 55								
60-								
65 65   70								
					·		,	

				BORING NO. SB8
OEPTH IN FEET ORGANIC VAPOR	SAMPLE BLOWS/FOOT	SOSO	PROFILE	FIELD ENGINEER ROBIN CHANG DATE BEGAN 05/28/92  DATE FINISHED 05/28/92  CHECKED BY ROBIN CHANG GROUND SURFACE EL.
5 15		ML		Clayey Silt, Biege, Very Moist, Stiff  Gray, Slightly Moist, Very Stiff
15 - 15				Moist
20				Note: T.D. = 15', No Groundwater Encountered Slant (approx. 30° from vertical) Boring Underneath Tank No. 8
65—				

# APPENDIX II SOIL SAMPLE CHAIN-OF-CUSTODY RECORDS

	6	)	CHA	IN OF CU	STODY RECO	RD											Log Nur	nber	
Client nar		JAMERLA	1	rili A		Project	or PO#	27773	-		/.	-/ ,	./	Ana	lyses	require	d //	, Ø	
City, State	9, Zip		1/ H.	1-6-1	Report attention	Fax #	-0.101										0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	<b>3</b> /	
Lab	Date	Time	Type* See key	Sampled by	,			Number	] /					/	/ /		3 2		
Sample number	Sampled	Sampled	See key below		Sample	description		of containers	3	/ 0.	5/					zô'c	\$ <u> </u>	Remark	KS.
3B3-54	3/234=	1955	50					1	./										
384	:	1750	,	h					V										
7.5 - 51		ر 5 ـ ـ ـ	)	٠.							<b>/</b>								
23 - 23		1477					÷			<b>V</b>									_
341-34		رفاحه	:			,				1							•	-	
158-73		1537	i i					. ;	1			1							
				:			A.												
								·.						2E. 3					
								43.		57			1	132	1				ang e
		·					3						- 4						
						,	, in the second second							)K.					
														\$\sqrt{3}					
	4	Signatu	ire			Print Nam	e	<i>i.</i>		<del>`</del>	Co	mpar	ny		A	4		Date	Time
Relinquished by Colin Clary			Ro	Lin C	hing	. <i>i</i> Jn	11=16	h	Ery	ine	ey: 5	2,	In	·- ;*		5/25/1	1740		
Received by Jack C. L. Ja				Pail	hal	Lu	Chemisk, Tow				10	י מי	),,	L. Y.	-	4 5	129/9	1740	
Relinquished by															0	,	1/10		
Received by																•			
Relinqu	ished by																		
Receive	ed by Lab	oratory									~							,	

# CHEMTEK ENVIRONMENTAL LABORATORIES INC.

14140 Alondra Boulevard, Suite A Santa Fe Springs Ca. 90670

Tel: (213) 926-9848 Fax: (213) 926-8324

#### Note

Samples are discarded 30 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.

* Key: AQ-Aqueous NA-Nonaqueous SL-Sludge GW-Groundwater SO-Soil OT-Other PE-Petroleum

DISTRIBUTION: WHITE with report / YELLOW To CHEMTEK / PINK To courier

# APPENDIX III RESULTS OF LABORATORY ANALYSES

inc.

ENVIRONMENTAL

LABORATORIES

14140 E. Alondra Boulevard Suite A Santa Fe Springs California 9 0 6 7 0

310-926-9848

Telephone Telefax

310 - 926-8324

# CERTIFICATE OF ANALYSIS

Job No:

205026

Date:06-03-92

This is the Certificate of Analysis for the following samples:

Client Work ID:

Unitech Eng.

Project No.:

E12009

Date Received:

05-29-92

Number of Samples:

6 . .

Sample Type:

soil

Samples were labeled as follows:

SAMPLE IDENTIFICATION	LABORATORY NUMBER
SB3-S4-20'	205026-01A
SB4-S4-20'	205026-02A
SB5-S1-5'	205026-03A
SB6-S3-15'	205026-04A
SB7-S4-20'	205026-05A
SB8-S3-15'	205026-06A

Reviewed and Approved:

Michael C.C. Lu

Laboratory Director

inc.

EFICIRONMENTAL LABORATORIES 14140 E. Alondra Boulevard Suite A Santa Fe Springs California 90670

Telephone

310-926-9848

Telefax

310-926-8324

Client:

Unitech Eng.

Project: E12009

Job No:

205026

Date: 06-03-92

Analysis: EPA 8015M (diesel)

Sample ID:

See below

Lab Sample ID: See below

Sample Date:

05-28-92

Analysis Date: 06-02-92

		Results	Detection
Sample ID	Lab Sample ID	(mg/Kg)	(mg/kg)
SB3-S4-20'	205026-01A	ND	50
SB4-S4-20'	205026-02A	ND	50
SB8-S3-15'	205026-06A	ND	50

COMMENTS: 'ND' INDICATES THAT THE COMPOUND IS NOT DETECTED AT THE SPECIFIED LIMIT.

inc.

14140 E. Alondra Boulevard Suite A Santa Fe Springs California 90670

ENVIRONMENTAL LABORATORIES

Telephone 310-926-9848 Telefax 310-926-8324

Client:

Unitech Eng.

Project:

E12009

Job No:

205026

Date: 06-03-92

Analysis: SCL 418/EPA 418.1

Sample ID:

See below

Lab Sample ID: See below

Sample Date: 05-28-92

Analysis Date: 06-03-92

Sample ID SB5-S1-5'

Lab Sample ID

Results (mg/kg)

Detection Limit (mg/kg)

205026-03A

46.57

10

COMMENTS: 'ND' INDICATES THAT THE COMPOUND IS NOT DETECTED AT THE SPECIFIED LIMIT.

inc.

ENVIRONMENTAL LABORATORIES

14140 E. Alondra Boulevard Suite A Santa Fe Springs California 9 0 6 7 0

Telephone 310-926-9848 Telefax 310-926-8324

Client: Unitech Eng.

Project: E12009

Job No: 205026 Date:06-03-92

# Analysis: EPA 8015M (gasoline)

Sample ID: See below Lab Sample ID: See below Sample Date: 05-28-92 Analysis Date: 05-29-92

		Dogulha	Detection Limit
		Results	
Sample ID	Lab Sample ID	(mg/kg)	(mg/kg)
SB6-S3-15'	205026-04A	ND	2.5
SB7-S4-20'	205026-05A	ND	2.5

COMMENTS: 'ND' INDICATES THAT THE COMPOUND IS NOT DETECTED AT THE SPECIFIED LIMIT.

inc.

14140 E. Alondra Boulevard Suite A Santa. Fe Springs California 90670

HIVIRONMENTAL LABORATORIES

Telephone 310-926-9848 Telefax 310-926-8324

Client:

Unitech Eng.

Project:

E12009

Job No:

205026

Date: 06-03-92

Analysis: BTEX (EPA 8020)

Sample ID:

See below

Lab Sample ID: See below

Sample Date: 05-28-92

Analysis Date: 05-29-92

Dilution Factor: 1

Detection Limit: 5 µg/kg

	SB3-S4-20' 205026-01A (μg/kg)	SB4-S4-20' 205026-02A (μg/kg)	SB5-S1-5' 205026-03A (μg/kg)
BENZENE	ND	ND	ND
TOLUENE	ND ND	ND ND	ND ND
M+P+O-XYLENE	ND	ND	ND
	SB6-S3-15'	SB7-S4-20'	SB8-S3-15'
	205026-04A	205026-05A	205026-06A
	$(\mu g/kg)$	$(\mu g/kg)$	$(\mu g/kg)$
BENZENE	ND	ND	ND
TOLUENE	ND	ND	ND
ETHYLBENZENE	. ND	ND	ND
M+P+O-XYLENE	ND	ND	ND



This document highlights the special installation requirements of the Owens-Corning double-wall tank. All other installation details are the same as single-wall tanks. (See OCF Publication 3-PE-6304.) Both this document and the OCF single-wall installation instructions are included in the tank shipping pocket.

Fiberglas underground tanks must be installed according to these instructions and NFPA 30 and 31. Local codes may apply and should be consulted. Failure to follow these installation instructions will void the warranty and may result in tank failure. Proper installation of Fiberglas underground tanks is required to prevent tank damage and to insure long-term corrosion-resistant service. It is imperative to read, understand and follow the instructions below.

The presence of an Owens-Corning representative at the jobsite does not relieve the contractor of his responsibility to follow the published installation instructions. Any variances to the published installation

# Double-Vall Fiberglas Underground Storage Tanks

Model DWT-2P, DWT-4P, and DWT-2S and Related Accessories **Installation Instructions** 

instructions must be approved by Owens-Corning in writing prior to the tank installation.

In order to activate the tank's 30-year structural warranty, the tank installation must be performed by an Owens-Corning Fiberglas Corporation trained contractor in accordance with these instructions. The Owens-Corning installation checklist, Pub. # 15-PE-8894 is shipped with each tank and must be completed and signed by the installing contractor's representative and the tank owner's representative. A copy of the installation checklist must be retained by the tank owner or installing contractor to substantiate any future warranty claim.




Table of Contents	Pages	Pages
Section A:		Section D:
Tank1nstallation	2-3	Switch Panels7
Section B:		Section E:
Hydrostatic Monitor	4-5	Piping Sumps8-9
Section C:		Section F:
Electronic Control Panels	6-7	/ Other Accessories
		Wiring Diagrams10-12

# Tank Installation Instruction lodel DWT-2P, DWT-4P, ar )WT-2

A1. Handling

Double-wall tanks cannot be unloaded from the truck manually; a crane or a backhoe of sufficient lifting capacity must be used. Do not use chains, cables, straps or ropes around the tank—these devices may "point-load" the tank and damage the tank wall.



Tanks 2,500 gallon capacity or larger are delivered to the jobsite with bumper pads fastened to each end of the tank. The tank may be installed with or without the bumper pads attached.

Do not roll or drop tank. For temporary storage at the jobsite, set tanks on smooth ground free of rocks and foreign objects and rechock with the tires or sandbags provided.

# A2. Bed and Backfill

The same as single-wall tanks. See OCF Pub. 3-PE-6304.

# A3. Testing

Double-wall tanks are shipped to the jobsite with a vacuum on the tank cavity. The vacuum should be left on the tank until the tank is ready to be air tested by the contractor. In the unlikely event of shipping damage, this temporary vacuum serves as an early warning device. The vacuum can detect relatively "large" leaks in the inner or outer tank, but it cannot detect "small" leaks. Therefore prior to installation, all tanks must also be air tested and soaped using the following procedure:

Release the vacuum in the tank cavity. Before setting the tank in the excavation, plug and tighten all fittings. Pressure test tanks to 5 psi as follows:


#### **Outer Wall Test:**

CAUTION: Pressurizing the tank cavity over 5 psi may damage the tank. For all tests, install an air gauge at the fitting where the air pressure hose is connected to the tank and a second gauge at the other monitoring fitting. Use an air gauge with ¼ or ½ lb. increments so that changes in pressure can be easily observed.

Using the OCF supplied manifold system connected to the inner tank and the cavity between the inner and outer tank, pressurize the tank cavity using air pressure from the inner tank

#### Step #1:

With the manifold valve to the cavity closed, first pressurize the inner tank to 5 psi maximum.



Step #2: Close the air supply valve to the inner tank and then DISCONNECT the air supply.

# Using a Manifold From The Inner Tank, Pressurize The Tank Cavity To 5 psi Maximum. manifold ar supply valve closed open ar gauge ar gauge ar gauge ar gauge

#### Step #3:

Pressurize the cavity between the inner and outer tank to 5 psi maximum by opening the manifold valve thereby transferring pressure from the inner tank

DO NOT CONNECT THE AIR SUPPLY DIRECTLY TO THE MONITORING FITTING OR ALLOW THE MANIFOLD VALVE TO BE OPEN DURING STEP #1. Typical air compressors can over pressurize (over 5 psi) the tank cavity between the inner tank and outer wall in less than 2 seconds.

#### Step #4:

Monitor the pressure on both the inner tank and cavity between the inner and outer tank for at least 30 minutes. Soap the outer tank and check for leaks as indicated by bubbles. An outer wall leak detected before backfilling is simple to repair. Do not backfill a tank with a known or suspected leak in the outer wall.

# Inner Wall Test:

#### Test #5:

Close the manifold valve to the cavity between the inner and outer wall. Release the pressure and vent the primary tank (by opening the air supply valve), but maintain the 5 psi maximum pressure on the cavity between the inner and outer walls.

#### Step #6:

Monitor the air gauge on the tank monitoring fitting for another 30 minutes, but no more than 60 minutes. Longer tests conducted during changing temperatures or changing cloud cover may distort test results ± 1 psi.

In the unlikely event a tank leak is discovered with any of the above tests, call the Owens-Corning Field Service Supervisor to schedule a tank repair.

Telephone: (419) 248-8196.

DO NOT EXCEED 5 PSI DURING AIR TEST.

After successfully completing the air test, disconnect and remove the air manifold fittings, hose, and valve.

# A4. Hole Size

The same as single-wall tanks. See OCF Pub. 3-PE-6304

# A5. Burial Depth

Minimum burial depths are the same as single-wall tanks. See OCF Pub. 3-PE-6304.

If a continuous vacuum monitor is used, the maximum burial depth is 3 feet from the tank top to grade.

For all other tank monitors the maximum burial depth is 7 feet from the tank top to grade.

# A6. Filter Fabric—Hole Liner

The same as single wall tanks. See OCF Pub. 3-PE-6304

# A7. Installation Procedure—Dry Hole

The sapre as single-wall tanks. See OCF Pub. 3-PE-6304.

# A8. Installation Procedure—Wet Hole

The same as single-wall tanks. See OCF Pub. 3-PE-6304.

# A9. Anchoring

Anchor straps must be placed between the arrows ▶ 

on the tank sides.

For tanks 2,500 gallon capacity and larger, the anchor straps must also be placed in the strap guides at the tank top.

# A10. Filling Primary Tank

The same as single-wall tanks. See OCF Pub. 3-PE-6304

# A11. Venting Primary Tank

The same as single-wall tanks. However, if the monitoring cavity between the inner and outer tank is also vented, it must be vented independently from the primary tank.

# A12. Tank Accessory Clearance

The same as single-wall tanks. See OCF Pub. 3-PE-6304


# A13. Tank Monitoring

Owens-Corning recommends the Hydrostatic Tank Monitor versus other methods because of its superior leak detection capability. However, the selection of the monitoring system and method is the responsibility of the tank owner and/or operator.

# Alternate Tank Monitoring Systems

The Owens-Corning double-wall tank is designed to accommodate a variety of leak monitoring systems. If another type of tank monitor is specified initially, the Hydrostatic Tank Monitor can still be activated at a future date.

An alternate tank monitoring sensor can be located at any monitoring fitting on the tank top. However, to provide maximum future flexibility, locating the tank sensor through the fitting in the Fiberglas reservoir will permit the tank owner to more economically retrofit the tank, if he chooses, to activate the Hydrostatic Tank Monitor in the future.



*Tank models DWT-2P and DWT-4P only

# Monitoring Capabilities—(All Owens-Corning Double-Wall Tanks)

The following restrictions apply for the various types of double-wall tank monitors:

- a. Liquid sensors—when "dry" cavity monitors (which detect the presence of a liquid) are used, the cavity between the inner and outer tank may be either vented to the atmosphere or sealed.
- b. Gasoline vapor sensors—when gasoline vapor sensors are used, the cavity between the inner and outer tank may be either vented to the atmosphere or sealed.

# Additional Monitoring Capabilities (Tank Models DWT-2P and DWT-4P Only).

 c. Hydrostatic Tank Monitor—tank burial depth must not exceed 7' from tank top to finish grade.


The monitoring cavity must be vented to the atmosphere. The optional reservoir sensor, supplied by Owens-Corning senses the liquid level in the reservoir and also automatically vents the monitoring cavity.

- d. Vacuum monitoring—when vacuum monitoring is used, the maximum vacuum is 3" mercury (1.5 psi maximum).
- e. Positive air pressure monitoring—when positive air pressure monitoring is used, the maximum air pressure is 3 psi

# A14. Installation of Liquid or Vapor Sensors

When liquid or vapor sensors are used, the tank should be sloped at time of installation so that the lowest elevation is at the monitoring end

These sensors are normally installed using an electrician's wire puller to position the sensor at or near the tank bottom. Most sensors can be installed from finished grade. However, for ease of installation, insert the sensor in the tank cavity before installing the monitoring riser pipe to grade.



The space between the inner and outer tank wall is  $1\frac{1}{6}$ " for tanks 12,000 gallon capacity and less; the cavity space is  $1\frac{3}{4}$ ' for tanks 15,000 gallon capacity and larger.

Consult monitoring equipment manufacturer for proper installation.

# A15. Installation of vacuum or air pressure monitoring systems

Consult monitoring equipment manufacturer for proper installation.

# A16. Installation of Hydrostatic Tank Monitor

See next page.

If you have an installation condition which is not fully addressed in these instructions, please call the Owens-Corning Tank Installation Supervisor at 419-248-7371.

If you need to schedule a tank repair, please call the Field Service Supervisor, 419-248-8196.

3

# Installation Instructions-

13—117

- In Irostatic Tank Monitor



For use with Model DWT-2P and DWT-4P tanks only.

# B1. Preparation

The annular space in the tank can be filled after tanks have been placed in the excavation. DO NOT PUT ANY PRODUCT IN THE INNER TANK WITHOUT SETTING AND BACKFILLING TO THE TANK TOP. FILL THE ANNULAR SPACE BEFORE FILLING THE TANK, THEN REMOVE A PRIMARY TANK FITTING PLUG AND INSPECT THE INNER TANK FOR LEAKS.

# **B2.** Antifreeze Solutions

Antifreeze solutions are necessary if ambient or product delivered temperature drops below freezing.

Chemically acceptable antifreeze solutions include ethylene glycol (automotive antifreeze), propylene glycol (food-grade antifreeze) and calcium chloride (non-toxic brine). However, before selecting the antifreeze solution, consult local environmental codes for possible restrictions—particularly if using ethylene glycol.

Freeze Protection	% Glycol Mixture , (with water)	Brine
20°F	20%	N/A
0°F	30%	N/A
– 20°F	40%	N/A
- 40°F	50%	Premixed*

^{*}As supplied by Owens-Corning

If using glycol antifreezes, mix the antifreeze solution before pouring into the tank cavity. Brine antifreeze provided by Owens-Corning is premixed and ready to use without the need for mixing or blending.

# **B3. Jobsite Safety Precautions**

Wear safety glasses and protective clothing when mixing or handling any antifreeze solution. In the event of an accident, take the following action:

#### Contact:

Contact may cause minor eye injury and skin irritation. In case of contact with eyes, promptly flush eyes with plenty of water for at least 15 minutes and get medical attention. For skin, flush skin with plenty of water.

#### Ingestion:


May cause gastrointestinal irritation or ulceration. If swallowed, induce vomiting and consult a physician.

#### Spillage:

Flush area with plenty of water. Surfaces on which people walk may remain wet longer due to moisture being held by spilled material.


# **B4. Filling the Annular Space**

Where safety conditions dictate, backfill the tank first, then fill the annular space. Slope the tank 2" to minimize trapped air in the cavity. Trapped air may cause false alarms at a later-date. If the Fiberglas reservoir is located near the tank end, set the tank in the excavation with the reservoir placed at the high end of the tank. Where jobsite conditions permit, fill the annular space with liquid prior to backfilling.



The 4" NPT fitting plug in the top of the reservoir should be removed prior to filling the annular space. Remove the fitting plugs and place standpipes at the 4" monitoring fitting located on each end of the tank. The standpipes (2" diameter or larger fiberglass pipe is recommended) must be no less than 4' higher than the tank top.

Note: Since the 1,000 and 2,500 gallon capacity tanks have only one monitoring fitting in addition to the Fiberglas reservoir, the standpipes should be placed on the one monitoring fitting and in the fitting at the top of the reservoir. Since the 550 gallon capacity tank only has the 4" fitting in the Fiberglas reservoir, place one standpipe in the Fiberglas reservoir fitting.



The liquid to fill the cavity must be gravity fed by pouring liquid into the standpipe. A water hose may be used only if it is *not* screwed or attached to any of the monitoring fittings. Connecting a pressurized hose directly to the monitoring fitting will overpressurize the cavity and will damage the tank.

To minimize the trapped air, fill the annular space from the low end of the sloped tank. Continue to fill the cavity with water until liquid begins to overflow the standpipes. Refilling the cavity through the fill standpipe will be required. After water overflows the Fiberglas reservoir, replace the plug in the reservoir fitting.

Disconnect the standpipe at the low end of the tank and replace the fitting plug. The standpipe at the high end of the tank remains connected to the monitoring fitting.

The cavity and remaining standpipe are gravity filled until the liquid level in the remaining standpipe is at least 4' higher than the tank top. Tighten the lower monitoring fitting securely.

# **Testing**

Continue refilling to the 4' level on the standpipe until the liquid level stabilizes (less than ½" drop in 1 hour).

If backfilling after filling the annular space, thoroughly check the outer tank for leaks. An exterior leak detected before backfilling is simple to repair. Do not backfill a tank with a known or suspected leak in the outer wall.

Remove a primary tank fitting plug and inspect the inner tank for leaks. Do not enter the tank without adequate safety protection.

In the unlikely event a tank leak is discovered, call the Owens-Corning Field Repair Supervisor to schedule a tank repair. Telephone: (419) 248-8196.


After the liquid level has stabilized, disconnect the remaining fill standpipe and plug the monitoring fitting. Additional fluid may be added, if necessary, in the Fiberglas reservoir so that the reservoir is  $\frac{2}{3}$  full.


# **B5. Fiberglas Reservoir Sensor**

After filling with liquid, the level in the Fiberglas reservoir may be monitored periodically by using a dipstick or continuously by using the optional reservoir sensor, in conjunction with an optional electronic control panel.

The monitoring sensor is placed into the Fiberglas reservoir through a 4"diameter riser pipe from grade. The sensor includes the riser pipe cap with a 16" length of flexible conduit, which is connected to an electrical junction box (contractor supplied).

The PVC riser pipe cap is designed to slip on and off the PVC fitting installed on the top of the riser pipe. These pipe fitting connections are designed to provide quick and easy access to the sensor and reservoir without disconnecting any electrical or piping connections. However, for extreme high groundwater conditions, to prevent the intrusion of groundwater into the reservoir, the factory drilled vent holes (4) in the PVC riser pipe cap must be plugged and a separate vent line installed from the riser pipe to above ground. In addition, the PVC riser pipe top should be glued to the riser pipe fitting.





# **B6.** Electrical

All electrical connections must be in accordance with local codes. To wire the reservoir sensor to the control panel use 16 AWG type MTW or 14 AWG type THNN.

# B7. Testing

Remove the sensor from the Fiberglas reservoir to simulate a low liquid level condition; removing the sensor from the fluid in the reservoir will activate the control panel low level alarm. Then, immerse the sensor into a bucket of water to activate the high level alarm.


# **B8. Reservoir Leak Detection**

In the event of an alarm condition, remove the riser pipe cap and extract the reservoir sensor. Then use a dipstick to measure the reservoir liquid level to determine if the low or high level alarm was tripped. If the dipstick measurement is 1.25" (2.00" for tanks 15,000 gallon capacity or larger) or less, the reservoir has drained, indicating a low level alarm. If the dipstick measurement is 10" or higher, the high level alarm was activated.

For a low level alarm, refill the reservoir to  $\frac{2}{3}$  full and continue monitoring. For a high level alarm, remove liquid from the reservoir until it is  $\frac{2}{3}$  full and continue monitoring.

If an alarm condition occurs and the reservoir level is normal, the control panel is improperly wired (consult your local electrician) or has a defective component. (See Section C9 on Control Panel False Alarms.)


If an additional low level or high level alarm occurs, call the Owens-Corning Field Service Supervisor at 419-248-8196.




# Installation Instructions— Electronic Control Panel Mo

# s SB0011A and SB0014A

Installation of Model SB0011A is detailed in this section and Figure B. Reference Figure C for Model SB0014A circuit diagram.






# C1. Location

Locate the control panel in a non-hazardous area where an explosive environment does not exist. The control panel can be wall mounted using the provided mounting hardware.

# C2. Power Circuit


The control panel is pre-assembled and ready to wire. A 120 volt AC power source is required. All wiring must be in accordance with local codes. The power circuit wiring (contractor provided) enters the left conduit at the bottom of the control panel and is connected to terminals 1 and 2.



A circuit breaker (contractor provided) common to other devices is recommended. Using a circuit breaker common to other devices will increase the probability the tank owner is aware of a tripped circuit breaker. If there is no power to the control panel, the alarm bell and other warning devices cannot be activated.

# C3. Sensor Circuit

The pre-assembled reservoir sensor is ready to wire (contractor supplied) to the control panel. For intrinsically safe wiring, use 16 AWG type MTW or 14 AWG type THNN (contractor supplied). For UL rated applications the maximum wiring distance between the sensor and control panel is 1,750 feet. The wiring for the sensor circuit enters the right conduit at the bottom of the control panel and is connected to terminals A and B.




On the four circuit control panel (Model SB0014A), there are four terminal pairs (AB, EF, IJ, and MN). Connect a separate sensor to each terminal pair. If less than four monitoring circuits are used, a jumper wire is required to separately connect each unused terminal pair.

# C4. Optional Warning Device Circuit

The tank owner may specify additional warning devices to be provided by the contractor. The optional warning device circuits enter the panel at the center conduit.

# Transmission Contact Switch

An automatic telephone dialer typically requires only a contact switch to activate the dialing function. The telephone dialer is plugged (or wired directly) into an electrical outlet for the power source. The power source for the dialer is not supplied by the control panel. With power to the control panel, normally closed contacts are at terminals 3 and 4. These terminals will open—providing the switching mechanism to activate the dialer—when the control panel goes into the alarm mode.



# **Power Source Switch**

A typical wiring diagram is provided for accessories requiring power such as a light beacon. The wiring diagram (see Figure B) will provide 120 volts AC; the optional warning device must be rated for 300 watts or less.



# C5. Alarm Bell Silence Switch

The control panel is equipped with an "ALARM BELL SILENCE" switch. Positioning this switch to "OFF" will silence all audible alarms, but will illuminate the "ALARM BELL" light. If this feature is not desired, the control panel can be rewired (at the location of the switch inside the control panel) by the contractor to override the alarm bell silence feature.

# **C6. Normal Operation**

A stable liquid level range in the reservoir indicates that both the inner and outer wall of the double-wall tank are leak-free. The liquid level in the reservoir will fluctuate as the temperature of the incoming stored product changes. The reservoir is designed to provide adequate capacity for normal thermal expansion and contraction. As long as the reservoir liquid level is in the normal range, the "NORMAL" light is illuminated continuously. The "ALARM BELL" switch should be set to "AUTO."

# C7. Testing and Maintenance

The control panel warning system should be checked at least once per year. Depress the "TEST BUTTON" switch located on the side of the control panel to verify that each circuit is operational. This "TEST BUTTON" verifies the operation of the internal circuits of the control panel. However, it does not test the operation of the monitoring sensors.

A faulty circuit in the control panel can be diagnosed using the troubleshooting guide (See Figure A). Contact the Owens-Corning Field Service Supervisor for control panel replacement parts.

# C8. Leak Detection

In the unlikely event the reservoir totally drains, the control panel alarm will be activated—the warning light will illuminate, the alarm bell will sound, and the transmission contacts will activate any accessory alarm devices.

The alarm bell can be temporarily silenced by setting the "ALARM BELL" switch to the "OFF" position. Under this condition, the "ALARM BELL" light is illuminated, the "WARNING" light remains on, and the "NORMAL" light is off.

See Section B8 on Reservoir Leak Detection

# C9. Control Panel False Alarms

A control panel false alarm occurs when the panel goes into the alarm mode, but the reservoir liquid level is still in the normal range. Although rare, these types of false alarms typically result from the failure of an electronic component inside the control panel. All electronic components must function properly to maintain the "NORMAL" condition. An electrical component failure will result in an "ALARM" condition. Refer to the troubleshooting guide below to identify the specific problem.

# Installation Instructions—Switch Panels Models SP1 and SP4

# D1. General

The switch panel will double the number of piping and double-wall tank sensors which can be monitored with the Owens-Corning supplied electronic control panels. A switch panel connects a tank sensor and piping sump sensor to one monitoring circuit of the control panel. In an alarm condition, when both the tank and piping sump sensor are connected to the same monitoring circuit, the switch panel is used to determine which sensor is in the alarm mode. The switch panels can also be used to connect a maximum of two reservoir sensors to each monitoring circuit.

Installation of Model SP1 is detailed in this section and Figure D. Reference Figure E for Model SP4 circuit diagram.

# D2. Location

Locate the switch panel in a non-hazardous area where an explosive environment does not exist, preferably next to the electronic control panel. The switch panel can be wall mounted using the provided mounting hardware.

# D3. Sensor Circuits

For UL rated applications, the maximum wiring distance between the control panel and the sensors is 1,750 feet. However, if a switch panel is used the maximum wiring distance is 875feet. For intrinsically safe wiring, use 16 AWG type MTW or 14 AWG type THNN (contractor supplied). The wiring from the switch panel (from terminals 1 and 2) enters the right conduit at the bottom of the control panel and is connected to terminals A and B.

On the four circuit control panel (Model SB0014A), there are four terminal pairs (AB, EF, IJ, and MN). Connect a separate sensor circuit from the switch panel (Model SP4) to each terminal pair. If less than four sensor circuits are used, a jumper wire is required to separately connect each unused terminal pair in the control panel.

The tank sensor (from the reservoir) and the piping sump sensor are wired to the switch panel. Connect the tank sensor wires to terminals 3 and 4 and the sump sensor wires to terminals 5 and 6 in the switch panel. The switch panel is pre-wired so that the tank and pipe sump sensors are connected in series.

# D4. Transmission Contact Switch

In the event the piping sump sensor detects liquid in the piping sump, Owens-Corning recommends that the power to the submersible sump be disconnected. This can be performed automatically by providing an electrical feedback circuit from the monitoring system to disengage the submersible pump. The transmission contacts in the electronic control panel (located at terminals 3 and 4 for Model SB0011A) can provide the switching mechanism for this feedback circuit

The four circuit control panel (Model SB0014A) has four separate sets of transmission contacts. When the tank sensor and piping sump sensor are connected in series using a switch panel, an alarm in either sensor would activate the transmission contacts for that monitoring circuit. If the tank sensor and pipe sump sensor are wired on separate monitoring circuits using the four circuit control panel, each sensor would activate a separate set of transmission contacts.

# D5. Testing

After connecting the tank sensor, the pipe sump sensor, and the switch panel to an operational control panel, activate the sensors to test the total system. To test the tank sensor, remove the reservoir sensor from the reservoir. To test the pipe sump sensor, lift the trip rod on the sensor. Depress the appropriate push button on the switch panel to temporarily silence the alarm. This will determine which sensor is in the alarm mode.

# D6. Leak Detection Using Switch Panels

In the unlikely event of an alarm condition, independently depress each push button on the switch panel until the alarm is temporarily silenced. The push button which silences the alarm indicates which sensor is in the alarm mode.



# Piping Sumps Model PS 42-27, PS 42-30A, SPS 42-22A and SPS 42-30A

# E1. General

The piping sump provides containment of a submersible pump leak and also provides a termination point for double-wall piping systems

The piping sump is produced in two pieces: a top half and bottom half. The bottom half is surface mounted on the manway where the submersible pump will be located. After completing the piping and wiring connections to the submersible pump and optional piping sump sensor, the top and bottom halves are cemented together using the two-part adhesive used for fiberglass pipe connections.

# E2. Handling

Use the side handles to manually or mechanically lift the piping sump. Do not roll or drop. Set on smooth ground. If high winds are anticipated, the contractor is responsible for tying down to prevent damage from being moved by high winds.


# E3. Inspection

Before installation visually inspect the piping sump for potential impact or handling damage.

# E4. Tank Burial Depth

The piping sump is designed for a tank burial depth of 48" from the tank top to grade. Deeper burial depths are possible by using a 24" manway extension.


The piping sump bottom can be cut in the field to accommodate tank burial depths less than 48" but above 36." Use a sabre saw or circular saw with carbide tipped masonry blades to trim up to 12" off the upper edge of the piping sump bottom.



# E5. Surface Mounting on a 22" or 30" Manway

If the piping sump is to be surface mounted on the manway, first remove the existing bolts on the manway cover. Rotate the manway cover to align the fittings and submersible pump with the intended piping run (see typical piping configuration). Wipe the manway cover to remove any dirt, gravel or other foreign substances that may interfere with the gasket. Place the supplied cork gasket on top of the steel cover and align it with the bolt pattern. Position the bottom of piping sump on top of the gasket.

Use the supplied silicone caulk and washers to seal the bolt holes. Before bolting the piping sump to the manway cover, fill the bolt holes with silicone caulk. After caulking the bolt holes, fasten the sump onto the manway using the bolts and neoprene coated washers. The neoprene coated washer must be installed with the neoprene side down to assure the piping sump is water tight.



As the bolts are tightened, the 1-riut will permanently imbed itself in the fiberglass manway flange. A surface-mounted piping sump will prevent future access to the tank from that manway.

# E6. Hydrostatic Water Test

Use the supplied cork manway gasket, silicone caulk and metal/ neoprene washers to surface mount the piping sump on the manway cover. After tightening all bolts, fill the piping sump bottom with one to two inches of water. Allow the water to stand at least 12 hours while other work is being performed.

Inspect the bolts and underside of the tank manway for potential leaks. Tighten bolts or repair any gaskets/seals as indicated by the presence of moisture.

# E7. Piping Connections


The pipe sump fittings are standard FRP couplings. Any unused pipe fittings can be plugged using standard FRP pipe plugs.

The primary piping passes through the pipe sump fitting. The outer jacket of the double-wall piping is cemented to the pipe sump fitting. Fiberglass pipe manufactured by Smith Fiberglass or Ameron is compatible with the pipe sump fitting.


# E8. Typical Configurations


Double-wall piping is stiffer and less forgiving of improper alignment than single-wall piping. Layout the piping trench and piping sump orientation to assure that the piping system can be connected properly. It may be necessary to rotate the manway cover and submersible pump so that the primary piping inside the piping sump is properly aligned to interface with the double-wall piping system.

The primary piping that connects to the submersible pump can be rigid FRP piping or flexible connectors. Although flexible connectors are more costly, they will minimize potential piping alignment problems inside the piping sump, particularly for contractors not familiar with double-wall piping systems. Two typical piping configurations are shown:



Note: When using the submersible pump offset from the center of the manway, the maximum height for the submersible pump (without leak detector) is 28° from the manway cover, this allows ample room to remove the submersible pump for maintenance A minimum height of 26° is recommended to avoid over-stressing the flexible connector.





# E9. Electrical Connections

Electrical conduits are connected to the steel NPT fittings. Four fittings are provided to accommodate wiring to the submersible pump and an optional monitoring sensor. All wiring connections must conform to local and national electrical codes.

The piping sump (Model series SPS only) is to be air tested after the electrical connections are made. Use seal-off fittings to make the electrical connections air, tight.

# E10. Monitoring

The piping sump can be equipped at the jobsite with an optional monitor to detect the presence of liquid in the piping sump. The monitoring sensor should be placed in a protective casing, which has been perforated. The casing is fastened to the sensor mounting bracket on the side of the piping sump using a mounting clamp.

The optional Owens-Corning Fiberglas factory supplied pipe sump sensor is already mounted inside a plastic casing and is supplied with the mounting clamp.


If the monitoring sensor detects liquid in the piping sump, Owens-Corning recommends that the power on the submersible pump be disconnected. This can be performed automatically by providing an electrical feedback circuit from the monitoring system to disengage the submersible pump. (See Section D4: Transmission Contact Switch)

# E11. Backfilling and Clearances

After completing all piping and electrical connections, the top and bottom halves of the piping sump are cemented together. Clean the joint area to insure maximum bonding strength. Use the two-part adhesive supplied by the fiberglass pipe vendor. Apply a generous amount of mixed adhesive to both the bottom and the top joint. Place the top half into position and press down to squeeze out the excessive adhesive. Follow other installation instructions provided by the adhesive manufacturer.

Hand place gravel around and under the bottom of the piping sump.

The piping sump must be isolated from direct traffic loading.



Allow a 2" minimum ...nce between the top of the piping sump and the bottom of the concrete pad. Backfill to the top of the piping sump, then place compressible foam board (48"L maximum x 48"W maximum x 2" thick—or equivalent layers) on top of the piping sump. The 9" thick concrete traffic slab can be poured directly onto the compressible foam board. However, the concrete must not come into direct contact with the piping sump. Styrofoam or urethane foam sheathing may be used for the compressible board (contractor supplied); the minimum length and width of the compressible board is 42".

As an alternate to the compressible board, a 48" diameter riser (12" long) can be used to isolate the piping sump from the traffic slab. Allow a 6" minimum clearance between the bottom of the riser and top of the double wall pipe.

# E12. Air Testing (Model Series SPS Only)


For Model series SPS sumps, the air test must not exceed 5 psi. Monitor the pressure for at least 30 minutes. While under pressure, soap the piping sump and check for leaks as indicated by soap bubbles.

# E13. Traffic Slab

Model series PS piping sumps can be accessed through a 24" street box; model series SPS sumps require a 30" street box.

Traffic areas require a rebar reinforced concrete road surface to span the underground void created by the piping sump.

# E14. Piping Sump Sensor



Using the supplied mounting clamp, mount the piping sump sensor on the sensor mounting bracket. For maximum sensitivity, the sensor must rest on the bottom of the piping sump.

The float switch is activated after 2" of liquid has accumulated in the bottom of the piping sump—approximately 12 gallons of liquid. To improve the sump sensor sensitivity, add 2" of gravel to the bottom of the piping sump. With gravel, the sensor is activated by approximately 5 gallons of liquid. If gravel is used in the sump bottom, wrap the sump sensor sides and bottom with filter fabric to prevent small stones or grit from entering the sensor casing.

The piping sump sensor can be wired directly to the Owens-Corning supplied electronic control panel or can be indirectly wired to the control panel using an optional switch panel. For intrinsically safe wiring, use 16 AWG type MTW or 14 AWG type THNN (contractor supplied). All electrical connections must be in accordance with local and national electrical codes.

After the sensor is installed and connected to an operating control panel, the sensor can be tested by lifting the trip rod located on the top of the sensor.

For details of wiring the Model PSS sensor see Figures D and E.

# E15. Maintenance

Use caution for normal maintenance or inspection of the submersible pump and piping located in the piping sump.

WARNING: FUEL VAPORS MAY BE PRESENT IN THE PIPING SUMP. KEEP ALL IGNITION SOURCES AWAY WHEN REMOVING THE PIPING SUMP LID.

# F1. Other Accessories

# **Compression Rings**


Optional steel compression rings are available to connect a piping trench liner (flexible membrane or Fiberglas trench liner) to:

. The manway cover.

pushbutton.

- · A Fiberglas attachment ring
- · A Manway interface ring.

When flexible membranes are used, a special caulk (supplied by the trench liner manufacturer) is applied to both sides of the liner before fastening it to the manway flange.




Replace relay ISR1


# Figure A: Troubleshooting Guide For Electronic Control Panels (Model SB0011A and SB0014A)


ell On, Alarm Light On, Normal Light Off	
Bell off, alarm light off, normal light on Bell on, alarm light on, normal light off	Replace fluid in sensor Proceed to Test 1.2
Bell on, alarm light on, normal light off Bell off, alarm light off, normal light on	Replace relay IRS1 Proceed to Test 1.3
Bell on, alarm light on, normal light off Bell off, alarm light off, normal light on	Replace pushbutton switch Inspect sensor and wiring for defect
ll On, Alarm Light Off, Normal Light On	
None	None
ll On, Alarm Light Off, Normal Light Off	
Bell on, alarm light on, normal light off Bell on, alarm light off, normal light off	Replace relay ISR1 Replace burned out light
	Bell on, alarm light on, normal light off Bell on, alarm light on, normal light off Bell off, alarm light off, normal light off Bell on, alarm light on, normal light off Bell off, alarm light off, normal light on II On, Alarm Light Off, Normal Light Off None II On, Alarm Light Off, Normal Light Off Bell on, alarm light on, normal light off

# Figure B: Detailed Circuit Diagram Model SB0011A Control Panel



Bell on, alarm light on, normal light off






#### Figure E: Detailed Circuit Diagram Model SB0014A Control Panel with Model SP4 Switch Panel Four Tanks with Sensors on Each Tank Reser-Model SB0014A **Four Circuit Control Panel** voir and Sensors on Optional Piping Sumps Monitoring Monitoring circuit circuit 2 circuit 3 circuit 4 If less than 4 monitoring circuits are used, a jumper wire is required to E separately connect each unused pair of terminals Model SP 4 switch panel Tank Pipe Pipe sensor sensor sensor sensor sensor sensor sensor sensor В4 B5 B6 C1 C2 C3 C4 C5 D2 D3 D4 D5 82 B3 D1 D6 В A3 A5 A6 Safe area Safe area Safe area Seal off fittings Hazardous Hazardous Hazardous area area Piping Tank Piping Tank Tank Piping Tank Piping reservoir sump reservoir sump reservoir reservoir sump sensor sensor sensor sensor



Non-Corrosive Products Division Fiberglas Tower Toledo, Ohio 43659



# HYDROSTATIC LIQUID LEVEL TANK GAUGING SYSTEMS




This family of indicators is the same as the hydraulic line only with relation to outside case dimensions and scale length. Based on an adaptation of the hydrostatic principle, air pressure is required to obtain liquid level indication. This is provided either by a built-in hand pump or by a source of clean dry air.

Installation is readily accomplished in either empty tanks or partially filled tanks. A 2" tank opening is required through which the air bell assembly (supplied by Pneumercator) is installed. Once the system has been properly installed, maintenance is practically non-existent. All that is required is an occasional check of the zero position which takes less than a minute.

For constant air systems, high or low level switches can be supplied which will activate a light, audible alarm or start and stop pumps to maintain predetermined levels.

The hydrostatic gaging system described on this page should be used only on tanks vented to the atmosphere.

# PRINCIPLE OF OPERATION



Air is introduced in the line between the indicator and the tank by means of either the built in hand pump or a source of clean compressed air. When the pressure in this line equals the pressure at the bottom of the bubble pipe (created by the head of liquid in the tank), the bellows in the indicator mechanism expands—or contracts—and thru suitable linkage moves the pointer over the face of the dial. Excess pressure bubbles out of the bottom of the bubble pipe.

#### HYDROSTATIC TYPE REMOTE READING

Pneumercator hydrostatic tank gaging systems operate on the principle that the pressure at the bottom of the tank varies with the liquid head. The pressure balance which is equal to the tank liquid height is converted into tank contents and indicated on a calibrated dial. These gages are designed to measure liquids having a constant specific gravity in vented tanks. The simple bubble pipe arrangement in the tank is ideal for vertical tanks and those having internal obstructions. For corrosive liquids the pipe can be of proper resistant material.

There are two types of systems available. One

system has a hand pump built into the gage case. A few strokes of the pump supplies the air for purging the tube in the tank to obtain the "pressure balance". The hand pump gages can operate a distance up to 150 feet from the tank. The other system is with the hand pump omitted and a constant source of clean dry air is used to instantly follow tank level changes and automatically indicate capacity on a calibrated dial. Constant air gages can be located up to 1000 feet from the tank.

This gaging system is listed by Underwriters Laboratories Inc., N.Y.C., Board of Standards and Appeals.

#### HAND PUMP MODELS

STANDARD SYSTEM: Includes a dial type indicator complete with gallons dial, built in hand pump, 30 feet of ¼ inch tubing, an air chamber, a 2 inch tank entrance bushing and all other necessary fittings to complete the installation. Additional tubing is available.

Instrument Case: Surface or flush mount.

Tank Pressure: Gage Models:

Vented tanks P-5 (5 inch scale),

P-11 (11 inch scale) P-14 (14½ inch scale), P-29 (291/2 inch scale)

SUGGESTED SPECIFICATION: Provide and install for each tank a remote reading UL listed tank gaging system which shall be of the dial hydrostatic type, utilizing an integral built in hand pump for manual operation. The instrument shall be factory calibrated for the tank contents and indicated on [ (5") (11") (14%") (29%") ] dial ) gallons without the use of scale marked for ( gage glass or fluids. The gaging system shall be ) manufactured by The Pneumercator model ( Co., Inc., Farmingdale, N.Y. 11735.

# GAGE SELECTION

Model gage recommended depends on tank capacity. A P-5 model on a 10,000 gallon tank has readable spaced marks representing 200 gallons each. A P-11 and P-14 has approximately 100 gallons each but the P-29 with 50 gallons for each mark is more suitable for measurement as you can interpolate between marks and read to approximately ten gallons.

#### CONTINUOUS READING MODELS

STANDARD SYSTEM: Includes indicating instrument and a 2" tank entrance assembly with choke and fittings for "4" tubing to air supply and indicator.

Surface or flush mount. Indicator Case:

Up to 1000 feet Tank Distance:

High and/or low level avail-Switches:

able S.P.D.T., 10 amp. non-

inductive at 120V-ac.

P-5A (5 inch scale), P-11A Gage Models:

(11 inch scale), P-14A (14½ inch scale), P-29A (29½ inch

scale).

SUGGESTED SPECIFICATION: Provide and install for each tank a remote continuous reading dial type hydrostatic tank gage. The gaging system shall utilize an external source of compressed air and include a pressure regulator, a sight glass bubbler, an air filter, a combination jewel choke and tank entrance fitting. The gaging system shall provide continuous indication of tanks' contents on a [(5") (11") (141/2") (291/2")] dial scale calibrated for ( ) gallons. Switches shall be provided for actuating a C-1SA or C-2SA alarm console which provides high and low level warning lights and an audible alarm. The gaging system shall be model ( manufactured by The Pneumercator Co., Farmingdale, N.Y. 11735.

Experience has established the following gage selection:


Model P-5 For tanks up to 3000 gallons


Model P-11 For tanks 3000 to 7500 gallons


Model P-14 For tanks 5000 to 10000 gallons

Model P-29 For tanks 8000 gallons and upward.

INSTALLATION: Either the hand pump or constant air type gages can be installed guickly and simply in empty or full tanks. No special skills are required.











# "ORDERING SPECIFICATIONS"

MODEL: P-5  , P-5A  , P-11  , P-11A  , P-14  , P-14A  , P-29  , P-29A	MOUNTING:		
${ t contents}$ : corrosive $\square$ , noncorrosive $\square$ $ extstyle /$ tubing length to indicator			
DIAL CALIBRATION: GALLONS [], LITERS [], FEET AND INCHES [], OTHER			
CONSTANT AIR SWITCH: LOW [], HIGH [] AIR FLOW INDICATOR: REGULATOR	FILTER:	ALAR	vi: •

"REQUIRED TANK INFORMATION"				
TANK TYPE (STEEL OR FIBERGLASS)	HORIZONTAL OR VERTICAL TANK			
TANK MANUFACTURER	OVERALL LENGTH OUTSIDE			
TANK MODEL (MANUFACTURERS Nº.)	INSIDE DIAMETER			
CAPACITY (ACTUAL)	TYPE OF ENDS			
TANK CONTENTS	SPECIFIC GRAVITY			






- 1 I.) SWITCHES ARE OPTIONAL AND WILL BE FACTORY SET TO OPERATE
- AT LEVEL SPECIFIED BY CUSTOMER.

  2 -2.) AIR FLOW INDICATOR OPTIONAL PROVIDES VISUAL INDICATION OF AIR FLOW THROUGH SYSTEM.

  3.) ALL SYSTEM COMPONENTS ARE SUPPLIED WITH FITTINGS TO
- 3.) ALL SYSTEM COMPONENTS ARE SUPPLIED WITH FITTINGS TO ACCEPT 1/4 O.D. TUBING,

  3. -4.) IN ROUTING LINES, AVOID (AS MUCH AS POSSIBLE) BENDS OR DIPS THAT WOULD ACT AS MOISTURE TRAPS. WHERE THEY CANNOT BE AVOIDED, IT IS SUGGESTED THAT CONDENSATE TRAPS BE INSTALLED.
- 4 5.) USE NºI INSTALLATION FOR TANKS UP TO 10'-6" IN DIAMETER.
  USE Nº2 INSTALLATION FOR TANKS OVER 10'-6" IN DIAMETER AND
  FOR Nº 6 OIL.
- 5 6.) FOR CORROSIVE LIQUIDS, USE STAINLESS STEEL OR PVC PIPING.



HUE 0 /00

# PNEUMERCATOR HYDROSTATIC GAGES

# Instructions for Installation and Adjustment

# Model P-5 Tank Gage

#### 1. OPERATING PRINCIPLE

- 1.1 The Pneumercator Tank Gauge is designed to provide remote indication of the contents of storage tanks containing non-corrosive liquids. Operation of the built-in pump forces air through the connecting tubing until it escapes from the air bell opening located 2" above the bottom of the tank. The hydrostatic head of the liquid above this point determines the air pressure in the system and thus the position of the pointer on the scale.
- 1.2 This gauge should not be used on unvented tanks, for corrosive liquids or on tanks whose diameter and capacity vary from those shown on the dial.
- 1.3 Each time a reading is desired the pump should be operated until all liquid has been purged from the tubing and the pointer returns to the same spot between successive strokes.



- 2.1 Mount the gauge securely on a wall in a location where it will be both visible and accessible.
- 2.2 Lower the air bell through the tank opening until it rests on the bottom. Screw in the reducing bushing and compression fitting taking the slack from the tubing inside the tank before tightening but making sure the air bell remains on the bottom. Run the tubing to the gauge being careful that it does not become distorted or plugged. It is desirable to have the tubing drain from the gauge to the tank, avoiding low spots or pockets where moisture can collect. Buried tubing can be protected by taping it to the underside of the oil suction pipe.
- 2.3 Before tubing is attached to gauge make sure the pointer is exactly on the first mark (empty position) on the dial. If it is necessary to zero the pointer, remove cover from the gauge, slightly loosen the red adjusting screw and tap the mechanism as shown in Fig. 1. Be sure to tighten the red adjusting screw before replacing the cover.





FIG. 1



2.4 Cut off any excess tubing. Install the brass insert into end of tubing, slip first brass nut then sleeve over the tubing as shown in Fig. 2. Insert tubing into fitting on gauge, slide sleeve and brass nut down and fasten tubing securely to gauge.

# 3. TROUBLE SHOOTING

- 3.1 If the pointer oscillates between pump strokes and gradually comes to rest, check for a liquid accumulation in a low pocket of the tubing.
- 3.2 If the pointer remains on "Empty" while the pump is operated, make sure there is liquid in the tank, check for a leaking connection between tubing and gauge, check for damaged tubing and check that the air bell is on the bottom of the tank.
- 3.3 If the tank is partly empty and the pointer remains on "Full" between strokes of the pump, check for an obstruction in the tubing or crushed tubing.
- 3.4 It is possible to localize malfunctions in the tank and transmission assembly or in the gauge by disconnecting the tubing from the gauge. Place the thumb over the tubing connection and operate the pump to observe for normal pointer travel.
- 3.5 If the pointer does not return to "Empty" after the tubing has been disconnected, rezero the gauge by following the procedure described in par. 2.3.
- 3.6 Additional repair or replacement of gauge parts in the field is not recommended. Return the gauge directly to the factory and attach a letter with your name, address and description of the trouble encountered.

#### 4. CAUTION

4.1 Do not use detergents, solvents, paint thinners, lighter fluids or chemical cleaning compounds to clean the gauge.
Use only a damp, soft cloth and a mild soap.

#### **ADJUSTMENT INSTRUCTIONS FOR P-11 AND P-14**


These gages are calibrated and adjusted at the factory specifically for the tanks on which they are to be installed. Actually, no further adjustment should be required but due to minor variations in tank diameter it may be necessary to re-position the pointer to the empty position. This is accomplished as follows:

- Loosen compression nut which secures the tubing to the fitting on top of the gage.
   This vents the system which is necessary before any adjustment is made.
- 2. Remove 4 cover screws and cover.
- 3. The pointer is held to the hub by 2 #1-72 screws. Loosen each crew slightly.
- 4. Re-position the pointer so that the pointer tip is in the center of the large increment representing the empty position.
- 5. Tighten the 1-72 screws and re-check the pointer position.
- 6. Replace cover and compression nut on top of gage.

NOTE: If inaccurate gage readings are observed after the pointer has been re-positioned to the empty mark, the following procedure is suggested:

- (a) Make certain the air bell is on the bottom of the tank.
- (b) Check tank diameter and compare with the tank diameter specified on the purchase order.
- (c) Check specific gravity or grade of fuel oil.

If (b) or (c) is found to show any appreciable difference the gage must be returned to the factory with new information.



# PNEUMERCATOR CO., INC.

120 FINN COURT, FARMINGDALE, N.Y.11735



TOM URAM DIRECTOR

L. REX EHLING, M.D. HEALTH OFFICER

SANTA ANA, CA B2706

TELEPHONE: 714/634-7601

MAILING ADDRESS: P.O. BOX 385 BANTA ANA; CA 92702

PUBLIC HEALTH AND MEDICAL SERVICES
ENVIRONMENTAL HEALTH

Jeb phone. 614)643-1034

APPLICATION FOR: (Check One)

SE .	PERMIT TO OPERATE/INSTALLATION
	FACILITY MODIFICATION

DATE 20 May 1988

FACILITY INFORMATION	TYPE OF CONSTRUCTION
NAME CHET HOUFIELD FEDERAL BUILDING	INDICATE NO. OF TANK(S)
STREET ADDRESS 24000 Avila Rd.	INSTALLATION(S) (COMPLETE PAGE 2)
CITY Laguna Niquel, 92636	REPAIR(S)/RELINE(S)
TOTAL NUMBER OF TANKS (AFTER LOCATION	CLOSURE(S)/REMOVAL(S)
TYPE OF BUSINESS GASOLINE STATION FARM GOVERNMENT OTHER	SYSTEM MODIFICATION (E.G., REPIPE) OTHER (SPECIFY)
DEPTH TO FIRST GROUNDWATER FT.	
TANK OWNER	24 HOUR EMERGENCY CONTACT PERSON
NAME (CORP., INDIVIDUAL, PUBLIC AGENCY)	DAYS
GENERAL GOVERNMENT REGION 9	
STREET ADDRESS 525 Market ST.	NIGHTS TELEPHONE
MAILING ADDRESS 525 Market St.	
CITY San Exaucista	APPL I CANT
STATE CONTRACTOR ZIP 94105	NAME DARLENE R. GREEN
PHONE NO.	10 0
	SIGNATURE Name R. STERRY
FACILITY OPERATOR (CONTACT PERSON)	COMPANY NAME BY L Hydrau le Hoist Co
	PHONE NO. (2/3)630-1669
NAME	
BUSINESS PHONE NO.	
TE: NEW INSTALLATIONS, CLOSURES, REPAIRS AND SYSTEM THE INITIATION OF ANY	STEM MODIFICATIONS OF UNDERGROUND STORAGE PLANS TO THIS DIVISION. THESE PLANS MUST CONSTRUCTION OR MODIFICATION.
OFFICE USE O	ONLY
CILITY PERMIT NO. APPROVAL DATE	
AN CHECK NO. 98-349 FEES: PLAN CHECK 412	09 EMPLOYEE NO.
1190 79256 NR #1	7.99

I.

[	0	N	
			,

	TANK I. D.		#1/	#2	#3	#4
M S FUE	MOTOR VEHICLE	PROPOSED	UNGENDER			
S FUE	CIFY THE	CURRENTLY	NIA			
CAS	NO. (IF TRADE		NIA			
TYPE (	TANK, SUMP, OT	HERS)	TANK			
DOUBLE	WALL/SINGLE W	ALL	DOUBLE WALL			
YEAR M	ANUFACTURED/IN	STALLED	1988			
VAULTE	D/NOT VAULTED		NOT VAULTED			
MAN	UFACTURER		OWENS CORNING			
CAP	ACITY (GALLON)		4,000			
R	STRUCTION MATE	RIAL	Fiberalass			
A THI	CKNESS (UNITS)		3/82	1		
LIN	ING/COATING	R)	NA	0) F.		
MAN	UFACTURER	ž,	DWENS CORNIN	6		
SE CAF	ACITY (GALLON)		4,000			
N CON	STRUCTION MATE	RIAL	FIBERGLASS			
A	CKNESS (UNITS)		3/8"			
LIN	ING/COATING		N/A			
	TERIOR/INTERIO	3476-1-34-1	HYDROSTATIC	•		
	NUFACTURER		QUENS CORNING			
LOCATI	ON (UNDER/ABOV GROUND)	E	GROUND			
	N/PRESSURE		SUCTION			3
	CONSTRUCT		SCH 40 BLACK STEEL			
PRIMA	MANUFACTU	RER	VOSS			·
SECOND	CONSTRUCT	ION	FIBERGLASS			7.000
SECOND	MANUFACTU	RER	A.O. SMITH			9 382
	F LEAK DETECTI	ON	HUNGARIATION	SENSOR	HEREEU - T	ANK GAVEF
ERFILL/	NUFACTURER SPILL CONTAINM	ENT,	POMECO III I	VE Acalar-a-	HERSEY-TA	DALUG (
	N (TYPE) S INSTALLED PR	100	BHILL CON	1 TINOM GW!	OVERFILL	
	SPECIFY THE M					

I. ATTACH A DIAGRAM (8 1/2" X 11") INCLUDE THE LOCATIONS OF THE UNDERGROUND STORAGE TANK(S), PIPING, AUXILIARY EQUIPMENT, BUILDINGS AND OTHER LANDMARKS.

COUNTY OF ORANGE
HEALTH CARE AGENCY
ENVIRONMENTAL HEALTH
WASTE MANAGEMENT SECTION

ACCOUNT NUMBER:

3918

FILE NUMBER

: 996723

DATE: 22 MAR Ø1

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3600

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23784 ALISO CREEK RU LAGUNA NIGUEL, CA 72677

# INVOICE NUMBER: 214081

PAYMENT DUE	BILLING	FROM	TO
23 APR 2001	PERIOD	01 JAN 2001	31 DEC 2001

	UNIT	QUANTITY	AMOUNT
HAZARDOUS WASTE MANAGEMENT PROBRAM FEE	EMP	Ø TO 10	298.00
TIERED PERMIT - ONSITE TREATMENT			9.99
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Tier Permitting Program.			
All fees have been established by the Orange County Poard of Supervisors to recover costs to operate the Programs.			
Retain one copy of this invoice for your records and rethe original with your payment.	eturn		
a late charge of 25% being added to the invoice will after the due date.  3918 HSO 168508 BATCH 11074 04/13/01 INV# 216081 CHECK# 1027 298.00	evoid		

TOTAL DUE

298.00

COUNTY OF ORANGE
HEALTH CARE AGENCY
ENVIRONMENTAL HEALTH
MASTE MANAGEMENT SECTION

ACCOUNT NUMBER:

3918

FILE NUMBER

: 98672

DATE: 29 JUN 8

BILL TO:

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3696

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 197612

PAYMENT	DUE	BILLING	FRON	то
31 JUL	2658	PERIOD	91 JAN 2005	31 DEC 2966

	UNIT	GUANTITY	AMOUN	NEW T
HAZARDOUS MASTE MANAGEMENT PROGRAM FEE	EMP	# TO 1	8 29	8.99
TIERED PERMIT - ONSITE TREATMENT				5. 55
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Tier Permitting Program.				
All fees have been established by the Orange County Board of Supervisors to recover costs to operate the Programs.				
Retain one copy of this invoice for your records and r the original with your payment.	eturn			
****PLEASE NOTE: Timely payment of this invoice will a late charge of 25% being added to the invoice 32 day after the due date. We recommend that disputes be resor payment made prior to that date to avoid the late f	s olved			

3918 HSO 163311 BATCH 9263 07/12/00 INV# 197612 CHECK# 7051 298.00

TOTAL DUE

298.46

COUNTY OF ORANGE HEALTH CARE AGENCY ENVIRONMENTAL HEALTH WASTE MANAGEMENT SECTION

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3696

ACCOUNT NUMBER:

3918

FILE NUMBER : 006723

21 JAN 99

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL: CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL CA 92677

INVOICE NUMBER: 173190

PAYMENT DUE	BILLING	FROM	TO
22 FEB 1999	PERIOD	Ø1 JAN 1999	31 DEC 1999

	UNIT	QUANTITY	AMOUNT
HAZARDOUS WASTE HEALTH SERVICES FEE	EMP	Ø TO 18	231,00
HAZARDOUS MATERIALS PROGRAM OFFICE FEE	EMP	Ø TO 10	61.30
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Hazardous Materials Program Office.			
All fees have been established by the Orange County Bos of Supervisors to recover costs to operate the Programs			
Retain one copy of this invoice for your records and re the original with your payment.	turn		
****PLEASE NOTE: Timely payment of this invoice will a late charge of 25% being added to the invoice 32 days after the due date. We recommend that disputes be resoned payment made prior to that date to avoid the late fe	lved		
3918 HSO 155218 BATCH 7332 02/10/99 INV# 173190 CHECK# 6159 292.00			

TOTAL DUE

292.00

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3696

ACCOUNT NUMBER: 30 +999+3918

FILE NUMBER : 6723

DATE: 14 DEC 98

BILL TO:

VILLAGE I HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677-3908

INVOICE NUMBER: 170484

PAYMENT DUE	BILLING	FROM	TO
15 JAN 1999	PERIOD	01 JAN 1998	31 DEC 1998

	UNIT	QUARTITY	AMOLINT
TATE SERVICE CHARGE ASSESSMENT	10.00	FLAT FEE	
ase Fee	19.92	FLAI FEE	19.99
This State service charge is assessed to industries whi generate or handle hazardous materials and/or hazardous wastes. The service charge supports State activities to ensure consistent and effective statewide implementation of the Unified Program. Please refer to the enclosed letter and fact sheet which will further explain the functions of the Unified Program and the service charge of the unified Program and the unified Program an	o n		
Please retain one copy of this invoice for your records return the original with your payment.	and		
***NON-PAYMENT OF FEES MAY CONSTITUTE REVOCATION OF PER	MITS***		

0*999*3918 SO 154758 BATCH 7149 1/15/99 INV# 170484 HECK# 6124 10 00

TOTAL DUE

COUNTY OF ORANGE
HEALTH CARE AGENCY
ENVIRONMENTAL HEALTH
WASTE MANAGEMENT SECTION

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3600

FILE NUMBER: 3918

DATE: 26 JAN 98

BILL TO:

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 151896

PAYMENT DUE	BILLING	FROM	то
27 FEB 1998	PERIOD	#1 JAN 1998	31 DEC 1998

	UNIT	QUANTITY	AMOUNT	
HAZARDOUS WASTE HEALTH SERVICES FEE	EIP	5 TO 15	231.00	
HAZARDOUS MATERIALS PROGRAM OFFICE FEE	EMP	S TO 18	61.00	
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Hazardous Materials Program Office.				
All fees have been established by the Orange County Boar of Supervisors to recover costs to operate the Programs.				
Retain one copy of this invoice for your records and ret the original with your payment.	turn			
a late charge of 25% being added to the invoice will as a late charge of 25% being added to the invoice 32 days after the due date. We recommend that disputes be resoluted or payment made prior to that date to avoid the late feet	ved			

3918 HSO 148795 BATCH 5692 02/25/98 INV# 151896 CHECK# 5823 292.00

TOTAL DUE

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3600

ACCUINT NUMBER: 38+999*3918

FILE NUMBER : 906723

DATE: Ø3 NOV 97

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL CA 92677-3908 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677-3908

INVOICE NUMBER: 147400

PAYMENT DUE	BILLING	FROM	то
Ø5 DEC 1997	PERIOD	Ø1 JAN 1997	31 DEC 1997

	UNIT	QUANTITY	AMOUNT
STATE SERVICE CHARGE ASSESSMENT			
Base Fee	18.50	FLAT FEE	18.50
This Fiscal Year 1996/97 State service charge is assess to industries which generate or handle hazardous materiand/or hazardous wastes. The service charge supports Sactivities to ensure consistent and effective statewide implementation of the Unified Program. Please refer to enclosed letter and fact sheet which will further explathe functions of the Unified Program and the service ch	als tate the in		
If there has been a change in ownership, please return invoice with the new owner's name and mailing address.	this		
Please retain one copy of this invoice for your records return the original with your payment.	and		
***NON-PAYMENT OF FEES MAY CONSTITUTE REVOCATION OF PER	MITS***		

30*999*3918 HSD 147298 BATCH 5207 12/01/97 INV# 147400 CHECK# 5722 18.50

TOTAL DUE 18.50

2009 E. EDINGER SANTA ANA. CA 92705 (714)667-3700

COUNT NUMBER:

3918

FILE NUMBER

: 006723

DATE: 02 JAN 97

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL: CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 130549

PAYMENT DUE	BILLING	FROM	ТО
Ø3 FEB 1997	PERIOD	Ø1 JAN 1997	31 DEC 1997

	UNIT	QUANTITY	AMOUNT
HAZARDOUS WASTE HEALTH SERVICES FEE	EMP	Ø TO 10	231.00
HAZAROOUS MATERIALS PROGRAM OFFICE FEE	EMP	Ø TO 10	61.00
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Hazardous materials Program Office.			
All fees have been established by the Orange County Boar of Supervisors to recover costs to operate the Programs	rd •		
Retain one copy of this invoice for your records and re the original with your payment.	turn		
****PLEASE NOTE: Timely payment of this invoice will a a late charge of 25% being added to the invoice 32 days after the due date. We recommend that disputes be reso or payment made prior to that date to avoid the late fe	lved		
a Eleka			

JAN 2 4 1997 L BATCH # 14/599

TOTAL DUE

COUNTY OF CHANGE ENVIRONMENTAL HEALTH WASTE MANAGEMENT SECTION

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3700

CCOUNT NUMBER:

FILE NUMBER

0067

391

DATE: Ø4 JAN 96

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

BILL TO:

INVOICE NUMBER: 122227

PAYMENT DUE	BILLING	FROM	ТО
Ø5 FEB 1996	PERIOD	Ø1 JAN 1996	31 DEC 1996

	UNIT	QUANTITY	AMOUNT
AZARDOUS WASTE HEALTH SERVICES FEE	EMP	1 TO 10	231.0
AZARDOUS MATERIALS PROGRAM OFFICE FEE	EMP	1 TO 10	61.9
Please refer to the enclosed letter which will explain the functions of the Hazardous Waste Program and the Hazardous Materials Program Office.			
All fees have been established by the Orange County Board of Supervisors to recover costs to operate the Programs.			
Retain one copy for your records and return original with payment.			N.
*****PLEASE NOTE: Timely payment of this invoice will a a late charge of 25% being added to the invoice 32 days after the due date. We recommend that disputes be reso or payment made prior to that date to avoid the late fe	lved		996
	1	H# 13600 CX 191	ah

TOTAL DUE

#### ange County Health Care Agericy Environmental Health Division 2009 E. Edinger, Santa Ana, CA 92705 Telephone (714) 667-3700

### PRELIMINARY INVESTIGATION REQUEST

Account No. 33/8 File No. 00 6723	Active: Yes No	IR#TI# 95 IL 265  Received By: 10 10  Date Received: 10 - 1-95
Requested By: OCFD	MARICO MACK Name	
Street Address		G+475611
City  Regarding: VILLALE IHR  Company Name/Location	Zip CLERNSES HE	Phone Number  ward Yang
24022 A2150 C	CLEEK	
Street Address  CA (VNA N) (NEL  City	92677 Zip	VNX Phone Number
Nearest Cross Streets: ALISO CA		95-1-6./ Map Coordinates
IN BOLK ALLEYWAY RELE	SINT 1-2 GALLONS O	TRE SCUDIE TIPPED OVER OF WASTERIEC SCUDIE TO THE UP WITH ABSORPET. SOCIOIFIED
(REPSE TO 95EI 126 PO	R ET DETRILS)	
Date Staff	A	ctivities/Comments  1 from . K. Baitx . Called
	ill be picked	
		that Mr. Yang has heart problem
11-6-95 Spoke to Mr. Ya	ang who explain	ged that the waste hodboo
onsite His da	te. No violation	snoted Caseclosed

**Use Blank Attachments if Needed**

BILL TO:

VILLAGE 1 HOUR CLEANERS

LAGUNA NIGUEL, CA 92677

23984 ALISO CREEK RD

2009 E. EDINGER SANTA ANA, CA 92705 (714)667-3700

ACCOUNT NUMBER:

3918

FILE NUMBER :

006723

DATE: 13 JAN 95

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 113847

PAYMENT DUE	BILLING	FROM	ТО
14 FEB 95	PERIOD	Ø1 JAN 95	31 DEC 95

	UNIT	QUANTITY	AMOUNT
HAZARDOUS WASTE HEALTH SERVICES FEE	EMP	Ø TO 1Ø	231.00
HAZARDOUS MATERIALS PROGRAM OFFICE FEE	EMP	Ø TO 1Ø	61.00
Effective January, 1995 the Hazardous Materials Program Office will be transferred from the County Fire Department to the County Health Care Agency. In an effort to reductosts, the fees are now consolidated into one invoice. Please refer to the enclosed letter which will explain the functions of the two programs.	e		
All fees have been established by the Orange County Boar of Supervisors to recover costs to operate the Programs.	d 		
Retain one copy of this invoice for your records and ret the original with your payment.	urn		
****PLEASE NOTE: Timely payment of this invoice will avoid a late charge of 25% being added to the invoice 32 days after the due date. We recommend that disputes be resolved payment made prior to that date to avoid the late fee	ved	FEB 2 4 19 H# _/30 K#	95 770 L. 4
	48:	52	

TOTAL DUE

# in # COUNTY OF ORANGE FIRE DEPARTMENT HAZARDOUS MATERIALS PROGRAM OFFICE 2009 E. EDINGER SANTA ANA, CA 92705 (714)289-7430 BILL TO:

CCOUNT NUMBER: 3918 FILE NUMBER : 006723 DATE: 04 JAN 94

COMPANY ADDRESS!

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 104590

PAYMENT DUE	BILLING	FROM	TO
Ø5 FEB 94	PERIOD	Ø1 JAN 94	31 DEC 94

This is your Hazardous Waste Management Fee for calendar year 1994. The fee, which was authorized by the Board of Supervisors per resolution 92-676 per Health and Safety Code Section 510, has been assessed to industries which generate hazardous	Ø TO 1Ø	61.00
calendar year 1994. The fee, which was authorized by the Board of Supervisors per resolution 92-676 per Health and Safety Code Section 510, has been assessed to industries which generate hazardous		
waste.	同風	ME
Retain one copy for your records and return original with payment.	JAN 2 7 BATCH # 2	1994
***NOTE: A late charge of 25% will be added if not paid by the due date***	CHECK #1406	.INTL. A

51,00 TOTAL DUE

		the state		
COUNTY OF ORANGE HEALTH CARE AGENCY ENVIRONMENTAL HEALTH WASTE MANAGEMENT SEC	FION		FILE NO	
2009 E. EDINGER SAN	ALTH CARE AGENCY VIRONMENTAL HEALTH STE MANAGEMENT SECTION  ### PROPERTY OF THE PROPERTY OF TH			DATE: 04 JAN 94
BILL	ro:		COMPA	NY ADDRESS:
23984 ALIS	VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677  INVOICE NUMBER: 98358  AVMENT DUE  BILLING FROM  D5 FEB 94  PERIOD  Ø1 JAN 94  TH SERVICES FEE  S is your Health Services Fee for the Hazardous the Program for calendar year 1994. The fee is essed to industries which generate hazardous waste Program and the fees were authorized by the Orange of Program and the fees were authorized by the Orange of Supervisors to regulate the storage of disposal of hazardous waste.		VILLAGE 1 HOU 23784 ALISO C LAGUNA NIGUEL	CREEK RI
Ŀ			L	CONTRACTOR
	INVOI	CE NUMBER: 98358		
PAYMENT DUE	BILLING	FROM		
Ø5 FEB 94	PERIOD	Ø1 JAN 94	31 DB	EC 94
			UNIT GUANT	ILA MODELL
This is your Health Ser Waste Program for caler assessed to industries The Program and the fer County Board of Superv and disposal of hazards Retain one copy for your with your payment.	ndar year 19 which gener es were auth isors to reg ous waste. ur records a	94. The fee is ate hazardous waste. orized by the Orange is ulate the storage and return original	BATCH :	JAN 2 7 1994 D # 2281 #1406 INTL. 07

COUNTY OF ORANGE	30000	Part De la Contraction de la C	ACCOUNT N	NUMBER:	3918
HAZARDONS MATERIALS PROGRAM OFFICE			FILE	NUMBER	: 995723
2009 E. EDINGER SA	NTA ANA, CA 927	Ø2 (714)667 <b>-37</b> ØØ		DA	TE: 28 DEC
BILL	TO:		CON	PANY ADDI	RE55:
23984 ALI	PAYMENT DUE  BILLING  PROM  PERIOD  Ø1 JAN 93  ARDOUS WASTE MANAGEMENT FEE  is is your Hazardous Waste Management Fee for lendar year 1993. The fee, which was authorized the Board of Supervisors per resolution 92-676 Health and Safety Code Section 510, has been sessed to industries which generate hazardous			HOUR CLEA SO CREEK B GUEL, CA	RD
L			L		
	INVOICE	NUMBER: 887Ø1			
PAYMENT DUE				ТО	
29 JAN 93	FIRE DEPARTMENT HAZARDOUS PATERIALS PROGRAM OFFICE  2007 E. EDINGER SANTA ANA. CA 92702 (714)667-3706  BILL TO:  VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677  INVOICE NUMBER: 88701  PAYMENT DUE  BILLING FROM 29 JAN 93 PERIOD  01 JAN 93  ARDOUS WASTE MANAGEMENT FEE  is is your Hazardous Waste Management Fee for lendar year 1993. The fee, which was authorized the Board of Supervisors per resolution 92-676 r Health and Safety Code Section 510, has been sessed to industries which generate hazardous ste.  late charge of 25% will be added if not paid by e date.  tain one copy for your records and return original	Ø1 JAN 93	31	DEC 93	
			UNIT GUA	MILITA	AMOUNT
calendar year 1993. by the Board of Supers per Health and Safety assessed to industries waste.  A late charge of 25% a due date.	The fee, which wisors per resormed Section 5: which generate will be added in	was authorized lution 92-676 10, has been e hazardous f not paid by	FEB BATCH # _ CHECK # _	22 1993 2548 NTL	
			395°	DE	51-00

			1-10-		
COUNTY OF ORANGE HEALTH CARE AGENCY ENVIRONMENTAL HEALT			1	NT NUMBER:	3718
WASTE MANAGEMENT SE	CTION				
2009 E. EDINGER SA	NTA ANA, CA 927	02 (714)667-3700		DAT	E: 28 DEC 9
BILL	TO:			COMPANY ADDR	ESS:
23984 ALI	29 JAN 93  PERIOD  Ø1 JAN 93  LTH SERVICES FEE  is is your Health Services Fee for the Hazardous ste Program for calendar year 1993. The fee is sessed to industries which generate hazardous was e Program and the fees were authorized by the Oraunty Board of Supervisors to regulate the storage d disposal of hazardous wastes.  late charge of 25% will be added if not paid by d tain one copy for your records and return origina			E 1 HOUR CLEA ALISO CREEK R NIGUEL, CA	ND .
L			L		
	INVOICE	NUMBER: 82561			
PAYMENT DUE	BILLING	FROM		10	
29 JAN 93	PERIOD	Ø1 JAN 93		31 DEC 93	
			UNIT	QUANTITY	AMOUNT
HEALTH SERVICES FEE			EMP	Ø TO 10	231.00
assessed to industrie The Program and the f County Board of Super and disposal of hazar  A late charge of 25%	s which generatees were author visors to regul dous wastes.	e hazardous waste. ized by the Orange ate the storage  f not paid by due da	BA	FEB 2 2 19: TCH # 2548 ECK #INTI	3 93 1. V
			13	955	
			1011	AL DUE	231.00

COUNTY OF OI NGE
HEALTH CARE AGENCY
ENVIRONMENTAL HEALTH
WASTE MANAGEMENT SECTION
P.O. BOX 355 SANTA ANA, CA, 92702 (714)834-8174

ACCOUNT NUMBER: 3918

DATE:

Ø1 APR 89

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS
23984 ALISO CREEK RD
LAGUNA NIGUEL, CA 92677


INVOICE NUMBER: 20841

PAYMENT DUE	BILLING	FROM	то
Ø3 MAY 89	PERIOD	Ø1 JAN 89	31 DEC 89

HEALTH SERVICES FEE	UNIT	QUANTITY	AMOUNT	
HAZARDOUS WASTE	EMP	Ø TO 10	179	,00
This is your Health Services fee for the Hazardous Wast calendar year 1989. The fee is assessed to industries hazardous waste. The Program and the fees were authori Orange County Board of Supervisors to regulate the stor of hazardous wastes.	which gener zed by the	rate		
A late charge of 25% will be added if not paid by date	due.		.1	
Retain one copy for your records and return original wi	BATCH CHECK	MAY 0 9 198		
	A			

TOTAL DUE

179



P.O. BOX 355 SANTA ANA, CA 92702 (714) 667-3700

CCOUNT NUMBER:

3918

FILE NUMBER : 00672

DATE: 27 DEC 91

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL: CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 68421

PAYMENT DUE	BILLING	FROM	T0
28 JAN 92	PERIOD	Ø1 JAN 92	31 DEC 92

		Ц.	
	UNIT	GLANTITY	AMOUNT
HEALTH SERVICES FEE	EMP	Ø TO 1Ø	231 00
	ille control		
This is your Health Services Fee for the Hazardous	100		
Waste Program for calendar year 1992. The fee is assessed to industries which generate hazardous waste.			
The Program and the fees were authorized by the Orange County Board of Supervisors to regulate the storage	D.		
and disposal of hazardous wastes.	N. Carlot		140
	1	and the second	
Retain one copy for your records and return original with payment.	0 0		
A late charge of 25% will be added if not paid by	A. I	500 to	2 ~
due date.	10	1300	S TIM
		JAN 3 0 1992	
	RATCH	1950	
	CHECK		1
		3494	THE PARTY

TOTAL DUE

P.O. BOX 355 SANTA ANA, CA 92702 (714) 667-3700

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 CCOUNT NUMBER:

3918

006723

DATE:

07 JAN 91

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 49692

PAYMENT DUE	BILLING	FROM	ТО
Ø8 FEB 91	PERIOD	Ø1 JAN 91	31 DEC 91

HEALTH SERVICES FEE	UNIT	QUANTITY	AMOUNT	
	EMP	Ø TO 1Ø	221	. 90
This is your Health Services fee for the Hazardous Waste Program for calendar year 1991. The fee is assessed to industries which generate hazardous waste. The Program and the fees were authorized by the Orange County Board of Supervisors to regulate the storage and disposal of hazardous wastes.				
A late charge of 25% will be added if not paid by due date.	50	) AS	575	
Retain one copy for your records and return original with payment.	The second second second	JAN 29 # 1480	1991	
	CHECK 3	089	1 40	

TOTAL DUE

COUNTY OF OI NGE HEALTH CARE GENCY			ACCOUNT NO.		3918
ENVIRONMEN WASTE MAN	MTI HI	EALTH			
P.O. BOX 355 SANTA				DATE	14 JAN 87
BILL	TO:		COMPANY	ADDRESS:	
VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK LAGUNA NIGUEL, CA 92677		VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK LAGUNA NIGUEL, CA 92677			
L			L		
#00673	?? INVO	DICE NUMBER 2197			
PAYMENT DUE	BILLING	FROM	TO		
15 FEB 87	PERIOD	15 JAN 87	14	JAN 88	
HEALTH SEI	RVICES	FEE	UNIT QUA	ANITY A	TOUNT
		dded if not paid by date ds and return original w	CHECKH 2	3 0 1987 242-40 24CASH 2	
<< <make ci<="" th=""><th>-IECKS I</th><th>PAYABLE TO OR</th><th>TOTAL ANGE COUNTY HE</th><th></th><th>159.00 AGENCY&gt;&gt;&gt;</th></make>	-IECKS I	PAYABLE TO OR	TOTAL ANGE COUNTY HE		159.00 AGENCY>>>

#### COUNTY OF OR FIRE DEPARTM HAZARDOUS MATERIALS PROGRAM OFFICE

P.O. BOX 355 SANTA ANA, CA 92702 (714) 744-0543

ACCOUNT NUMBER:

006723

3918

DATE: 07 JAN 91

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 59699

PAYMENT DUE	BILLING	FROM	то
Ø8 FEB 91	PERIOD	Ø1 JAN 91	31 DEC 91

Ø8 FEB 91 PERIOD DI SHIN 71		
AZARDOUS WASTE MANAGEMENT FE	E UNIT QUANTIT	AMOUNT
	EMP Ø TO 10	46.0
This is your Hazardous Waste Management fee for calendar year 1991. The fee, which was authorized by the Board of Supervisors per resolution 90-1529 per Health and Safety Code Section 510, has been assessed to industries which generate hazardous waste.		
A late charge of 25% will be added if not paid by due date.		
Retain one copy of your records and return original with payment.	JAN 29 BATCH # 1/80	1891
	CHECK #II	il. A

TOTAL DUE

# COUNTY OF COMMENTAL HEALTH WASTE MANAGEMENT SECTION

P.O. BOX 355 SANTA ANA,CA, 92702 (714)834-8175

ACCOUNT NO. 3918

05 FEB 88

COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

BILL TO:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER

13005

PAYMENT DUE	BILLING	FROM	TO
Ø8 MAR 88	PERIOD	Ø1 JAN 88	- 31 DEC 88

HEALTH SERVICES FEE	UNIT	QUANTITY	AMOUNT	
HAZARDOUS WASTE PROGRAM	EMP	Ø TO 5	165;	00
This is your Health Services fee for the Hazardous Was calendar year 1988. The fee is assessed to industries hazardous waste. The Program and the fees were author Orange County Board of Supervisors to regulate the stoof hazardous wastes.	which gen ized by th	erate e		
A late charge of 25% will be added if not paid by date	due,			
Retain one copy for your records and return original w	ith paymen			
S A R				



TOTAL DUE

165,00

## COUNTY OF ORANGE HAZARDOUS MATERIALS PROGRAM OFFICE AUDITOR CONTROLLER P.O. BOX 355, SANTA ANA, CA. 92702

COUNT NUMBER:

3918

DATE:

Ø1 APR 89

BILL TO;


VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677 COMPANY ADDRESS:

VILLAGE 1 HOUR CLEANERS 23984 ALISO CREEK RD LAGUNA NIGUEL, CA 92677

INVOICE NUMBER: 25575

PAYMENT DUE	BILLING	FROM	то
#3 MAY 89	PERIOD	Ø1 JAN 89	31 DEC 89

PRANCE COUNTY FIRE DEPARTMENT	UNIT	QUANTITY	AMOUNT	
HAZARDOUS WASTE MANAGEMENT FEE	EMP	Ø TO 1Ø	37.	00
This is your Hazardous Waste Management fee for calendar year 1989. The fee, which was authorized by the Board of Supervisors per Resolution 89-322 per Health and Safety Code Section 510, has been assessed to industries which generate hazardous waste.				
If you have any questions regarding this fee please contact the Hazardous Materials Program Office at (714) 744-0543.				
A late charge of 25% will be added if not paid by due date.				
Retain one copy of your records and return original with payment.				



TOTAL DUE

37,00

