

## **GM Product Emission Recall Bulletin:**

**Date: September, 2003**

Subject: 03048 – OBDII Misfire Monitor

Models: 2004 Chevrolet Malibu with 3.5L V6 (RPO LX9 – VIN Code 8) engine.

Vehicles affected fall within the following VIN breakpoints:

**4F100567 thru 4F104624**

A condition exists that incorrectly disables the On-Board Diagnostics (OBD) misfire monitor above 35 MPH.

Operators of these vehicles should contact the nearest GM Dealer to see if their particular vehicle is involved in this recall.