

Possible problem with Ford Triton V8 and V10 engines

- Reports from our field offices were sufficient enough to warrant an investigation into how many Ford Triton V8 and V10 engines suffered cylinder head and other major component failures. After reviewing applicable data, it is GSA's determination that there is not an unusual failure rate with these engines.

- If, at such time, an increased failure rate is reported and investigation confirms so, we will take the appropriate actions.