

November 28, 2022

Diane Czarnecki Industrial Hygienist Facilities Management Division GSA Public Buildings Service – Heartland Region 2300 Main Street Kansas City, MO 64108

Re: Goodfellow Federal Center – Building 107 Air and Wipe Sampling Evaluation Addendum Project No. 121244

Dear Ms. Czarnecki:

Thank you for the opportunity to provide the General Services Administration (GSA) with the above referenced environmental sampling activities. The following is our report.

INTRODUCTION

As requested, Burns & McDonnell conducted area air sampling and wipe sampling for the presence of seven (7) RCRA metals including arsenic, barium, cadmium, chromium, lead, selenium, and silver within the occupied areas of the first floor of building 107 of the Goodfellow Federal Center located at 4300 Goodfellow Boulevard in St. Louis, Missouri. The purpose of the investigation was to provide ongoing sampling data to monitor conditions at the site. This report serves as an addendum to the *Goodfellow Federal Center – Building 107 Air and Wipe Sampling Evaluation*, dated December 27, 2021.

SAMPLING METHODOLOGY

Dust wipe sampling was conducted in accordance with ASTM Standard E1728: Standard Practice for Collection of Settled Dust Samples Using Wipe Sampling Methods for Subsequent Lead Determination and ASTM Standard D6966: Standard Practice for Collection of Settled Dust Samples Using Wipe Sampling Methods for Subsequent Determination of Metals. ASTM Standards E1728 and D6966 are consistent with the methodology described in the Housing and Urban Development Guidelines-Appendix 13.1 and 40 CFR 745.63. The Brookhaven National Laboratory's Surface Wipe Sampling Procedure (IH75190) was also used as a guideline.

A representative surface area of approximately one square foot (1 SF) was measured and delineated. The dust wipe samples were collected using dedicated dust wipe cloths meeting ASTM E1792 Standard. Each dust wipe cloth was pre-moistened and individually wrapped. Each sample was collected by wiping in a back and forth "S" pattern over a measured sampling area using a clean, disposable glove. Then, the wipe was folded over itself and the area was wiped again in a direction perpendicular to the first wipe orientation. Then, the wipe folded over itself again and the area was wiped around the perimeter. The wipe sample was then placed into a labeled, clean container.



Diane Czarnecki Facilities Management Division November 28, 2022 Page 2

Air samples for RCRA metals were collected on 37-millimeter (mm) cassettes with 0.8 micrometer (µm) mixed cellulose ester (MCE) filters, using powered air sampling pumps, in accordance with the National Institute for Occupational Safety and Health (NIOSH) Method 7300. The sampling strategy included collecting a minimum sample volume of 500 liters based on the calibrated pump flow rate and sample duration.

All samples were submitted under chain-of-custody to Environmental Hazards Services, LLC (EHS) in Richmond, Virginia for independent analysis of 7 RCRA metals. Air samples were analyzed by Inductively Coupled Plasma (ICP) according to NIOSH method 7300. Wipe samples were analyzed according to Environmental Protection Agency (EPA) method SW846-3050B/6010D. EHS is accredited under the American Industrial Hygiene Association (AIHA) Industrial Hygiene Laboratory Accreditation Program (IHLAP) program, identification number LAP-100420.

SAMPLE SUMMARY AND RESULTS

Air and wipe samples were collected on November 16, 2022, by Abiodun Akinola of Burns & McDonnell.

One (1) air sample was collected from the first floor of building 107, from the small alcove next to the kitchen and field office. All analytes were below laboratory reporting limits. The complete air sampling laboratory report from EHS is included in Appendix A.

One (1) wipe sample was collected on November 16, 2022. The sample location and results are listed below. The complete wipe sampling laboratory report from EHS is included in Appendix B.

- 1st floor, top of table in the small alcove next to the kitchen and field office
 - Arsenic, cadmium, chromium, lead, selenium, and silver were all below laboratory reporting limits
 - O Barium was detected at 0.82 μg/sq. ft, below the clean area limit of 3,094 μg/sq. ft

LIMITATIONS

The scope of this assessment was limited in nature. Burns & McDonnell collected samples from a representative number of surfaces in an effort to minimize cost while providing a general overview of site conditions. Sample locations do not encompass all surfaces at the site. Additionally, samples were only analyzed for a select number of potential contaminants. Burns & McDonnell is not responsible for potential contaminants not identified in this report.



Diane Czarnecki Facilities Management Division November 28, 2022 Page 3

Burns & McDonnell appreciates the opportunity to work for GSA on this project. Please contact us if you have any questions regarding this report or if we may be of any additional service.

Sincerely,



Matt Shanahan, CHMM Project Manager

Attachments:

Appendix A – Air Sampling Laboratory Report Appendix B – Wipe Sampling Laboratory Report

Information in Appendices A and B are not accessible for people using screen reader technology. If this information is required, it can be furnished upon request by contacting 816-223-6198 or r6environmental@gsa.gov.





Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237

Telephone: 800.347.4010

Air Metals Analysis Report

Client: Burns & McDonnell Engineering

9400 Ward Pkwy.

Kansas City, MÓ 64114

Report Number: 22-11-03020

Received Date:

11/17/2022

Reported Date: 11/22/2022

Project/Test Address: 168765; GFC / 4300 Goodfellow Blvd

Client Number: 26-3514 Laboratory Results

Fax Number: 816-822-3494

Lab Sample Number	Client Sample Number	Analyzed Date	Analyte	Air Volume (L)	Total Metal (ug)	Concentration (ug/m³)	Narrative ID
22-11-03020-001	107-A-01	11/18/2022	Arsenic (As)	578	<0.15	<0.26	
			Barium (Ba)		<0.15	<0.26	
			Cadmium (Cd)		<0.030	<0.052	
			Chromium (Cr)		<0.75	<1.3	
			Lead (Pb)		<0.15	<0.26	
			Selenium (Se)		<0.75	<1.3	
			Silver (Ag)		<0.15	<0.26	
22-11-03020-002	107-A-02	11/18/2022	Arsenic (As)		<0.15		
			Barium (Ba)		<0.15		
			Cadmium (Cd)		<0.030		
			Chromium (Cr)		<0.75		
			Lead (Pb)		<0.15		
			Selenium (Se)		<0.75		
			Silver (Ag)		<0.15		

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 22-11-03020

Project/Test Address: 168765; GFC / 4300 Goodfellow Blvd

Lab Sample Client Sample Analyzed Analyte Air Total Metal Concentration Narrative Number Date Volume (L) (ug) (ug/m³) ID

Sample Narratives:

Method: NIOSH 7300M Analyst: Carlos Gonzalez

(b) (6)

Reviewed By Authorized Signatory:

Tasha Eaddy QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contains less than the reporting limit for each particular metal, based on a 15mL volume. The reporting limit is 0.03ug for Cadmium, 0.15ug for Arsenic, Barium, Lead and Silver, and 0.75ug for Chromium and Selenium.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Unless otherwise noted, samples are reported without a dry weight correction. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. NY ELAP #11714.

LEGEND ug = microgram ug/m³ = micrograms per cubic meter
mL = milliliter L= Liters

ENVIRONMENTAL HAZARDS SERVICES, LLC

		Metals Ch	ain of C	ustody Fo	orm			Pg_	oi	d	
Company Name	- 				Account #	26-3					
Company Address Phone				City	y/State/Zip			y, MO			
	esting Address ⁻ G l		ndfellow Blvc	-4	` Email	eapu	denerg	@burns	imca.i	COITI	
PO Number		101700000		ected By							
Turn-Around Time		1 3 DAY	2 DAY	1 DAY	CANAL	FRAVE	~ M \ \ \ T C C	PERID A	A	- II ah-	
	J DAT	3 UMT	CUAT	4 UAT	SHIVIE	DAYO	ik vveer	KEND - N	/lust ca	ill Anec	ed .
		META	LS		PARTICULA	ATES		AIR		WIPE	ES
g Client Sample 10	Collection Date & Time	Pla TCLP TCLP RCKA 8 RCKA 8 Total RCKA 8 Total	Wething Sume Profile TX_11TCLP CA_17_Total	Other Metals	Total Nucsance Dust Respicable Dust TSP Gravimetric	TSP Pty PW- 10	4	Frew Pate	A CONTRACTOR OF THE PARTY OF TH	ARE Shipe Shy Watsi shriy	FA current of and other
					Total N Resp TSP (F	M-7.5		18813	in ∪	ra
107-A-01 107-A-02	11/16/22 8:55		APL	g. As. Ba. Cd. Cr.			225	2.57	578	× ×	VA
107-W-01 107-W-02	11/16/22 GAM								The state of the s	12°.	12°
					A CONTRACTOR OF THE CONTRACTOR	A contract of the contract of			A. and appropriate memory and a	- 8	ŧ
•					and of Charles and	The state of the s	Control organization manuscriptors. Titles	÷ · · · ·	And (page and person)	, x	
*							The second secon		- ANALYSIS MICHIGAN	The second secon	΄ Κ
							4			5	×
						-				S. Carlotte and Ca	X.
Released By: Signature:	Abiodum (b) (6)	Aknofe	LAB USE ONLY - 8	Date: 11/1	16/22	The second secon	Time	A control and			*
Received By	Marker				matrolefrinahassinster	27	2-11-0	3020			
(b) (6)	VVVVIV.	Translation translation control of the control of t									
Signature:			7. I	/ ·	***************************************		ue Dat		# 11 #61 # m11 b m	A) 	
Date:	tida Time:	2 3	<u> 54</u> 0	AM PM			/28/2 (Monda				
Portal Contact	. Added						EL	137 Mariana Mariana	MM-	-L	
an area make the selection of the select	INE RD, RICHMOND		00)-347-4010								The state of the s





Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237

Telephone: 800.347.4010

9400 Ward Pkwy. Kansas City, MO 64114

Wipe Metals **Analysis Report**

Report Number: 22-11-03024

Received Date: 11/17/2022 Analyzed Date: 11/18/2022 Reported Date: 11/22/2022

Project/Test Address: 168765; GFC / 4300 Goodfellow Blvd

Burns & McDonnell Engineering

Client Number:

Client:

Fax Number: **Laboratory Results** 816-822-3494 26-3514

Lab Sample Number	Client Sample Number	Analyte:	Wipe Area (ft²)	Total Metal (ug)	Concentration (ug/ft²)	Narrative ID
22-11-03024-001	107-W-01	Arsenic (As)	1.00	<2.50	<2.5	
		Barium (Ba)	1.00	0.815	0.82	
		Cadmium (Cd)	1.00	<0.100	<0.10	
		Chromium (Cr)	1.00	<1.00	<1.0	
		Lead (Pb)	1.00	<0.500	<0.50	
		Selenium (Se)	1.00	<2.50	<2.5	
		Silver (Ag)	1.00	<0.500	<0.50	
22-11-03024-002	107-W-02	Arsenic (As)		<2.50		
		Barium (Ba)		<0.500		
		Cadmium (Cd)		<0.100		
		Chromium (Cr)		<1.00		

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 22-11-03024

Project/Test Address: 168765; GFC / 4300 Goodfellow Blvd

	Concentration (ug/ft²)	Total Metal (ug)	Wipe Area (ft²)	Analyte:	Client Sample Number	Lab Sample Number
		<0.500		Lead (Pb)		
		<2.50		Selenium (Se)		
		<0.500		Silver (Ag)		
		<0.500		Silver (Ag)	ives:	Sample Narrat

Analyst: Carlos Gonzalez

Method: Mercury (Hg): EPA SW846 7471B

All other metals: EPA SW846 3050B/6010D

(b) (6)

Reviewed By Authorized Signatory:

Tasha Eaddy QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contains less than the reporting limit for each particular metal, based on a 50mL volume. The reporting limit for Cadmium is 0.10ug, Barium, Lead and Silver are 0.50ug, Arsenic and Chromium are 1.0ug, and Selenium is 2.5ug.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Unless otherwise noted, samples are reported without a dry weight correction. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. NY ELAP #11714.

Legend ug = microgram $ug/ft^2 = micrograms$ per square foot mL = milliliter $ft^2 = square$ foot

ENVIRONMENTAL HAZARDS SERVICES, LLC

Company Address Phone	Burns & McDe 9400 Ward P 314-302-466	arkway 1		· · · · · · · · · · · · · · · · · · ·	Orm Account # /State/Zip Email		as Cit	y, M06411 Dburnsmcd	14
PO Number	sting Address GI	-C/4300 G00		ted By (
Turn Around Time	5 DAY	3 DAY	2 DAY	1 DAY	CANA	: nav au) \A/EEU	(END-Must (Call Aband
		3 3.11	m Sec () I	* 0/1	37,711	. CATO	AA CCI	CIAO MONE	Lait Arieau
		METAL	_S		PARTICUL	ATES :		AIR	WIPES
Client Sample 10	Collection Date & fime	Pla TCLP TCLP RUNA E RCNA 8 Total GMC Metal Profile	Weiding Sumic Profite TX 1.1 PCLP CA 17 Total	Other Metals	otal Nuisana e Dust Respeable Dust TSP Gravimetric	1SP Pu	Total Time	Figure 23 Rand 23 Rand 23 Rand 23 Rand 24 Rand 24 Rand 24 Rand 24 Rand 24 Rand 24 Rand 24 Rand 24 Rand 24 Rand 25 Rand 25 Rand 25 Rand 25 Rand 25 Rand 25 Rand 25 Rand 26 Rand	AREA 1. Let he destructed by the second sec
107-A-01 107-A-02	11/16/22 8:55	01		As, Ba, Cd, Cr, Se	io M		225	2.57 57	8 Na
107-W-01 107-W-02	11/16/22 Gam								12".12"
									X.
									S. S
						Opportunities of the state of t			4
Released By: Signature:	Abiodum (b) (6)		AB USE ONLY – 8FL	Date: ILLI	6/22		Time		,
Received By (b) (6) Date:	Nauker) ;]	м Дрм		Du 11/	e Date 28/20)22	
Portal Contact	Added						1onda EL	y) Ml∨	1-L
	NE RD, RICHMOND		0)-347-4010						