
APPENDIX E PHOTOGRAPHIC LOG





TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows a private utility locator with ground penetrating radar.	1
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: South	PHOTOGRAPHER	Keith Brown	04/30/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-1/DPTGW-1.	2
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Keith Brown	04/30/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of DPTS-1 soil cores.	3
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: NA	PHOTOGRAPHER	Jason Heflin	04/30/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of DPTGW-1.	4
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: South	PHOTOGRAPHER	Jason Heflin	05/08/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-2.	5
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	04/30/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-3.	6
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	04/30/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-4.	7
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: West	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-5.	8
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/01/12



	l	I	I
TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-6.	9
PROJECT NO.			
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-7.	10
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-8.	11
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: West	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-9.	12
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-10.	13
PROJECT NO.			13
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-11.	14
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-12.	15
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-13.	16
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-14.	17
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-15.	18
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-16.	19
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-17.	20
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-18.	21
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: South	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-19.	22
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-20.	23
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/02/12




TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-21.	24
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/03/12



TETTO A TECAN	DESCRIPTION	This photograph shows the location of DPTS-22.	
TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of Di 13-22.	25
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southwest	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-23.	26
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-24.	27
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: West	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-25.	28
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-26.	
PROJECT NO.	BESCHII IIOI	This photograph sho we are focution of \$1.15.20.	29
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-27.	30
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: West	PHOTOGRAPHER	Jason Heflin	05/03/12



t				I
	TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-28.	31
	PROJECT NO.			31
	103G1058232.02	CLIENT	U.S. General Services Administration	Date
	Direction: Southwest	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows staining from 0-4" below ground surface (bgs) from collection of DPTS-28.	32
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: West	PHOTOGRAPHER	Jason Heflin	05/03/12



TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-30.	
PROJECT NO.		· r · · · · · · · · · · · · · · · · · ·	33
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-31.	34
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-32.	35
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: East	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-33.	36
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-34.	
PROJECT NO.	2200111 1101	The photograph one is all to cause of 21 12 cm	37
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-35.	38
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-36.	39
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: East	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-37.	40
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/04/12



TETRA TECH	DESCRIPTION	This photograph shows the location of DPTS-38.	41
PROJECT NO. 103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-39.	42
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-40.	43
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-41.	44
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-42.	45
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southeast	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-43.	46
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: East	PHOTOGRAPHER	Jason Heflin	05/07/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-44.	47
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: East	PHOTOGRAPHER	Jason Heflin	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-45.	48
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of DPTS-45.	49
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: NA	PHOTOGRAPHER	Jason Heflin	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of abandoned DPTS-46.	50
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the location of DPTS-47.	51
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Jason Heflin	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 102E-ID2 on the second floor of Building 102 E.	52
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: East	PHOTOGRAPHER	Keith Brown	05/01/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 102E-ID4 on the first floor of Building 102 E.	53
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Keith Brown	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 104F-ID3 on the first floor of Building 104 F.	54
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: NA	PHOTOGRAPHER	Keith Brown	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 105-ID10 on the first floor of Building 105 next to column H10.	55
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Southwest	PHOTOGRAPHER	Keith Brown	05/05/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 105F-ID4 on the first floor of Building 105 F between columns L28 and L29.	56
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northeast	PHOTOGRAPHER	Keith Brown	05/09/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 101-C3 in basement 1 vault 1 of Building 101.	57
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: South	PHOTOGRAPHER	Adam Watkins	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 105E-C1 in the second floor electrical closet of Building 105 E.	58
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: NA	PHOTOGRAPHER	Keith Brown	05/02/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the collection of 101-C3 in basement 1 vault 1 of Building 101.	59
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: Northwest	PHOTOGRAPHER	Adam Watkins	05/03/12



TETRA TECH PROJECT NO.	DESCRIPTION	This photograph shows the basement north crawlspace in Building 104 F.	60
103G1058232.02	CLIENT	U.S. General Services Administration	Date
Direction: North	PHOTOGRAPHER	Keith Brown	05/03/12