

January 4, 2024

Diane Czarnecki Industrial Hygienist Facilities Management Division GSA Public Buildings Service – Heartland Region 2300 Main Street Kansas City, MO 64108

Re: Goodfellow Federal Center – Bldg. 110 Air Sampling Project No. 121244

Dear Ms. Czarnecki:

Thank you for the opportunity to provide the General Services Administration (GSA) with the Resource Conservation and Recovery Act (RCRA) metals air sampling investigation of the above referenced building located at the Goodfellow Federal Complex, in St. Louis, Missouri. Burns & McDonnell understands that the purpose of the investigation was to provide sampling data regarding existing conditions to supplement previous investigation reports prepared for the facility. The following report summarizes air-sample collection activities and the laboratory analytical results of the samples submitted.

METHODOLOGY

On December 6, 2023, Ashley Anstaett of Burns & McDonnell conducted area air-sampling for the presence of seven (7) of the RCRA metals including arsenic, barium, cadmium, chromium, lead, selenium, and silver. Sampling was conducted in various locations throughout Building 110.

The sampling plan, number of samples, sample distribution, and general methodology was developed based on previous investigation methodology and in coordination with the GSA. Sample locations and samples collected from discretionary locations were determined by sampling personnel while on-site.

Air samples for RCRA metals were collected on 37-millimeter (mm) cassettes with 0.8 micrometer (µm) mixed cellulose ester (MCE) filters, using powered air sampling pumps, in accordance with the National Institute for Occupational Safety and Health (NIOSH) Method 7300. The sampling strategy included collecting a minimum sample volume of 500 liters based on the calibrated pump flow rate and sample duration. Air samples were submitted under chain-of-custody to Environmental Hazards Services, LLC (EHS) in Richmond, Virginia for independent analysis of 7 RCRA metals according to NIOSH method 7300. EHS is accredited under the American Industrial Hygiene Association (AIHA) Industrial Hygiene Laboratory Accreditation Program (IHLAP) program, identification number LAP-100420.



Diane Czarnecki Facilities Management Division January 4, 2024 Page 2

RESULTS AND DISCUSSION

Results of the air sampling are summarized in the table below by identifying the range of results for Building 110 for each of the seven (7) metals that were sampled. Results indicate that all 6 air samples collected from Building 110 and analyzed for RCRA metals were below their respective OSHA Permissible Exposure Limit (PEL), as based on a time-weighted-average.

Table 1. Summary of Air Sampling Results

| Analyte | Lowest Concentration ^(a) (μg/m ³) ^(b) | Highest Concentration ^(a) (μg/m ³) ^(b) | Permissible Exposure Limit (PEL) (μg/m³) (b) |
|------------------|---|--|--|
| Arsenic | < 0.27 | <0.28 | 10 |
| Barium | < 0.27 | <0.28 | 500 |
| Cadmium | < 0.053 | < 0.055 | 5 |
| Chromium (Total) | <1.4 | <1.4 | 500 |
| Lead | < 0.27 | <0.28 | 1 |
| Selenium | <1.4 | <1.4 | 200 |
| Silver | < 0.27 | <0.28 | 10 |

Notes:

- (a) Samples with a "<" sign indicate that the results were below the laboratory's reporting limit, which varies based on sample air volume.
- (b) $\mu g/m^3 = \text{micrograms per cubic meter of air.}$

GSA may choose to compare results with guidance limits from additional organizations for risk evaluation, including but not limited to the American Conference of Governmental Industrial Hygienists (ACGIH) and/or the World Health Organization (WHO).

A summary table of all sampling results by location is included in Appendix A. The complete laboratory report for the air sampling from EHS is attached in Appendix B.

LIMITATIONS

The scope of this assessment was limited as follows. Burns & McDonnell collected samples from a select number of locations in an effort to minimize cost while providing a general overview of the air quality at the site. Sample locations do not encompass every indoor space at the site. Additionally, based on previous sampling history, samples were only analyzed for a select number of potential contaminants likely to affect the air quality at the site. Burns &



Diane Czarnecki Facilities Management Division January 4, 2024 Page 3

McDonnell is not responsible for potential contaminants not identified in this report. This report was prepared for the sole use of GSA.

Burns & McDonnell appreciates the opportunity to work with the GSA on this project. Please contact us if you have any questions regarding this report or if we may be of any additional service.

Sincerely,



Matt Shanahan, CHMM Project Manager

Attachments:

Appendix A – Results Summary by Location Appendix B – Air Sample Laboratory Report

Information in Appendices A and B is not accessible for people using screen reader technology. If this information is required, it can be furnished upon request by contacting 816-223-6198 or required, it can be furnished upon request by contacting 816-223-6198 or required.



Appendix A Results Summary by Location

| Sample Number | Location | Analyte | Result | Units | Recommended Limits ¹ |
|------------------|---|-------------------|---------|-------------------|------------------------------------|
| 110-A-01 | Warehouse, metal shelf east of office entrance | Arsenic | < 0.27 | μg/m³ | 10 |
| | | Barium | < 0.27 | μg/m³ | 500 |
| | | Cadmium | < 0.053 | μg/m³ | 5 |
| | | Chromium | < 1.4 | μg/m³ | 500 |
| | | Lead ² | < 0.27 | μg/m³ | 1 |
| | | Selenium | < 1.4 | μg/m³ | 200 |
| | | Silver | < 0.27 | μg/m³ | 10 |
| 110-A-02 | Warehouse, mezzanine in front of AHU-11 | Arsenic | < 0.27 | μg/m³ | 10 |
| | | Barium | < 0.27 | μg/m³ | 500 |
| | | Cadmium | < 0.053 | μg/m³ | 5 |
| | | Chromium | < 1.4 | μg/m³ | 500 |
| | | Lead ² | < 0.27 | μg/m³ | 1 |
| | | Selenium | < 1.4 | μg/m³ | 200 |
| | | Silver | < 0.27 | μg/m³ | 10 |
| 110-A-03 | Warehouse, wood chest on south wallin workshop area | Arsenic | < 0.28 | μg/m³ | 10 |
| | | Barium | < 0.28 | μg/m³ | 500 |
| | | Cadmium | < 0.055 | μg/m³ | 5 |
| | | Chromium | < 1.4 | μg/m³ | 500 |
| | | Lead ² | < 0.28 | μg/m³ | 1 |
| | | Selenium | < 1.4 | μg/m³ | 200 |
| | | Silver | < 0.28 | μg/m³ | 10 |
| 110-A-04 | Warehouse offices, metal cabinet behind desk | Arsenic | < 0.27 | μg/m³ | 10 |
| | | Barium | < 0.27 | μg/m³ | 500 |
| | | Cadmium | < 0.053 | μg/m³ | 5 |
| | | Chromium | < 1.4 | μg/m³ | 500 |
| | | Lead ² | < 0.27 | μg/m³ | 1 |
| | | Selenium | < 1.4 | μg/m³ | 200 |
| | | Silver | < 0.27 | μg/m³ | 10 |
| 110-A-05 | Warehouse offices, east office behind main desk | Arsenic | < 0.27 | μg/m³ | 10 |
| | | Barium | < 0.27 | μg/m³ | 500 |
| | | Cadmium | < 0.054 | μg/m³ | 5 |
| | | Chromium | < 1.4 | μg/m³ | 500 |
| | | Lead ² | < 0.27 | μg/m³ | 1 |
| | | Selenium | < 1.4 | μg/m ³ | 200 |
| | | Silver | < 0.27 | μg/m ³ | 10 |

Appendix A Results Summary by Location

| Sample Number | Location | Analyte | Result | Units | Recommended Limits ¹ |
|------------------|-------------|-------------------|---------|-------|------------------------------------|
| 110-A-06 | Field blank | Arsenic | < 0.15 | μg | |
| | | Barium | < 0.15 | μg | |
| | | Cadmium | < 0.030 | μg | |
| | | Chromium | < 0.75 | μg | |
| | | Lead ² | < 0.15 | μg | |
| | | Selenium | < 0.75 | μg | |
| | | Silver | < 0.15 | μg | |

Notes:

¹Limits equal to the Occupational Safety and Health Administration (OSHA) Permissible Exposure Limits (PELs)

²Limits equal to the World Health organization (WHO) Ambient Air Limit





Environmental Hazards Services, L.L.C. 7469 Whitepine Rd Richmond, VA 23237

Telephone: 800.347.4010

Air Metals Analysis Report

Client: Burns & McDonnell Engineering

9400 Ward Pkwy.

Kansas City, MO 64114

Report Number: 23-12-01183

Received Date:

12/11/2023

Reported Date: 12/18/2023

Project/Test Address: 168795; GFC; 4300 Goodfellow Blvd.

Client Number: 26-3514 Laboratory Results

Fax Number: 816-822-3494

| Lab Sample Number | Client Sample Number | Analyzed Date | Analyte | Air Volume (L) | Total Metal (ug) | Concentration (ug/m³) | Narrative ID |
|----------------------|-------------------------|------------------|---------------|-------------------|---------------------|-----------------------|-----------------|
| 23-12-01183-001 | 110-A-01 | 12/12/2023 | Arsenic (As) | 572 | <0.15 | <0.27 | |
| | | | Barium (Ba) | | <0.15 | <0.27 | |
| | | | Cadmium (Cd) | | <0.030 | <0.053 | |
| | | | Chromium (Cr) | | <0.75 | <1.4 | |
| | | | Lead (Pb) | | <0.15 | <0.27 | |
| | | | Selenium (Se) | | <0.75 | <1.4 | |
| | | | Silver (Ag) | | <0.15 | <0.27 | |
| 23-12-01183-002 | 110-A-02 | 12/12/2023 | Arsenic (As) | 568 | <0.15 | <0.27 | |
| | | | Barium (Ba) | | <0.15 | <0.27 | |
| | | | Cadmium (Cd) | | <0.030 | <0.053 | |
| | | | Chromium (Cr) | | <0.75 | <1.4 | |
| | | | Lead (Pb) | | <0.15 | <0.27 | |
| | | | Selenium (Se) | | <0.75 | <1.4 | |
| | | | Silver (Ag) | | <0.15 | <0.27 | |
| 23-12-01183-003 | 110-A-03 | 12/12/2023 | Arsenic (As) | 555 | <0.15 | <0.28 | |
| | | | Barium (Ba) | | <0.15 | <0.28 | |
| | | | Cadmium (Cd) | | <0.030 | <0.055 | |

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 23-12-01183

Project/Test Address: 168795; GFC; 4300 Goodfellow Blvd.

| Lab Sample Number | Client Sample Number | Analyzed Date | Analyte | Air Volume (L) | Total Metal (ug) | Concentration (ug/m³) | Narrative ID |
|----------------------|-------------------------|------------------|---------------|-------------------|---------------------|--------------------------|-----------------|
| | | | Chromium (Cr) | | <0.75 | <1.4 | |
| | | | Lead (Pb) | | <0.15 | <0.28 | |
| | | | Selenium (Se) | | <0.75 | <1.4 | |
| | | | Silver (Ag) | | <0.15 | <0.28 | |
| 23-12-01183-004 | 110-A-04 | 12/12/2023 | Arsenic (As) | 567 | <0.15 | <0.27 | |
| | | | Barium (Ba) | | <0.15 | <0.27 | |
| | | | Cadmium (Cd) | | <0.030 | <0.053 | |
| | | | Chromium (Cr) | | <0.75 | <1.4 | |
| | | | Lead (Pb) | | <0.15 | <0.27 | |
| | | | Selenium (Se) | | <0.75 | <1.4 | |
| | | | Silver (Ag) | | <0.15 | <0.27 | |
| 23-12-01183-005 | 110-A-05 | 12/12/2023 | Arsenic (As) | 562 | <0.15 | <0.27 | |
| | | | Barium (Ba) | | <0.15 | <0.27 | |
| | | | Cadmium (Cd) | | <0.030 | <0.054 | |
| | | | Chromium (Cr) | | <0.75 | <1.4 | |
| | | | Lead (Pb) | | <0.15 | <0.27 | |
| | | | Selenium (Se) | | <0.75 | <1.4 | |
| | | | Silver (Ag) | | <0.15 | <0.27 | |
| 23-12-01183-006 | 110-A-06 | 12/12/2023 | Arsenic (As) | | <0.15 | | |
| | | | Barium (Ba) | | <0.15 | | |
| | | | Cadmium (Cd) | | <0.030 | | |
| | | | Chromium (Cr) | | <0.75 | | |
| | | | Lead (Pb) | | <0.15 | | |
| | | | Selenium (Se) | | <0.75 | | |
| | | | Silver (Ag) | | <0.15 | | |
| | | | | | | | |

Environmental Hazards Services, L.L.C

Client Number: 26-3514 Report Number: 23-12-01183

Project/Test Address: 168795; GFC; 4300 Goodfellow Blvd.

Lab Sample Client Sample Analyzed Analyte Air Total Metal Concentration Narrative Number Date Volume (L) (ug) (ug/m³) ID

Sample Narratives:

Method: NIOSH 7300M Analyst: Carlos Gonzalez

(b) (6)

Reviewed By Authorized Signatory:

Tasha Eaddy QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contains less than the reporting limit for each particular metal, based on a 15mL volume. The reporting limit is 0.03ug for Cadmium, 0.15ug for Arsenic, Barium, Lead and Silver, and 0.75ug for Chromium and Selenium.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Unless otherwise noted, samples are reported without a dry weight correction. Sample location, description, area, volume, etc., was provided by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

LEGEND ug = microgram ug/m³ = micrograms per cubic meter

mL = milliliter L= Liters

ENVIRONMENTAL HAZARDS SERVICES, LLC

Pg ____ of ____ Metals Chain of Custody Form 26-3514 Account # Burns & McDonnell Company Name Kansas City, MO 64114 City/State/Zip 9400 Ward Parkway Company Address alanstaett@burnsmcd.com Email 314-302-4661 Phone GFC / 4300 Goodfellow Blvd Project Name / Testing Address Anstalt Collected By 168765 PO Number SAME DAY OR WEEKEND - Must Call Ahead ₹ 5 DAY Turn-Around Time 1 DAY C 3 DAY 2 DAY AIR WIPES **PARTICULATES METALS** Flow Total Welding Fume Profile Total Nuisance Dust Vol. Foxic Metal Profile TSP Gravimetric Time Rate Respirable Dust AREA Collection CLP RCRA 8 RCRA 8 Total Client CA 17 Total TX 11 TCLP 10 Circle The Unit of Pb TCLP Other Date & Time Sample ID Measurement Used TSP Metals Total Mins. cm or in Liters Ag, As, Ba, Cd, Cr, Pb, Se 572 219 110- A-01 12/6/23 1441 568 219 1442 110-A-02 555 218 14413 110-1-03 567 Х 218 1445 110-A-041 562 217 1447 110-A-05 1500 110 - A - UCO Х 13 х 12/8/2023 1030 Time: Anstactt Released By: Signature: LAB USE ONLY - BELOW THIS LINE 23-12-01183

| Received By: HHUMPhrou | |
|--|--|
| Signature: | |
| Portal Contact Added | |
| 7469 WHITEPINE RD, RICHMOND, VA 23237 (800)-347-4010 RESULTS VIA CLIENT PORTAL AVAILABLE @ www.leadlab.com | |

23-12-01183

Due Date:
12/18/2023
(Monday)

EL MM-L