

**KCORP Federal McNamara Building Domestic Water Testing**

Testing Date:				November 8, 2023 Results						December 12, 2023 Results					
Sample #	Sample Location	Floor	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
1	Basement Drinking Fountain 4E	B	Drinking fountain	280	1	NEGATIVE	NEGATIVE	0.8	non pneumophila						
2	Basement B105 Restroom (1)	B	Restroom sink	90	ND	NEGATIVE	NEGATIVE	2.8	serogroup 2-14					NLI	
								2	non pneumophila					NLI	
3	Basement 3E Gym Mens Shower #2	B	Shower	30	ND	NEGATIVE	NEGATIVE	NLI							
4	Basement Gym Drinking Fountain	B	Drinking fountain	320	ND	NEGATIVE	NEGATIVE	NLI							
5	1st Floor Drinking Fountain O4	1	Drinking fountain	450	ND	NEGATIVE	NEGATIVE	NLI							
6	Basement Gym Womens B104	B	Restroom sink	70	ND	NEGATIVE	NEGATIVE	NLI							
7	Basement Drinking Fountain 3E	B	Drinking fountain	300	ND	NEGATIVE	NEGATIVE	NLI							
8	Basement Mens Bathroom 2M	B	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI							
9	Basement Womens Bathroom 2W	B	Restroom sink	110	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
10	1st Floor Bathroom 106	1	Restroom sink	480	ND	NEGATIVE	NEGATIVE	NLI							
11	Basement Holding Cell (1)	B	Restroom sink	1600	14	NEGATIVE	NEGATIVE	16.8	serogroup 2-14	350	3			14	serogroup 2-14
			Restroom sink					30	non pneumophila					4	non pneumophila
12	Basement Kitchen Sink 1 (1)	B	Kitchen sink	90	ND	NEGATIVE	NEGATIVE	0.8	serogroup 2-14						
								0.8	non pneumophila						
13	Basement Kitchen Sink 2	B	Kitchen sink	80	ND	NEGATIVE	NEGATIVE	NLI							
14	Basement Kitchen Sink 3	B	Kitchen sink	120	1	NEGATIVE	NEGATIVE	NLI							
15	GSA Kitchen Sink 12	1	Kitchen sink	520	ND	NEGATIVE	NEGATIVE	NLI							
16	GSA Bathroom Sink O3	1	Restroom sink	260	ND	NEGATIVE	NEGATIVE	NLI							
17	14th Floor Drinking Fountain 3E	14	Drinking fountain	460	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
18	14th Floor Drinking Fountain 1E	14	Drinking fountain	280	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
19	14th Floor Women 1W Sink #1	14	Restroom sink	50	2	NEGATIVE	NEGATIVE	NLI							
1	14th Floor Women 1W Sink #2	14	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
21	14th Floor Men 4M Sink #1	14	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
22	14th Floor Men 4M Sink #2	14	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
23	13th Floor Drinking Fountain 3E	13	Drinking fountain	400	2	NEGATIVE	NEGATIVE	NLI							
24	13th Floor Mens Bathroom 4M	13	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
25	13th Floor Womens Bathroom 4W	13	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI							
26	13th Floor Drinking Fountain 2E	13	Drinking fountain	390	9	NEGATIVE	NEGATIVE	2.4	non pneumophila					NLI	
27	12th Floor Drinking Fountain 4E	12	Drinking fountain	260	ND	NEGATIVE	NEGATIVE	NLI							
28	12th Floor Mens Bathroom 4M	12	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
29	12th Floor Womens Bathroom 4W	12	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
30	12th Floor Drinking Fountain 3E	12	Drinking fountain	370	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila						
31	19th Floor Womens Bathroom 3W	19	Restroom sink	210	ND	NEGATIVE	NEGATIVE	2.8	non pneumophila					NLI	
32	19th Floor Mens Bathroom 4M (1)	19	Restroom sink	380	ND	NEGATIVE	NEGATIVE	1.2	serogroup 2-14					NLI	
								3.2	non pneumophila					NLI	
33	19th Floor Drinking Fountain 2W	19	Drinking fountain	380	ND	NEGATIVE	NEGATIVE	NLI							
34	19th Floor Breakroom 113	19	Breakroom sink	140	ND	NEGATIVE	NEGATIVE	NLI							
35	19th Floor 111	19	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI							
36	19th Floor 107	19	Hand sink	270	ND	NEGATIVE	NEGATIVE	NLI							
37	20th Floor Mens Bathroom 4M	20	Restroom sink	150	2	NEGATIVE	NEGATIVE	NLI							
38	20th Floor Womens Bathroom 3W	20	Restroom sink	1500	13	NEGATIVE	NEGATIVE	NLI		150	ND				
39	20th Floor Drinking Fountain 201	20	Drinking fountain	470	ND	NEGATIVE	NEGATIVE	2.4	non pneumophila					NLI	
40	20th Floor 1B	20	Kitchen sink	50	ND	NEGATIVE	NEGATIVE	NLI							
41	20th Floor 218	20	Kitchen sink	740	2	NEGATIVE	NEGATIVE	3.6	non pneumophila					0.4	non pneumophila
42	20th Floor 217	20	Restroom sink	220	ND	NEGATIVE	NEGATIVE	NLI							
43	21st Floor Mens Bathroom 4M	21	Restroom sink	560	ND	NEGATIVE	NEGATIVE	1.2	non pneumophila					11.6	non pneumophila
44	21st Floor Womens Bathroom 3W	21	Restroom sink	4500	9	NEGATIVE	NEGATIVE	17.2	non pneumophila	200	ND			1.2	serogroup 2-14
45	21st Floor 2C	21	Drinking fountain	320	ND	NEGATIVE	NEGATIVE	NLI							
46	21st Floor 107	21	Kitchen sink	100	ND	NEGATIVE	NEGATIVE	NLI							

**KCORP Federal McNamara Building Domestic Water Testing**

Testing Date:				November 8, 2023 Results						December 12, 2023 Results					
Sample #	Sample Location	Floor	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
47	22nd Floor Mens Bathroom 4M	22	Restroom sink	130	ND	NEGATIVE	NEGATIVE	NLI							
48	22nd Floor Womens Bathroom 3W	22	Restroom sink	200	1	NEGATIVE	NEGATIVE	0.4	non pneumophila						
49	22nd Floor 1B	22	Kitchen sink	110	ND	NEGATIVE	NEGATIVE	NLI							
50	22nd Floor 2C	22	Drinking fountain	290	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
51	26th Floor Mens Bathroom 4M	26	Restroom sink	960	7	NEGATIVE	NEGATIVE	0.4	non pneumophila						
52	26th Floor Womens Bathroom 3W (1)	26	Restroom sink	490	8	NEGATIVE	NEGATIVE	0.4	serogroup 2-14						
								1.2	non pneumophila					0.4	non pneumophila
53	26th Floor 1B	26	Kitchen sink	40	ND	NEGATIVE	NEGATIVE	NLI							
54	26th Floor 2C	26	Drinking fountain	250	1	NEGATIVE	NEGATIVE	NLI							
55	26th Floor 211	26	Restroom sink	330	1	NEGATIVE	NEGATIVE	NLI							
56	26th Floor 308	26	Restroom sink	140	ND	NEGATIVE	NEGATIVE	NLI							
57	26th Floor 309	26	Kitchen sink	2400	2	NEGATIVE	NEGATIVE	NLI		100	ND				
58	8th Floor Womens Bathroom 3W	8	Restroom sink	60	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
59	8th Floor 3E	8	Drinking fountain	250	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila						
60	8th Floor 2C02	8	Drinking fountain	2800	ND	NEGATIVE	NEGATIVE	NLI		4100	ND				
61	Sub Basement Sink	SB	Hand sink	290	ND	NEGATIVE	NEGATIVE	NLI							
62	Mez Mens Bathroom	MEZ	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
63	Mez Womens Bathroom	MEZ	Restroom sink	240	14	NEGATIVE	NEGATIVE	0.8	non pneumophila						
64	Mez Drinking Fountain	MEZ	Drinking fountain	970	10	NEGATIVE	NEGATIVE	12	non pneumophila					NLI	
65	2nd Floor 2Q-1C	2	Drinking fountain	140	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
66	2nd Floor Mens Bathroom Q4-4M	2	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
67	2nd Floor Q3-3C	2	Drinking fountain	30	ND	NEGATIVE	NEGATIVE	NLI							
68	2nd Floor Womens Bathroom Q3-3W	2	Restroom sink	40	ND	NEGATIVE	NEGATIVE	NLI							
69	3rd Floor Q1 Room 28	3	Kitchen sink	710	ND	NEGATIVE	NEGATIVE	NLI							
70	3rd Floor Q4 Room 328	3	Restroom sink	780	ND	NEGATIVE	NEGATIVE	1.6	non pneumophila					NLI	
71	3rd Floor Q1-1C	3	Drinking fountain	270	ND	NEGATIVE	NEGATIVE	NLI							
72	3rd Floor Mens Bathroom Q1-1M (1)	3	Restroom sink	300	ND	NEGATIVE	NEGATIVE	0.8	serogroup 2-14					NLI	
								8	non pneumophila					NLI	
73	3rd Floor Womens Bathroom Q2-2W (1)	3	Restroom sink	280	ND	NEGATIVE	NEGATIVE	0.4	serogroup 2-14					NLI	
								2.8	non pneumophila					NLI	
74	3rd Floor Q3-3C	3	Drinking fountain	240	ND	NEGATIVE	NEGATIVE	NLI							
75	4th Floor Q1-1C	4	Drinking fountain	250	ND	NEGATIVE	NEGATIVE	NLI							
76	4th Floor Q1 Room 113	4	Restroom sink	150	ND	NEGATIVE	NEGATIVE	NLI							
77	4th Floor Q1 Room 11-1	4	Shower	670	ND	NEGATIVE	NEGATIVE	NLI							
78	4th Floor Q1 Room 11-2	4	Shower	470	ND	NEGATIVE	NEGATIVE	NLI							
79	4th Floor Q1 Room 11-3	4	Shower	560	ND	NEGATIVE	NEGATIVE	NLI							
80	4th Floor Q1 Room 2	4	Shower	570	2	NEGATIVE	NEGATIVE	NLI							
81	4th Floor Q1 Room 2-5	4	Shower	2200	4	NEGATIVE	NEGATIVE	NLI		310	ND				
82	4th Floor Q4 Room 2-S	4	Shower	5500	3	NEGATIVE	NEGATIVE	NLI		200	ND				
83	4th Floor Q3 Room 28	4	Kitchen sink	60	ND	NEGATIVE	NEGATIVE	NLI							
84	4th Floor Q3 Room 25	4	Restroom sink	20	ND	NEGATIVE	NEGATIVE	NLI							
85	4th Floor Mens Bathroom Q4-4M	4	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	1.6	non pneumophila					NLI	
86	4th Floor Womens Bathroom Q3-3W	4	Restroom sink	50	ND	NEGATIVE	NEGATIVE	7.2	non pneumophila					NLI	
87	5th Floor Q3-3C	5	Drinking fountain	340	1	NEGATIVE	NEGATIVE	2	non pneumophila					NLI	
88	5th Floor Q2-2C	5	Drinking fountain	300	1	NEGATIVE	NEGATIVE	NLI							
89	5th Floor Q1-1C	5	Drinking fountain	280	2	NEGATIVE	NEGATIVE	0.8	non pneumophila						
90	5th Floor Mens Bathroom Q4-4M	5	Restroom sink	30	1	NEGATIVE	NEGATIVE	NLI							
91	23rd Floor Mens Bathroom 4M	23	Restroom sink	440	ND	NEGATIVE	NEGATIVE	NLI							
92	23rd Floor Womens Bathroom 3W	23	Restroom sink	170	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila						
93	23rd Floor Room 1B Pantry	23	Kitchen sink	50	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						

**KCORP Federal McNamara Building Domestic Water Testing**

Testing Date:				November 8, 2023 Results						December 12, 2023 Results					
Sample #	Sample Location	Floor	Outlet Type	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species	Copper (ppb) AL: 1300 ppb	Lead (ppb) AL: 15 ppb	E. Coli	Total Coliform	Legionella (CFU/mL)	Legionella Species
94	23rd Floor Drinking Fountain 1B	23	Drinking fountain	220	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila						
95	Basement 108 Sink	B	Restroom sink	500	ND	NEGATIVE	NEGATIVE	NLI							
96	Basement 108 Shower #1	B	Shower	40	ND	NEGATIVE	NEGATIVE	NLI							
97	Basement 108 Shower #3	B	Shower	ND	ND	NEGATIVE	NEGATIVE	NLI							
98	Basement 108 Shower #4	B	Shower	40	ND	NEGATIVE	NEGATIVE	NLI							
99	Basement 104 Shower #1	B	Shower	190	ND	NEGATIVE	NEGATIVE	NLI							
100	Basement 104 Shower #2	B	Shower	130	26	NEGATIVE	NEGATIVE	NLI		60	ND				
101	Basement 104 Shower #3	B	Shower	160	ND	NEGATIVE	NEGATIVE	NLI							
102	18th Floor Womens Bathroom 2W	18	Restroom sink	100	ND	NEGATIVE	NEGATIVE	NLI							
103	18th Floor Mens Bathroom 1M	18	Restroom sink	50	ND	NEGATIVE	NEGATIVE	NLI							
104	18th Floor 1C Drinking Fountain	18	Drinking fountain	340	ND	NEGATIVE	NEGATIVE	NLI							
105	17th Floor Womens Bathroom 2W	17	Restroom sink	80	ND	NEGATIVE	NEGATIVE	0.4	non pneumophila						
106	17th Floor Mens Bathroom 1M	17	Restroom sink	40	ND	NEGATIVE	NEGATIVE	NLI							
107	17th Floor 3C Drinking Fountain	17	Drinking fountain	160	ND	NEGATIVE	NEGATIVE	NLI							
108	17th Floor 1C Drinking Fountain	17	Drinking fountain	ND	ND	NEGATIVE	NEGATIVE	NLI							
109	17th Floor 206	17	Kitchen sink	680	ND	NEGATIVE	NEGATIVE	NLI							
110	17th Floor 212	17	Kitchen sink	2700	ND	NEGATIVE	NEGATIVE	NLI		740	ND				
111	18th Floor 065	18	Kitchen sink	120	2	NEGATIVE	NEGATIVE	NLI							
112	18th Floor 020	18	Restroom sink	80	2	NEGATIVE	NEGATIVE	NLI							
113	18th Floor 020-H1	18	Restroom sink	110	1	NEGATIVE	NEGATIVE	2	non pneumophila					NLI	
114	15th Floor 027	15	Restroom sink	680	ND	NEGATIVE	NEGATIVE	NLI							
115	15th Floor 3C Drinking Fountain	15	Drinking fountain	370	ND	NEGATIVE	NEGATIVE	NLI							
116	15th Floor Womens Bathroom 3W	15	Restroom sink	260	8	NEGATIVE	NEGATIVE	0.4	non pneumophila						
117	8th Floor 2C2E	8	Drinking fountain	550	21	NEGATIVE	NEGATIVE	14.8	non pneumophila	300	ND			NLI	
118	8th Floor 1C1E	8	Drinking fountain	310	3	NEGATIVE	NEGATIVE	1.2	non pneumophila					6.4	non pneumophila
119	8th Floor Mens Bathroom 4C4M	8	Restroom sink	ND	ND	NEGATIVE	NEGATIVE	NLI							
120	12th Floor 1E Drinking Fountain	12	Drinking fountain	260	ND	NEGATIVE	NEGATIVE	0.8	non pneumophila						
121	Cooling Tower	28	Cooling tower					NLI							